

Battery Relay Fault

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
Battery Relay Fault	General	Inverter alarm

Possible Cause

Cause ID	Possible Cause
1	Battery relay malfunction
2	Relay self-check failed

Suggestion

- 1.Update the firmware to the latest version.
- 2.This error indicates a relay fault at the inverter's battery port. Try restarting the battery multiple times.
- 3.If the issue remains, provide the completed troubleshooting results to SolaX technical support team through video or images.Including but not limited to:
 - 1) SN number of the inverter.
 - 2)A video of multiple battery restarts.