

Communication Time Out 2030.5

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
Communication Time Out 2030.5	General	Communication alarm

Possible Cause

Cause ID	Possible Cause
1	2030.5 Communication Time Out: The communication to the dongle module is lost after enabling the 2030.5 function

Suggestion

- 1.Please try to unplug and re-plug the dongle module;
2. If the issue remains,provide the inverter's SN number to the SolaX technical support team for further analysis.