

DSP Boot Fault

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
DSP Boot Fault	General	Communication alarm

Possible Cause

Cause ID	Possible Cause
1	Boot stuck failure of DSP
2	DSP upgrade failed or incomplete program, causing inability to run properly

Suggestion

1. Try to upgrade the DSP again using a USB drive or remotely.
2. If the problem remains, power off the entire system, then attempt the firmware update again. If multiple attempts fail, provide the inverter's SN number to the SolaX technical support team for further analysis.