

Hard Limit Fault

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
Hard Limit Fault	General	Inverter alarm

Possible Cause

Cause ID	Possible Cause
1	Power overload fault in Australian safety code
2	Power exceeds hard limit under Australian safety code

Suggestion

1.Under Australian safety code, if the feed-in exceeds the value set by the hard limit, an error will occur. If the error persists, check if the hard limit setting matches the actual conditions.

2.If the issue remains, provide the completed troubleshooting results to SolaX technical support team through video or images.Including but not limited to:

- 1) SN number of the inverter.
- 2) Hard limit settings.