

INV EEPROM Fault

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
INV EEPROM Fault	General	Inverter alarm

Possible Cause

Cause ID	Possible Cause
1	EEPROM malfunction
2	DSP EEPROM cannot be red/written

Suggestion

1. Upgrade the firmware to the latest version and restart the inverter.
2. If the issue remains, provide the inverter's SN number to the SolaX technical support team for further analysis.