

Power Type Fault

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
Power Type Fault	General	Communication alarm

Possible Cause

Cause ID	Possible Cause
1	Power type mismatch
2	Machine power type self check failed

Suggestion

1. Upgrade to the latest firmware.
2. Check if the SN number in the inverter's "About" menu matches the SN on the external nameplate. If there is a discrepancy, provide the inverter's SN number to the SolaX technical support team for further analysis.