

Software Over Current Protection Fault

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
Software Over Current Protection Fault	General Alarm	Inverter alarm

Possible Cause

Cause ID	Possible Cause
1	Over-current Fault: Software over-current protection triggered by sudden change of the current.

Suggestion

- 1.Try to disconnect the AC, PV and battery power and set it aside for 30 minutes and then reboot the inverter.
- 2.If the issue remains, provide the inverter's SN number to the SolaX technical support team for further analysis.