



Happy Link Claude TLDR Ticket Summary

AI-powered HappyFox ticket analysis — Problem · Actions · Next Steps · Timeline

Ticket number

129347

Show Recent Ticket IDs



Investigate Ticket

Ticket Overview

MX6200 无法重置

GB MX6200 cannot reset

<https://support.linksys.com/staff/ticket/129347>

TICKET	CATEGORY	STATUS	UPDATES	PRIORITY
#129...	Prod...	Upd...	37	P2

Customer Details

Name: WONG CHI WA

Email: wcw0608@hotmail.com

Phone: 85293102624

Country: Hong Kong

The Problem

Customer's MX6202 router (part of a 2-unit pack) cannot be reset — the LED flashes rhythmically but no Wi-Fi signal appears and all troubleshooting steps including factory reset and rescue mode have failed. The device is confirmed to be a hardware failure requiring replacement.

✓ Actions Taken

- Agent asked customer about LED color — customer reported rhythmic blue flashing
- Agent instructed customer to hold reset button for 20 seconds until light goes off — no change
- Agent guided customer through rescue mode (power on 30s, off 30s, repeat 3 times) — no change
- Agent instructed customer to hold reset for 30 seconds — LED continued flashing
- Agent checked for Wi-Fi signal — customer confirmed no Wi-Fi visible
- Agent diagnosed hardware failure and registered warranty replacement request
- Support sent email to customer requesting photos of router label (S/N, MAC) and proof of purchase
- Customer replied with photos and a video as requested
- Support noted email appeared garbled/corrupted and asked agent to call customer to confirm
- Agent attempted callback — phone number reported as unregistered/not found
- Multiple callback attempts on 2026-05-14 all resulted in 'number not registered' message
- RMA approved by Ivan — RMA type: RMA to Distributor (Tech Data)
- Replacement product MX6201 assigned

- RMA to Tech Data HK email trigger fired on 2026-05-18
- Internal note confirmed hardware damage and replacement application submitted

Summary: Agent troubleshooted the unresettable MX6202 router, confirmed hardware failure, collected evidence from customer, attempted multiple callbacks that failed due to unregistered phone number, and processed an RMA to distributor Tech Data with replacement unit MX6201 approved by Ivan.

Insights: The customer's provided phone number (85293102624) appears to be inactive or unregistered, making voice follow-up impossible — all communication had to rely on email, which also had garbled encoding issues. Despite these communication barriers, the RMA was successfully processed and escalated to the distributor.

▼ Next Steps

- Confirm with Tech Data that the RMA for MX6201 replacement has been actioned
- Send a follow-up email to wcw0608@hotmail.com (in plain text or confirmed UTF-8 encoding) to inform the customer of the replacement process and next steps for contacting Tech Data
- Verify the correct customer phone number to enable future voice contact

> Timeline (9 entries)

 Download Executive Report

 Print / Save as PDF

> Raw ticket data (JSON)

