



Happy Link Claude TLDR Ticket Summary

AI-powered HappyFox ticket analysis — Problem · Actions · Next Steps · Timeline

129832

 Investigate Ticket

FGW5500 无法使用

EN: FGW5500 cannot be used

 <https://support.linksys.com/staff/ticket/129832>

▼ Ticket Overview

Ticket: #129832

Category: Linksys Technical Support

Status: Updated

Updates: 47

Assignee: Xiangjie Zhang

Time Spent: —

▼ Customer Details

Name: 李先生

Email: chrislikhc@gmail.com

Phone: 85298666976

Country: Hong Kong

▼ Device Details

Model Number: FGW5500	Serial Number: 56G10227D02375
Warranty Start Date: 2024-07-16	Warranty Status: Active
Problem Category 1: Hardware Failure	Problem Category 2: Warranty/RMA

The Problem

Customer's Linksys FGW5500 router (China Mobile contract device) cannot be reset, shows abnormal cycling LED lights, and broadcasts no SSID after factory reset attempts. The device is confirmed faulty and the discontinued model cannot be replaced under warranty, so a pro-rated refund is being considered.

▼ Actions Taken

- Agent guided customer through factory reset (holding reset button 5+ seconds) — no change in LED behavior
- Agent confirmed no default Linksys SSID broadcast after reset, diagnosing hardware failure
- Agent requested product bottom label photo and China Mobile contract screenshots for warranty/RMA processing
- Customer submitted contract documents and product photos via email
- Agent requested clearer/complete re-submission of contract documents as initial photos were insufficient
- Callback attempted on 2026-05-19 at 17:05 — no answer
- Internal escalation to Kris Qin and Ashley Alayon to determine RMA path given Tech Data is listed as warranty service provider in contract
- Ashley Alayon advised to compute pro-rated refund (Tango card) and refer to Tech Data if customer declines
- Agent called customer back on 2026-05-21 and discussed refund amount (~71 CNY via Tango card based on June 11 purchase date)
- Customer declined immediate refund and requested repair/replacement; agent noted FGW5500 is discontinued with no replacement stock
- Customer's concern escalated internally as customer recently renewed a 300GB China Mobile data plan and now has no working 5G router

 **Summary:** Support performed remote troubleshooting, confirmed hardware failure, collected warranty documents, identified Tech Data as the contract warranty provider, and internally escalated to determine a resolution path — currently offering a ~71 CNY pro-rated Tango card refund or Tech Data referral, pending customer acceptance.

 **Insights:** The FGW5500 being discontinued with no replacement stock creates a significant resolution gap — the only option offered is a small pro-rated refund (~71 CNY) which the customer has rejected, as they still have an active China Mobile data contract and need a functioning 5G router. There is a process ambiguity between Linksys and Tech Data as warranty service providers that is causing delays and internal escalation.

▼ Next Steps

- Escalate customer's request for a functional 5G router replacement to relevant department as promised
- Determine whether Tech Data can provide a replacement device since the contract lists them as warranty service provider
- If no replacement is possible, finalize and formally offer the pro-rated Tango card refund (~71 CNY based on June 11, 2024 date)
- Ashley Alayon to send heads-up email to Tech Data if customer is referred there
- Ensure customer phone remains reachable for follow-up callback

▼ Timeline (13 entries)

DATE	AUTHOR	SUMMARY
2026-05-18	Customer (Mr. Li)	Customer called reporting FGW5500 cycling LED lights and inability to use the device; agent performed troubleshooting (factory reset, SSID check) and confirmed hardware failure, promising RMA follow-up by email.
2026-05-18	Agent (xiangjie.zhang)	Agent sent email to customer requesting product bottom label photo and complete China Mobile contract screenshots to proceed with warranty claim.
2026-05-18	Customer	Customer submitted first set of photos and contract documents via email.
2026-05-18	Agent	Internal note to Kris Qin: FGW5500 cannot reset and has no SSID broadcast; device is a China Mobile contract unit purchased June 11, 2024; querying warranty eligibility and RMA location.
2026-05-18	Agent	Second internal note clarifying customer had already contacted China Mobile who directed them to Tech Data, and asking where RMA

DATE	AUTHOR	SUMMARY
		should be processed.
2026-05-19	Agent	Agent sent follow-up email requesting clearer, complete re-submission of China Mobile contract documents as initial submission was insufficient.
2026-05-19	Agent	Callback attempted at 17:05 — customer did not answer.
2026-05-19	Customer	Customer submitted additional contract document (PDF) via email in response to the re-submission request.
2026-05-20	Agent	Internal note: awaiting headquarters reply on how to proceed.
2026-05-21	Agent	Internal note to Ashley Alayon: contract documents received and clearly show Tech Data as warranty service provider; requested guidance on customer response.
2026-05-21	Ashley Alayon	Ashley advised to compute pro-rated refund and offer Tango card refund; if declined, refer customer to Tech Data and notify Tech Data in advance.
2026-05-21	Customer	Customer replied asking if submitted documents were sufficient.
2026-05-21	Agent	Agent called customer back, discussed pro-rated refund of ~71 CNY via Tango card; customer declined refund and requested repair or replacement, citing recently renewed 300GB China Mobile plan; agent escalated the request internally.



Download Executive Report



Print / Save as PDF