



Happy Link Claude TLDR Ticket Summary

AI-powered HappyFox ticket analysis — Problem · Actions · Next Steps · Timeline

128936

 Investigate Ticket

fgmm1000自动重启

EN: FGMM1000 auto restart

 <https://support.linksys.com/staff/ticket/128936>

 Ticket Overview

Ticket: #128936

Status: Updated

Assignee: Zhiliang Chen

Category: Linksys Technical Support

Updates: 66

Priority: P2

 <https://support.linksys.com/staff/ticket/128936>

 Customer Details

Name: 张女士

Email: kelvincheung247@gmail.com

Phone: +85261206455

Country: Hong Kong

▼

 Device Details

Model Number: FGMM1000

Serial Number: 47K10FA9B00323

Warranty Start Date: 2025-05-01

Warranty Status: Active

Problem Category 1: Hardware Failure

Problem Category 2: Connectivity

The Problem

Customer's FGMM1000 router automatically restarts when the network mode is set to 5G or 4G/5G combined using CSL SIM cards. The issue does not occur when using 4G-only mode or with a '3' carrier SIM card.

>

 Actions Taken

 **Summary:**

Support asked diagnostic questions about SIM carrier and network mode, requested screenshots of signal strength in the router UI, and made two unanswered callback attempts.

 **Insights:**

The issue appears to be specific to 5G network mode with CSL SIM cards, as it does not reproduce in 4G-only mode or with a different carrier, suggesting a possible compatibility or firmware issue with 5G band handling. Progress is stalled because the customer cannot be reached by phone and has not yet provided the requested UI screenshots.

▼

 Next Steps

- Follow up via email requesting the router UI screenshots in 5G and 4G modes along with the phone signal screenshot
- If screenshots confirm a 5G signal/connectivity issue, escalate to L2 or engineering for firmware investigation
- Consider testing with a CSL 5G SIM on a known-good unit to reproduce the issue internally

- If customer remains unresponsive, follow the no-contact closure policy

▼ Timeline (10 entries)

2026-05-11 | *Customer*

Customer called in reporting that the FGMM1000 router auto-restarts when set to 5G or 4G/5G mode using two CSL SIM cards; agent asked customer to send email with video evidence.

2026-05-13 | *Linksys Support (Charlotte)*

Agent emailed customer asking whether the issue also occurs in 4G-only mode and whether it persisted after a previous reset, and whether a different carrier SIM was tried.

2026-05-14 | *Customer*

Customer replied that 4G-only mode does not trigger the issue, and a '3' carrier SIM also works fine, but all her desired data SIMs are 5G so 4G-only mode is not a viable workaround.

2026-05-14 | *Linksys Support*

Agent asked whether the '3' carrier SIM is also 5G-capable and requested testing with another carrier's 5G SIM.

2026-05-18 | *Linksys Support*

Agent followed up again asking if the customer had tested with another carrier's 5G SIM card.

2026-05-18 | *Customer*

Customer replied that she does not have another carrier's 5G SIM card available for testing.

2026-05-18 | *Zhiliang Chen (Staff)*

Agent internally noted to Kris Qin that the customer cannot test with another 5G SIM.

2026-05-19 | *Kris Qin (Staff)*

Kris Qin instructed agent to ask customer for screenshots of the router UI signal in 5G and 4G modes, and the SIM signal on phone.

2026-05-19 | *Zhiliang Chen (Staff)*

Agent called customer back at 16:55 but there was no answer; sent follow-up email requesting UI screenshots.

2026-05-21 | *Zhiliang Chen (Staff)*

Agent attempted another callback at 13:49 but customer did not answer.



Download Executive Report



Print / Save as PDF



Raw ticket data (JSON)

