

Call Detail

Provider Call ID: f76dbda6-5291-11f1-82c✕

T HappyFox Ticket

Navigation

	nav_order	dashboard	open_dashboard
	1	Back to Product Signals	https://metaboard.linksys-apps.com/dashboard/20
	2	Back to Agent Quality	https://metaboard.linksys-apps.com/dashboard/19

2 rows

Case Data

field	value
Provider Call ID	f76dbda6-5291-11f1-82c1-42010a663f80
Call Start	2026-05-18 08:17:10+00
Customer Phone	+85298666976
Duration Seconds	667
Product Family	ROUTERS
Product Model	FGW5500
Problem Category	HARDWARE
Warranty Status	in_warranty
Warranty Source	happyfox
HappyFox Ticket	#LTS00129830
HappyFox Contact	先生
HappyFox Agent	Weiyu Zeng
Match Score	105
Match Method	deterministic_phone_time_contact

16 rows

Summary and Evidence

field	value
Generated Summary	# Issue Summary Customer reported a blinking LED and loss of connectivity on an aging Linksys router after years of use. Agent failed to identify the router model or serial number and provided incorrect reset instructions (5-minute press instead of 10–15 seconds per KB). No standard troubleshooting steps (power-cycle, LED interpretation, admin access) were performed. Escalation path (LCW500) referenced but not explained; resolution depends on unverified photo submissions. # Actions Taken - Instructed customer to press reset button for five minutes (incorrect per KB). - Requested photos of device label and mobile contract. - Escalated to HQ via internal code LCW500. - Collected customer name (CHRIS Cracroft) and email (cd4kathy.ahc@gmail.com). # Outcome / Next Step Customer to send photos of device and contract; agent to escalate to HQ. No technical resolution or root cause confirmation achieved. Issue remains pending. # QA Coaching Notes - **Technical accuracy violation**: Incorrect reset procedure (5-minute press vs. KB-mandated 10–15 seconds). - **Missed critical data**: Failed to collect model, serial, or warranty status. - **Deviation from KB flow**: Skipped power-cycle, LED checks, and admin access steps. - **Poor call control**: Incoherent statements, filler phrases, and lack of structured guidance. - **Positive**: Collected contact details and set a concrete next step (photo submission). # Data Gaps - Missing router model, serial number, and warranty status. - No validation of WAN/modem state or physical device access. - No attempt to interpret blinking LED patterns or access admin interface. - Escalation path (LCW500) not clarified or justified.
Resolution Or Next Step	Customer to send photos of device and contract; agent to escalate to HQ. No technical resolution or confirmation of issue root cause.
Warranty Evidence	Customer stated the router 'stopped working after years of use' [00:00], suggesting out-of-warranty status.

3 rows