



Support Ticket Detective

Paste a HappyFox ticket number and get an instant AI-powered case summary.

Ticket number

129832

Show Recent Ticket IDs

Investigate

Ticket	Status	Priority	Updates
#129832	Updated	P2	22

FGW5500 无法使用

The Problem: Mr. Li's FGW5500 router (a China Mobile contract device) is completely non-functional — the indicator light cycles abnormally and no default Wi-Fi SSID is broadcast even after a factory reset, indicating a hardware fault requiring RMA.

The Action:

- Agent guided the customer through basic troubleshooting: confirmed abnormal indicator light (cycling up and down) and performed a factory reset (hold reset button 5+ seconds).
- After the reset produced no change, agent asked the customer to scan for the default Linksys SSID — none was found, confirming a hardware fault.
- Agent determined an RMA/warranty claim was needed and promised to follow up by email within the same day or the next day.
- Support (Kelly Cheung) emailed the customer requesting: (1) a clear photo of the product bottom label showing the serial number, and (2) a full screenshot of the China Mobile contract.
- Customer replied with attachments (image and PDF) twice (likely duplicate sends from iPhone).

- Agent posted an internal note to Kris Qin asking whether the device (China Mobile contract unit, purchased 2024-06-11) is eligible for warranty and where to send it for RMA, noting the customer had already been directed from China Mobile to TechData.
- Support sent a follow-up email to the customer requesting clearer/complete photos of the China Mobile contract (lift the overlay sheet, photograph every page, ensure no obstructions).

Next Steps:

- Await Kris Qin's response on RMA eligibility and the correct RMA location/process for this China Mobile contract device.
- Await the customer's resubmission of complete, clear contract photos as requested.
- Once warranty eligibility is confirmed and documents are verified, communicate the RMA arrangement to the customer.

Timeline:

-  2026-05-18 08:35 — Customer — Mr. Li called in reporting his FGW5500 was not working; agent walked him through troubleshooting (factory reset, SSID scan) and concluded a hardware fault was present, promising an email follow-up by the next day.
-  2026-05-18 08:35 — System (Smart Rule) — Ticket auto-assigned to xiangjie.zhang@concentrix.com.
-  2026-05-18 08:37 — Agent (Kelly Cheung) — Sent email to customer requesting a photo of the product label (serial number) and a full screenshot of the China Mobile contract to proceed with the warranty/RMA process.
-  2026-05-18 08:41 — Customer — Replied with two attachments (image of product label and a PDF) from iPhone (sent twice, likely a duplicate).
-  2026-05-18 08:43 — Customer — Second duplicate submission of the same attachments received.
-  2026-05-18 08:43 — Agent — Posted internal note to @Kris Qin asking whether this China Mobile contract device (purchased 2024-06-11) qualifies for warranty and where the RMA should be processed.
-  2026-05-18 12:41 — System (SLA) — L1 Phone Time to Resolve SLA triggered.
-  2026-05-18 12:47 — System (SLA) — L1 Phone Time to Respond to Customer Email SLA triggered.
-  2026-05-18 (after 12:47) — Agent — Posted a second internal note to @Kris Qin clarifying that the customer had already contacted China Mobile, who redirected him to TechData, and asked where the RMA should go.
-  2026-05-19 01:56 — Agent — Sent follow-up email to Mr. Li requesting clearer, complete photos of the China Mobile contract (lift overlay sheet, photograph all pages, no obstructions, good lighting).

› View full ticket thread

› View raw JSON from HappyFox