POUGHKEEPSIE
Department 539
South Road Lab.
July 2, 1958

FILE MEMO

SUBJECT: LASL Meeting of June 30 - July 1

BY: W. Buchholz

The following points raised at the meeting struck me as particularly worthy of consideration by IBM.

1. Preserve the previous instruction counter contents during initial program loading.

2. Change some of the console switches to 3-position switches with momentary contact setting corresponding lights for Reading and which can also set by a Write operation.

3. Connect the high-order effective address bit to an indicator for break-point operation. Reconsider the AD indicator.

4. LASL will have multiple printers, and they are very much interested in one of them being an extended character printer for low-volume report printing. Bengt Carlson suggests alphabets from 120 characters on up, and never mind the speed.

5. Provide one or two "Result Sign Changed" indicators to replace the Augment set of operations.

6. Provide an indicator to allow testing whether the machine is disabled.

WB/pkb

cc: Mr. S. W. Dunwell
Mr. E. Bloch
Project 7000 Product Planning Group ←
Project 7000 Planning Group

Dr. H. D. Kolsky