


MANUFACTURING OVERVIEW


Overview


Scrap Products


Manufacturing Time































MANUFACTURING OVERVIEW

Overview


Scrap Products


Manufacturing Time


























Scrapped Quantity by Product & Reason		
Name	Name	TotalScrap
BB Ball Bearing		0
BB Ball Bearing	Brake assembly not as ordered	35
BB Ball Bearing	Drill pattern incorrect	22
BB Ball Bearing	Drill size too small	30
BB Ball Bearing	Gouge in metal	24
BB Ball Bearing	Handling damage	36
DD Dall Doaring	Drimar process failed	40
Total		10651



AVG Manufactoring Days

AVG Manufactoring Hours

297

Total Work Order

73K

Late Ratio

58%

MANUFACTURING OVERVIEW

Overview

Scrap Products

Manufacturing Time

Time

Product


ΑII


ΑII

ΑII

Stage

Avg Actual vs Scheduled Manufactoring Day AvgMfgDays AvgSchDays 12.9 12.4 12.5 12.1 11.0 11.0 11.0 2011 2012 2013 2014





Avg Actual vs Scheduled Day by Stages

