
3/24/2016 Next, TPC used fiber optic bridge to bypass network connection of 1H23-0302B. Then, DRS NET 2 restored to normal condition. TPC replaced the original network adapter with new ones. No more anomalies were found.

3/24/2016



TPC decided to troubleshoot by replacing NIM network adapter cards, primarily focusing on those in 1H23-PL-0301B/0302B/0303B