Komplette Tabelle der durchschnittlichen Jobpositionen jeder Instanz mit dynamischem intermediate Buffer aus 71 verschiedenen Seeds

Seed	Variation	kl.JobPosAvg	gr.JobPosAvg
10115	$v_{\alpha} = [0.25, 0.45]$	J_1 : 1	J_2 : 4
10115	$v_{\alpha} = [0.45, 0.65]$	J_1 : 1	J_2 : 4
10115	$v_{\alpha} = [0.65, 0.85]$	J_1 : 5	J_2 : 6
10115	$v_{\beta} = 0.2$	J_1 : 1.23	J_2 : 4.05
10115	$v_{\beta} = 0.5$	J_1 : 1	J_2 : 4
10115	$v_{\beta} = 0.8$	J_1 : 1	J_2 : 4
10115	$v_{\gamma} = [0.1, 0.5]$	J_1 : 1	J_2 : 4
10115	$v_{\gamma} = [0.3, 0.7]$	J_1 : 5	J_2 : 6
10115	$v_{\gamma} = [0.5, 0.9]$	J_1 : 5	J_2 : 6
10117	$v_{\alpha} = [0.25, 0.45]$	J_2 : 1	$J_4, J_6: 4, 4$
10117	$v_{\alpha} = [0.45, 0.65]$	J_2 : 1	$J_4, J_6: 4, 4$
10117	$v_{\alpha} = [0.65, 0.85]$	J_2 : 3	$J_4, J_6: 3.25, 3.25$
10117	$v_{\beta} = 0.2$	J_2 : 3	$J_4, J_6: 5.5, 5.5$
10117	$v_{\beta} = 0.5$	J_2 : 1	$J_4, J_6: 4, 4$
10117	$v_{\beta} = 0.8$	J_2 : 1	$J_4, J_6: 4, 4$
10117	$v_{\gamma} = [0.1, 0.5]$	J_2 : 1	$J_4, J_6: 4, 4$
10117	$v_{\gamma} = [0.3, 0.7]$	J_2 : 3	J_4, J_6 : 4.17, 4.17
10117	$v_{\gamma} = [0.5, 0.9]$	J_2 : 3	J_4, J_6 : 4.17, 4.17
10119	$v_{\alpha} = [0.25, 0.45]$	J_6 : 1	J_1, J_5 : 4, 4
10119	$v_{\alpha} = [0.45, 0.65]$	J_6 : 1.09	J_1, J_5 : 4, 4
10119	$v_{\alpha} = [0.65, 0.85]$	$J_6: 2$	J_1, J_5 : 4, 4
10119	$v_{\beta} = 0.2$	$J_6: 5$	J_1, J_5 : 4.5, 4.5
10119	$v_{\beta} = 0.5$	J_6 : 1	J_1, J_5 : 4, 4
10119	$v_{\beta} = 0.8$	J_6 : 1	J_1, J_5 : 4, 4
10119	$v_{\gamma} = [0.1, 0.5]$	$J_6: 2$	J_1, J_5 : 4, 4
10119	$v_{\gamma} = [0.3, 0.7]$	$J_6: 2$	J_1, J_5 : 4, 4
10119	$v_{\gamma} = [0.5, 0.9]$	$J_6: 2$	J_1, J_5 : 4, 4
10176	$v_{\alpha} = [0.25, 0.45]$	J_3 : 1	$J_1, J_6: 4, 4$
10176	$v_{\alpha} = [0.45, 0.65]$	J_3 : 1	$J_1, J_6: 4, 4$
10176	$v_{\alpha} = [0.65, 0.85]$	J_3 : 1	$J_1, J_6: 4, 4$
10176	$v_{\beta} = 0.2$	J_3 : 1	$J_1, J_6: 4, 4$
10176	$v_{\beta} = 0.5$	J_3 : 1	$J_1, J_6: 4, 4$

```
v_{\beta} = 0.8
10176
                                    J_3: 1
                                                                           J_1, J_6: 4, 4
10176
           v_{\gamma} = [0.1, 0.5]
                                    J_3: 1
                                                                           J_1, J_6: 4, 4
10176
           v_{\gamma} = [0.3, 0.7]
                                    J_3: 1
                                                                           J_1, J_6: 4, 4
           v_{\gamma} = [0.5, 0.9]
10176
                                    J_3: 1
                                                                          J_1, J_6: 4, 4
           v_{\alpha} = [0.25, 0.45]
                                    J_5: 1
                                                                           J_1, J_6: 4, 4
10178
10178
           v_{\alpha} = [0.45, 0.65]
                                    J_5: 1
                                                                          J_1, J_6: 4, 4
10178
           v_{\alpha} = [0.65, 0.85]
                                    J_5: 2.5
                                                                          J_1, J_6: 3.94, 3.94
10178
           v_{\beta} = 0.2
                                    J_5: 4
                                                                          J_1, J_6: 4.62, 4.62
10178
           v_{\beta} = 0.5
                                    J_5: 1
                                                                           J_1, J_6: 4, 4
10178
           v_{\beta} = 0.8
                                    J_5: 1
                                                                           J_1, J_6: 4, 4
10178
           v_{\gamma} = [0.1, 0.5]
                                    J_5: 1
                                                                          J_1, J_6: 4, 4
10178
           v_{\gamma} = [0.3, 0.7]
                                    J_5: 1
                                                                          J_1, J_6: 4, 4
           v_{\gamma} = [0.5, 0.9]
10178
                                    J_5: 4.75
                                                                           J_1, J_6: 4.31, 4.31
10179
           v_{\alpha} = [0.25, 0.45]
                                    J_6: 1
                                                                          J_2: 4
10179
           v_{\alpha} = [0.45, 0.65]
                                    J_6: 1
                                                                          J_2: 4
10179
           v_{\alpha} = [0.65, 0.85]
                                    J_6: 4.6
                                                                          J_2: 4.6
10179
           v_{\beta} = 0.2
                                    J_6: 1
                                                                           J_2: 5
           v_{\beta} = 0.5
                                                                           J_2: 4
10179
                                    J_6: 1
                                                                           J_2: 4
10179
           v_{\beta} = 0.8
                                    J_6: 1
                                                                           J_2: 4
10179
           v_{\gamma} = [0.1, 0.5]
                                    J_6: 1
           v_{\gamma} = [0.3, 0.7]
10179
                                    J_6: 5
                                                                           J_2: 6
           v_{\gamma} = [0.5, 0.9]
                                                                           J_2: 6
10179
                                    J_6: 5
10243
           v_{\alpha} = [0.25, 0.45]
                                    J_1, J_5: 2.5, 2.5
                                                                          J_3, J_4, J_6: 4, 4, 4
                                    J_1, J_5: 2.5, 2.5
10243
           v_{\alpha} = [0.45, 0.65]
                                                                          J_3, J_4, J_6: 4, 4, 4
                                    J_1, J_5: 2.43, 2.43
                                                                           J_3, J_4, J_6: 4.43, 4.43, 4.43
10243
           v_{\alpha} = [0.65, 0.85]
10243
           v_{\beta} = 0.2
                                    J_1, J_5: 2.55, 2.55
                                                                           J_3, J_4, J_6: 3.95, 3.95, 3.95
                                    J_1, J_5: 2.5, 2.5
10243
           v_{\beta} = 0.5
                                                                           J_3, J_4, J_6: 4.5, 4.5, 4.5
10243
           v_{\beta} = 0.8
                                    J_1, J_5: 2.5, 2.5
                                                                           J_3, J_4, J_6: 4, 4, 4
           v_{\gamma} = [0.1, 0.5]
                                    J_1, J_5: 2.5, 2.5
10243
                                                                           J_3, J_4, J_6: 4, 4, 4
                                                                          J_3, J_4, J_6: 4, 4, 4
           v_{\gamma} = [0.3, 0.7]
                                    J_1, J_5: 2.5, 2.5
10243
10243
           v_{\gamma} = [0.5, 0.9]
                                    J_1, J_5: 2.5, 2.5
                                                                          J_3, J_4, J_6: 4, 4, 4
10245
           v_{\alpha} = [0.25, 0.45]
                                    J_5: 2.33
                                                                           J_2: 4
10245
           v_{\alpha} = [0.45, 0.65]
                                    J_5: 2.58
                                                                           J_2: 4.17
10245
           v_{\alpha} = [0.65, 0.85]
                                    J_5: 2.5
                                                                           J_2: 3.5
                                                                           J_2: 5.33
10245
           v_{\beta} = 0.2
                                    J_5: 2.78
                                                                           J_2: 4.4
10245
           v_{\beta} = 0.5
                                    J_5: 3.4
10245
           v_{\beta} = 0.8
                                    J_5: 4
                                                                           J_2: 5
```

```
v_{\gamma} = [0.1, 0.5]
                                   J_5: 1.2
                                                                          J_2: 4
10245
                                   J_5: 1.2
           v_{\gamma} = [0.3, 0.7]
                                                                          J_2: 4
10245
10245
           v_{\gamma} = [0.5, 0.9]
                                   J_5: 3
                                                                          J_2: 4
                                                                          J_2: 4
10247
           v_{\alpha} = [0.25, 0.45]
                                   J_5, J_6: 2.5, 2.5
                                   J_5, J_6: 2.5, 2.5
           v_{\alpha} = [0.45, 0.65]
                                                                          J_2: 4
10247
           v_{\alpha} = [0.65, 0.85]
                                   J_5, J_6: 2.5, 2.5
                                                                          J_2: 4
10247
           v_{\beta} = 0.2
                                   J_5, J_6: 2.5, 2.5
                                                                          J_2: 4
10247
10247
           v_{\beta} = 0.5
                                   J_5, J_6: 2.5, 2.5
                                                                          J_2: 4
10247
           v_{\beta} = 0.8
                                   J_5, J_6: 2.5, 2.5
                                                                          J_2: 4
                                   J_5, J_6: 2.5, 2.5
           v_{\gamma} = [0.1, 0.5]
                                                                          J_2: 4
10247
                                   J_5, J_6: 2.5, 2.5
10247
           v_{\gamma} = [0.3, 0.7]
                                                                          J_2: 4
10247
           v_{\gamma} = [0.5, 0.9]
                                   J_5, J_6: 2.5, 2.5
                                                                          J_2: 4
10249
           v_{\alpha} = [0.25, 0.45]
                                   J_1: 5
                                                                          J_4, J_5, J_6: 4, 4, 4
10249
           v_{\alpha} = [0.45, 0.65]
                                   J_1: 2.33
                                                                          J_4, J_5, J_6: 4.11, 4.11, 4.11
10249
           v_{\alpha} = [0.65, 0.85]
                                   J_1: 2.8
                                                                          J_4, J_5, J_6: 3.96, 3.96, 3.96
10249
           v_{\beta} = 0.2
                                   J_1: 2.5
                                                                          J_4, J_5, J_6: 4.5, 4.5, 4.5
           v_{\beta} = 0.5
                                   J_1: 3.4
                                                                          J_4, J_5, J_6: 4.33, 4.33, 4.33
10249
           v_{\beta} = 0.8
                                   J_1: 4
                                                                          J_4, J_5, J_6: 3.33, 3.33, 3.33
10249
10249
           v_{\gamma} = [0.1, 0.5]
                                   J_1: 3
                                                                          J_4, J_5, J_6: 4, 4, 4
           v_{\gamma} = [0.3, 0.7]
10249
                                   J_1: 3
                                                                          J_4, J_5, J_6: 4, 4, 4
           v_{\gamma} = [0.5, 0.9]
                                   J_1: 3.14
                                                                          J_4, J_5, J_6: 3.9, 3.9, 3.9
10249
10315
           v_{\alpha} = [0.25, 0.45]
                                   J_2: 1
                                                                          J_6: 4.12
10315
           v_{\alpha} = [0.45, 0.65]
                                   J_2: 5
                                                                          J_6: 6
10315
           v_{\alpha} = [0.65, 0.85]
                                   J_2: 1
                                                                          J_6: 6
10315
           v_{\beta} = 0.2
                                   J_2: 1
                                                                          J_6: 4
           v_{\beta} = 0.5
                                   J_2: 1.67
                                                                          J_6: 2
10315
10315
           v_{\beta} = 0.8
                                   J_2: 1
                                                                          J_6: 6
10315
           v_{\gamma} = [0.1, 0.5]
                                   J_2: 5
                                                                          J_6: 6
           v_{\gamma} = [0.3, 0.7]
10315
                                   J_2: 5
                                                                          J_6: 6
           v_{\gamma} = [0.5, 0.9]
                                   J_2: 5
                                                                          J_6: 6
10315
10317
           v_{\alpha} = [0.25, 0.45]
                                   J_2, J_3: 2.5, 2.5
                                                                          J_1, J_4, J_6: 4.11, 4.11, 4.11
                                   J_2, J_3: 2.5, 2.5
10317
           v_{\alpha} = [0.45, 0.65]
                                                                          J_1, J_4, J_6: 4.5, 4.5, 4.5
           v_{\alpha} = [0.65, 0.85]
                                   J_2, J_3: 2.8, 2.8
                                                                          J_1, J_4, J_6: 4.27, 4.27, 4.27
10317
           v_{\beta} = 0.2
                                   J_2, J_3: 2.5, 2.5
                                                                          J_1, J_4, J_6: 4, 4, 4
10317
                                   J_2, J_3: 2.5, 2.5
10317
           v_{\beta} = 0.5
                                                                          J_1, J_4, J_6: 4, 4, 4
                                   J_2, J_3: 2.5, 2.5
10317
           v_{\beta} = 0.8
                                                                          J_1, J_4, J_6: 4, 4, 4
10317
           v_{\gamma} = [0.1, 0.5]
                                   J_2, J_3: 2.5, 2.5
                                                                          J_1, J_4, J_6: 4.11, 4.11, 4.11
```

```
10317 v_{\gamma} = [0.3, 0.7]
                                   J_2, J_3: 2.5, 2.5
                                                                         J_1, J_4, J_6: 4.11, 4.11, 4.11
                                   J_2, J_3: 2.5, 2.5
           v_{\gamma} = [0.5, 0.9]
                                                                          J_1, J_4, J_6: 4.11, 4.11, 4.11
10317
10318
           v_{\alpha} = [0.25, 0.45]
                                   J_4: 1
                                                                          J_6: 4
10318
           v_{\alpha} = [0.45, 0.65]
                                   J_4: 1
                                                                          J_6: 4
           v_{\alpha} = [0.65, 0.85]
                                   J_4: 1
                                                                          J_6: 4
10318
10318
           v_{\beta} = 0.2
                                   J_4: 1
                                                                         J_6: 4
10318
           v_{\beta} = 0.5
                                   J_4: 5
                                                                         J_6: 6
10318
           v_{\beta} = 0.8
                                   J_4: 1
                                                                         J_6: 4
           v_{\gamma} = [0.1, 0.5]
                                   J_4: 1
                                                                          J_6: 4
10318
           v_{\gamma} = [0.3, 0.7]
                                   J_4: 1
                                                                          J_6: 4
10318
10318
          v_{\gamma} = [0.5, 0.9]
                                   J_4: 1
                                                                         J_6: 4
                                                                         J_1: 4.1
10319
           v_{\alpha} = [0.25, 0.45]
                                   J_5: 1.19
                                                                         J_1: 4
10319
           v_{\alpha} = [0.45, 0.65]
                                   J_5: 1
10319
           v_{\alpha} = [0.65, 0.85]
                                   J_5: 1.19
                                                                         J_1: 4.1
10319
           v_{\beta} = 0.2
                                   J_5: 1
                                                                         J_1: 4
10319
           v_{\beta} = 0.5
                                   J_5: 1
                                                                         J_1: 4
           v_{\beta} = 0.8
                                   J_5: 1
                                                                          J_1: 4
10319
           v_{\gamma} = [0.1, 0.5]
                                   J_5: 1.32
                                                                          J_1: 4.14
10319
           v_{\gamma} = [0.3, 0.7]
                                                                         J_1: 5.5
10319
                                   J_5: 1
           v_{\gamma} = [0.5, 0.9]
                                                                         J_1:5.5
10319
                                   J_5: 1
10365
           v_{\alpha} = [0.25, 0.45]
                                   J_1, J_6: 2.21, 2.21
                                                                         J_4, J_5: 4.36, 4.36
                                   J_1, J_6: 2.17, 2.17
10365
           v_{\alpha} = [0.45, 0.65]
                                                                          J_4, J_5: 4, 4
10365
           v_{\alpha} = [0.65, 0.85]
                                   J_1, J_6: 3, 3
                                                                         J_4, J_5: 4.25, 4.25
                                   J_1, J_6: 2.44, 2.44
10365
           v_{\beta} = 0.2
                                                                         J_4, J_5: 4.11, 4.11
           v_{\beta} = 0.5
                                   J_1, J_6: 2.61, 2.61
                                                                         J_4, J_5: 3.89, 3.89
10365
                                   J_1, J_6: 2.75, 2.75
                                                                          J_4, J_5: 3.8, 3.8
10365
           v_{\beta} = 0.8
                                   J_1, J_6: 3.5, 3.5
                                                                         J_4, J_5: 5, 5
10365
           v_{\gamma} = [0.1, 0.5]
10365
           v_{\gamma} = [0.3, 0.7]
                                   J_1, J_6: 3.5, 3.5
                                                                          J_4, J_5: 5, 5
10365
           v_{\gamma} = [0.5, 0.9]
                                   J_1, J_6: 3.5, 3.5
                                                                         J_4, J_5: 5, 5
           v_{\alpha} = [0.25, 0.45]
                                   J_1: 1
                                                                         J_2, J_6: 4, 4
10367
10367
           v_{\alpha} = [0.45, 0.65]
                                   J_1: 1
                                                                         J_2, J_6: 4, 4
10367
           v_{\alpha} = [0.65, 0.85]
                                   J_1: 1
                                                                         J_2, J_6: 4, 4
10367
           v_{\beta} = 0.2
                                   J_1: 1.09
                                                                         J_2, J_6: 3.82, 3.82
10367
           v_{\beta} = 0.5
                                   J_1: 2.14
                                                                         J_2, J_6: 4.07, 4.07
10367
           v_{\beta} = 0.8
                                   J_1: 1
                                                                         J_2, J_6: 4, 4
10367
           v_{\gamma} = [0.1, 0.5]
                                   J_1: 1.29
                                                                         J_2, J_6: 3.86, 3.86
10367
           v_{\gamma} = [0.3, 0.7]
                                   J_1: 1.29
                                                                          J_2, J_6: 3.86, 3.86
```

```
10367
          v_{\gamma} = [0.5, 0.9]
                                   J_1: 1.29
                                                                          J_2, J_6: 3.86, 3.86
                                                                          J_1: 4
10369
          v_{\alpha} = [0.25, 0.45]
                                   J_2, J_4: 2.5, 2.5
10369
          v_{\alpha} = [0.45, 0.65]
                                   J_2, J_4: 2.5, 2.5
                                                                         J_1: 4
                                   J_2, J_4: 2.5, 2.5
                                                                         J_1: 4.25
10369
          v_{\alpha} = [0.65, 0.85]
                                   J_2, J_4: 2.5, 2.5
                                                                         J_1: 4
10369
          v_{\beta} = 0.2
10369
          v_{\beta} = 0.5
                                   J_2, J_4: 2.5, 2.5
                                                                         J_1: 4
10369
          v_{\beta} = 0.8
                                   J_2, J_4: 2.5, 2.5
                                                                         J_1: 4
10369
          v_{\gamma} = [0.1, 0.5]
                                   J_2, J_4: 2.5, 2.5
                                                                         J_1: 4
10369
          v_{\gamma} = [0.3, 0.7]
                                   J_2, J_4: 3, 3
                                                                          J_1: 6
                                   J_2, J_4: 3, 3
                                                                          J_1: 6
10369
          v_{\gamma} = [0.5, 0.9]
10405
          v_{\alpha} = [0.25, 0.45]
                                   J_3, J_5: 2.5, 2.5
                                                                         J_6: 4
10405
          v_{\alpha} = [0.45, 0.65]
                                   J_3, J_5: 2.5, 2.5
                                                                         J_6: 4
                                   J_3, J_5: 2.5, 2.5
10405
          v_{\alpha} = [0.65, 0.85]
                                                                         J_6: 4
10405
          v_{\beta} = 0.2
                                   J_3, J_5: 2.5, 2.5
                                                                         J_6: 3.93
10405
          v_{\beta} = 0.5
                                   J_3, J_5: 2.25, 2.25
                                                                         J_6: 4.12
10405
          v_{\beta} = 0.8
                                   J_3, J_5: 2.5, 2.5
                                                                         J_6: 4
                                   J_3, J_5: 2.5, 2.5
          v_{\gamma} = [0.1, 0.5]
                                                                          J_6: 4
10405
          v_{\gamma} = [0.3, 0.7]
                                   J_3, J_5: 2.5, 2.5
                                                                          J_6: 4
10405
                                   J_3, J_5: 2.5, 2.5
                                                                         J_6: 4
10405
          v_{\gamma} = [0.5, 0.9]
10407
          v_{\alpha} = [0.25, 0.45]
                                   J_4: 1.36
                                                                         J_5, J_6: 4.05, 4.05
          v_{\alpha} = [0.45, 0.65]
                                   J_4: 2.88
10407
                                                                         J_5, J_6: 4, 4
10407
          v_{\alpha} = [0.65, 0.85]
                                   J_4: 2.5
                                                                         J_5, J_6: 2.5, 2.5
10407
          v_{\beta} = 0.2
                                   J_4: 1.67
                                                                         J_5, J_6: 3.25, 3.25
10407
          v_{\beta} = 0.5
                                   J_4: 1.06
                                                                         J_5, J_6: 4.02, 4.02
10407
          v_{\beta} = 0.8
                                   J_4: 4
                                                                         J_5, J_6: 4.33, 4.33
          v_{\gamma} = [0.1, 0.5]
                                                                         J_5, J_6: 4.5, 4.5
10407
                                   J_4: 1
10407
          v_{\gamma} = [0.3, 0.7]
                                   J_4: 1
                                                                         J_5, J_6: 4.5, 4.5
10407
          v_{\gamma} = [0.5, 0.9]
                                   J_4: 1
                                                                         J_5, J_6: 4.5, 4.5
10409
          v_{\alpha} = [0.25, 0.45]
                                   J_2: 2.5
                                                                         J_3, J_4, J_5: 4.17, 4.17, 4.17
          v_{\alpha} = [0.45, 0.65]
                                   J_2: 2.5
                                                                         J_3, J_4, J_5: 4.17, 4.17, 4.17
10409
                                                                         J_3, J_4, J_5: 4.25, 4.25, 4.25
10409
          v_{\alpha} = [0.65, 0.85]
                                   J_2: 3
          v_{\beta} = 0.2
10409
                                   J_2: 1
                                                                         J_3, J_4, J_5: 4, 4, 4
10409
          v_{\beta} = 0.5
                                   J_2: 1
                                                                         J_3, J_4, J_5: 5, 5, 5
10409
          v_{\beta} = 0.8
                                   J_2: 3
                                                                         J_3, J_4, J_5: 4.67, 4.67, 4.67
10409
          v_{\gamma} = [0.1, 0.5]
                                   J_2: 2.5
                                                                         J_3, J_4, J_5: 4.17, 4.17, 4.17
          v_{\gamma} = [0.3, 0.7]
10409
                                   J_2: 3.5
                                                                         J_3, J_4, J_5: 4.33, 4.33, 4.33
10409
          v_{\gamma} = [0.5, 0.9]
                                   J_2: 3.5
                                                                         J_3, J_4, J_5: 4.33, 4.33, 4.33
```

```
J_4: 6
10435 \quad v_{\alpha} = [0.25, 0.45]
                                   J_2: 5
           v_{\alpha} = [0.45, 0.65]
                                   J_2: 4.2
                                                                          J_4: 5.2
10435
10435
           v_{\alpha} = [0.65, 0.85]
                                   J_2: 4
                                                                          J_4: 5
           v_{\beta} = 0.2
                                                                          J_4: 4
10435
                                   J_2: 1
           v_{\beta} = 0.5
                                                                          J_4: 4
10435
                                   J_2: 2
10435
           v_{\beta} = 0.8
                                   J_2: 3.33
                                                                          J_4: 5.67
10435
          v_{\gamma} = [0.1, 0.5]
                                   J_2: 3
                                                                          J_4: 4
          v_{\gamma} = [0.3, 0.7]
10435
                                   J_2: 3
                                                                          J_4: 4
10435
          v_{\gamma} = [0.5, 0.9]
                                   J_2: 3
                                                                          J_4: 4
                                                                          J_5: 4
10437
           v_{\alpha} = [0.25, 0.45]
                                   J_4: 1.62
                                                                          J_5: 3.86
10437
          v_{\alpha} = [0.45, 0.65]
                                   J_4: 3.29
10437
          v_{\alpha} = [0.65, 0.85]
                                   J_4: 2
                                                                          J_5: 5
                                                                          J_5: 4.83
10437
           v_{\beta} = 0.2
                                   J_4: 1
                                                                          J_5: 3
10437
           v_{\beta} = 0.5
                                   J_4: 2
10437
          v_{\beta} = 0.8
                                   J_4: 2.86
                                                                          J_5: 5.79
          v_{\gamma} = [0.1, 0.5]
10437
                                   J_4: 5
                                                                          J_5: 4.5
          v_{\gamma} = [0.3, 0.7]
                                                                          J_5: 4.5
                                   J_4: 5
10437
           v_{\gamma} = [0.5, 0.9]
                                                                          J_5: 4.5
10437
                                   J_4: 5
                                                                          J_5: 4
10439
          v_{\alpha} = [0.25, 0.45]
                                   J_3: 1
                                                                          J_5: 4
10439
           v_{\alpha} = [0.45, 0.65]
                                   J_3: 1
10439
           v_{\alpha} = [0.65, 0.85]
                                   J_3: 1
                                                                          J_5: 4
                                                                          J_5: 4
10439
           v_{\beta} = 0.2
                                   J_3: 1
10439
          v_{\beta} = 0.5
                                   J_3: 1
                                                                          J_5: 4
           v_{\beta} = 0.8
                                                                          J_5: 4
10439
                                   J_3: 1
          v_{\gamma} = [0.1, 0.5]
                                   J_3: 1.43
                                                                          J_5: 3.86
10439
          v_{\gamma} = [0.3, 0.7]
                                   J_3: 1.43
                                                                          J_5: 3.86
10439
          v_{\gamma} = [0.5, 0.9]
                                   J_3: 1.43
                                                                          J_5: 3.86
10439
10551
          v_{\alpha} = [0.25, 0.45]
                                   J_3: 5
                                                                          J_2: 4.5
           v_{\alpha} = [0.45, 0.65]
                                                                          J_2: 2.5
10551
                                   J_3: 4
10551
           v_{\alpha} = [0.65, 0.85]
                                   J_3: 4
                                                                          J_2: 4.25
10551
           v_{\beta} = 0.2
                                   J_3: 1
                                                                          J_2: 5.5
                                                                          J_2: 4
10551
           v_{\beta} = 0.5
                                   J_3: 1
          v_{\beta} = 0.8
                                   J_3: 4
                                                                          J_2: 5
10551
           v_{\gamma} = [0.1, 0.5]
10551
                                   J_3: 2
                                                                          J_2: 4.67
          v_{\gamma} = [0.3, 0.7]
                                                                          J_2: 4.67
10551
                                   J_3: 2
           v_{\gamma} = [0.5, 0.9]
                                                                          J_2: 3
10551
                                   J_3: 2
18055
          v_{\alpha} = [0.25, 0.45]
                                   J_5: 1
                                                                          J_1, J_3, J_4: 4.33, 4.33, 4.33
```

```
18055
          v_{\alpha} = [0.45, 0.65]
                                    J_5: 1
                                                                           J_1, J_3, J_4: 4.33, 4.33, 4.33
           v_{\alpha} = [0.65, 0.85]
                                    J_5: 1
                                                                           J_1, J_3, J_4: 4.33, 4.33, 4.33
18055
18055
           v_{\beta} = 0.2
                                    J_5: 2.5
                                                                           J_1, J_3, J_4: 3.33, 3.33, 3.33
18055
           v_{\beta} = 0.5
                                    J_5: 1
                                                                          J_1, J_3, J_4: 4, 4, 4
18055
           v_{\beta} = 0.8
                                    J_5: 2
                                                                          J_1, J_3, J_4: 4.33, 4.33, 4.33
18055
           v_{\gamma} = [0.1, 0.5]
                                    J_5: 1
                                                                          J_1, J_3, J_4: 4.33, 4.33, 4.33
18055
           v_{\gamma} = [0.3, 0.7]
                                    J_5: 1
                                                                          J_1, J_3, J_4: 4.33, 4.33, 4.33
           v_{\gamma} = [0.5, 0.9]
18055
                                    J_5: 1
                                                                          J_1, J_3, J_4: 4.33, 4.33, 4.33
18057
           v_{\alpha} = [0.25, 0.45]
                                    J_6: 5
                                                                           J_3: 6
18057
           v_{\alpha} = [0.45, 0.65]
                                    J_6: 5
                                                                           J_3: 6
18057
           v_{\alpha} = [0.65, 0.85]
                                    J_6: 4
                                                                          J_3: 5
18057
           v_{\beta} = 0.2
                                    J_6: 1
                                                                           J_3: 3.93
18057
                                                                          J_3: 4.5
           v_{\beta} = 0.5
                                    J_6: 3.5
18057
           v_{\beta} = 0.8
                                    J_6: 4.5
                                                                          J_3: 5.5
18057
           v_{\gamma} = [0.1, 0.5]
                                    J_6: 5
                                                                          J_3: 6
           v_{\gamma} = [0.3, 0.7]
18057
                                    J_6: 4
                                                                          J_3: 5
18057
           v_{\gamma} = [0.5, 0.9]
                                    J_6: 4.5
                                                                           J_3: 5.5
           v_{\alpha} = [0.25, 0.45]
                                                                           J_2: 4
18059
                                    J_6: 1
                                                                           J_2: 4
18059
           v_{\alpha} = [0.45, 0.65]
                                    J_6: 1
                                                                           J_2: 6
18059
           v_{\alpha} = [0.65, 0.85]
                                    J_6: 5
           v_{\beta} = 0.2
18059
                                    J_6: 2.14
                                                                           J_2: 3.74
18059
           v_{\beta} = 0.5
                                    J_6: 1.1
                                                                          J_2: 4.02
18059
           v_{\beta} = 0.8
                                    J_6: 1
                                                                          J_2: 4
           v_{\gamma} = [0.1, 0.5]
18059
                                    J_6: 5
                                                                          J_2: 6
           v_{\gamma} = [0.3, 0.7]
                                                                           J_2: 6
18059
                                    J_6: 5
18059
           v_{\gamma} = [0.5, 0.9]
                                    J_6: 5
                                                                           J_2: 6
                                                                          J_1: 4
18069
           v_{\alpha} = [0.25, 0.45]
                                    J_5: 1
18069
           v_{\alpha} = [0.45, 0.65]
                                    J_5: 1
                                                                           J_1: 4
                                    J_5: 1.05
                                                                           J_1: 3.95
18069
           v_{\alpha} = [0.65, 0.85]
18069
           v_{\beta} = 0.2
                                    J_5: 1
                                                                           J_1: 3.95
18069
           v_{\beta} = 0.5
                                    J_5: 1
                                                                          J_1: 3
           v_{\beta} = 0.8
                                                                          J_1: 4
18069
                                    J_5: 1
18069
           v_{\gamma} = [0.1, 0.5]
                                    J_5: 1
                                                                           J_1: 4
18069
           v_{\gamma} = [0.3, 0.7]
                                    J_5: 1
                                                                           J_1: 4
           v_{\gamma} = [0.5, 0.9]
                                                                          J_1: 4
18069
                                    J_5: 1
18106
           v_{\alpha} = [0.25, 0.45]
                                    J_3: 1
                                                                           J_2, J_6: 4, 4
18106
           v_{\alpha} = [0.45, 0.65]
                                    J_3: 1
                                                                           J_2, J_6: 4, 4
```

$v_{\alpha} = [0.65, 0.85]$	J_3 : 4	$J_2, J_6: 5.5, 5.5$
$v_{\beta} = 0.2$	J_3 : 1	$J_2, J_6: 4.67, 4.67$
$v_{\beta} = 0.5$	J_3 : 4	$J_2, J_6: 5.5, 5.5$
$v_{\beta} = 0.8$	J_3 : 1	$J_2, J_6: 4, 4$
$v_{\gamma} = [0.1, 0.5]$	J_3 : 2	$J_2, J_6: 4, 4$
$v_{\gamma} = [0.3, 0.7]$	J_3 : 2.5	$J_2, J_6: 4.38, 4.38$
$v_{\gamma} = [0.5, 0.9]$	J_3 : 2.5	$J_2, J_6: 4.38, 4.38$
$v_{\alpha} = [0.25, 0.45]$	J_3 : 5	J_1 : 6
$v_{\alpha} = [0.45, 0.65]$	J_3 : 1.19	J_1 : 4.1
$v_{\alpha} = [0.65, 0.85]$	J_3 : 2.5	J_1 : 5.5
$v_{\beta} = 0.2$	J_3 : 1	J_1 : 4
$v_{\beta} = 0.5$	J_3 : 1	J_1 : 4
$v_{\beta} = 0.8$	J_3 : 1	J_1 : 4
$v_{\gamma} = [0.1, 0.5]$	J_3 : 1	J_1 : 6
$v_{\gamma} = [0.3, 0.7]$	J_3 : 1	J_1 : 6
$v_{\gamma} = [0.5, 0.9]$	J_3 : 1	J_1 : 6
$v_{\alpha} = [0.25, 0.45]$	J_6 : 1	J_1, J_3 : 4.5, 4.5
$v_{\alpha} = [0.45, 0.65]$	J_6 : 1	J_1, J_3 : 4.33, 4.33
$v_{\alpha} = [0.65, 0.85]$	J_6 : 1	J_1, J_3 : 4.33, 4.33
$v_{\beta} = 0.2$	J_6 : 1.21	J_1, J_3 : 3.88, 3.88
$v_{\beta} = 0.5$	J_6 : 1	J_1, J_3 : 5, 5
$v_{\beta} = 0.8$	J_6 : 1	$J_1, J_3: 3.75, 3.75$
$v_{\gamma} = [0.1, 0.5]$	J_6 : 1	J_1, J_3 : 4.5, 4.5
$v_{\gamma} = [0.3, 0.7]$	J_6 : 1	J_1, J_3 : 4.5, 4.5
$v_{\gamma} = [0.5, 0.9]$	J_6 : 1	J_1, J_3 : 4.5, 4.5
$v_{\alpha} = [0.25, 0.45]$	$J_5, J_6: 1.5, 1.5$	J_2 : 3
$v_{\alpha} = [0.45, 0.65]$	$J_5, J_6: 1.5, 1.5$	J_2 : 3
$v_{\alpha} = [0.65, 0.85]$	$J_5, J_6: 1.5, 1.5$	J_2 : 3
$v_{\beta} = 0.2$	$J_5, J_6: 2.5, 2.5$	J_2 : 4
$v_{\beta} = 0.5$	$J_5, J_6: 2.5, 2.5$	J_2 : 4
$v_{\beta} = 0.8$	$J_5, J_6: 2.5, 2.5$	J_2 : 4
$v_{\gamma} = [0.1, 0.5]$	$J_5, J_6: 1.5, 1.5$	J_2 : 3
$v_{\gamma} = [0.3, 0.7]$	$J_5, J_6: 1.5, 1.5$	J_2 : 3
$v_{\gamma} = [0.5, 0.9]$	$J_5, J_6: 1.5, 1.5$	J_2 : 3
$v_{\alpha} = [0.25, 0.45]$	J_1 : 1	J_2 : 4
$v_{\alpha} = [0.45, 0.65]$	J_1 : 1	J_2 : 4
$v_{\alpha} = [0.65, 0.85]$	J_1 : 1	J_2 : 4
	$v_{\beta} = 0.2$ $v_{\beta} = 0.5$ $v_{\beta} = 0.8$ $v_{\gamma} = [0.1, 0.5]$ $v_{\gamma} = [0.5, 0.9]$ $v_{\alpha} = [0.25, 0.45]$ $v_{\alpha} = [0.45, 0.65]$ $v_{\alpha} = [0.65, 0.85]$ $v_{\beta} = 0.2$ $v_{\beta} = 0.5$ $v_{\beta} = 0.8$ $v_{\gamma} = [0.1, 0.5]$ $v_{\gamma} = [0.5, 0.9]$ $v_{\alpha} = [0.45, 0.65]$ $v_{\alpha} = [0.45, 0.65]$ $v_{\alpha} = [0.45, 0.65]$ $v_{\alpha} = [0.45, 0.65]$ $v_{\beta} = 0.8$ $v_{\gamma} = [0.1, 0.5]$ $v_{\gamma} = [0.3, 0.7]$ $v_{\gamma} = [0.5, 0.9]$ $v_{\alpha} = [0.45, 0.65]$ $v_{\beta} = 0.8$ $v_{\gamma} = [0.1, 0.5]$ $v_{\gamma} = [0.5, 0.9]$ $v_{\alpha} = [0.25, 0.45]$ $v_{\alpha} = [0.45, 0.65]$ $v_{\beta} = 0.2$ $v_{\beta} = 0.5$ $v_{\beta} = 0.8$ $v_{\gamma} = [0.1, 0.5]$ $v_{\gamma} = [0.5, 0.9]$ $v_{\alpha} = [0.25, 0.45]$ $v_{\gamma} = [0.3, 0.7]$ $v_{\gamma} = [0.5, 0.9]$ $v_{\alpha} = [0.45, 0.65]$ $v_{\gamma} = [0.3, 0.7]$ $v_{\gamma} = [0.5, 0.9]$ $v_{\alpha} = [0.45, 0.65]$	$v_{\beta} = 0.2 \qquad J_3: 1$ $v_{\beta} = 0.5 \qquad J_3: 4$ $v_{\beta} = 0.8 \qquad J_3: 1$ $v_{\gamma} = [0.1, 0.5] \qquad J_3: 2$ $v_{\gamma} = [0.3, 0.7] \qquad J_3: 2.5$ $v_{\gamma} = [0.5, 0.9] \qquad J_3: 2.5$ $v_{\alpha} = [0.25, 0.45] \qquad J_3: 5$ $v_{\alpha} = [0.45, 0.65] \qquad J_3: 1.19$ $v_{\alpha} = [0.65, 0.85] \qquad J_3: 2.5$ $v_{\beta} = 0.2 \qquad J_3: 1$ $v_{\beta} = 0.8 \qquad J_3: 1$ $v_{\gamma} = [0.1, 0.5] \qquad J_3: 1$ $v_{\gamma} = [0.3, 0.7] \qquad J_3: 1$ $v_{\gamma} = [0.5, 0.9] \qquad J_3: 1$ $v_{\alpha} = [0.25, 0.45] \qquad J_6: 1$ $v_{\alpha} = [0.45, 0.65] \qquad J_6: 1$ $v_{\beta} = 0.2 \qquad J_6: 1.21$ $v_{\beta} = 0.8 \qquad J_6: 1$ $v_{\beta} = 0.8 \qquad J_6: 1$ $v_{\gamma} = [0.1, 0.5] \qquad J_6: 1$ $v_{\gamma} = [0.3, 0.7] \qquad J_6: 1$ $v_{\gamma} = [0.5, 0.9] \qquad J_{\gamma} = [0.5, 0.9] \qquad J_{\gamma} = [0.5, 0.9]$ $v_{\gamma} = [0.5, 0.9] \qquad J_{\gamma} = [0.5, 0.9]$ $v_{\gamma} = [0.5, 0.9] \qquad J_{\gamma} = [0.5, 0.9]$ $v_{\gamma} = [0.5, 0.9] \qquad J_{\gamma} = [0.5, 0.9]$ $v_{\gamma} = [0.5, 0.9] \qquad J_{\gamma} = [0.5, 0.9]$ $v_{\gamma} = [0.5, 0.9] \qquad J_{\gamma} = [0.5, 0.9]$ $v_{\gamma} = [0.5, 0.9] \qquad J_{\gamma} = [0.5, 0.9]$ $v_{\gamma} = [0.5, 0.9] \qquad J_{\gamma} = [0.5, 0.9]$

18146	$v_{\beta} = 0.2$	J_1 : 1	J_2 : 4
18146	$v_{\beta} = 0.5$	J_1 : 1	J_2 : 4
18146	$v_{\beta} = 0.8$	J_1 : 1	J_2 : 4
18146	$v_{\gamma}=[0.1,0.5]$	J_1 : 1	J_2 : 4
18146	$v_{\gamma} = [0.3, 0.7]$	J_1 : 1	J_2 : 4
18146	$v_{\gamma} = [0.5, 0.9]$	J_1 : 1	J_2 : 4
18147	$v_{\alpha} = [0.25, 0.45]$	J_4 : 1.23	J_1 : 3.95
18147	$v_{\alpha} = [0.45, 0.65]$	J_4 : 1.5	J_1 : 4
18147	$v_{\alpha} = [0.65, 0.85]$	J_4 : 3	J_1 : 4.75
18147	$v_{\beta} = 0.2$	J_4 : 1	J_1 : 4
18147	$v_{\beta} = 0.5$	J_4 : 2	J_1 : 3
18147	$v_{\beta} = 0.8$	J_4 : 3	J_1 : 4
18147	$v_{\gamma} = [0.1, 0.5]$	J_4 : 1	J_1 : 5
18147	$v_{\gamma} = [0.3, 0.7]$	J_4 : 1	J_1 : 5
18147	$v_{\gamma} = [0.5, 0.9]$	J_4 : 1	J_1 : 5
18181	$v_{\alpha} = [0.25, 0.45]$	J_1 : 4	J_2 : 5
18181	$v_{\alpha} = [0.45, 0.65]$	J_1 : 1	J_2 : 5
18181	$v_{\alpha} = [0.65, 0.85]$	J_1 : 1	J_2 : 5
18181	$v_{\beta} = 0.2$	J_1 : 1.08	J_2 : 3.83
18181	$v_{\beta} = 0.5$	J_1 : 1	J_2 : 5
18181	$v_{\beta} = 0.8$	J_1 : 1.06	J_2 : 4.14
18181	$v_{\gamma} = [0.1, 0.5]$	J_1 : 1	J_2 : 4.6
18181	$v_{\gamma} = [0.3, 0.7]$	J_1 : 1	J_2 : 4.6
18181	$v_{\gamma} = [0.5, 0.9]$	J_1 : 1	J_2 : 4.6
18182	$v_{\alpha} = [0.25, 0.45]$	J_2, J_3 : 2.5, 2.5	$J_4, J_6: 4, 4$
18182	$v_{\alpha} = [0.45, 0.65]$	$J_2, J_3: 3, 3$	$J_4, J_6: 3, 3$
18182	$v_{\alpha} = [0.65, 0.85]$	$J_2, J_3: 3, 3$	J_4, J_6 : 4.5, 4.5
18182	$v_{\beta} = 0.2$	$J_2, J_3: 3, 3$	$J_4, J_6: 4.5, 4.5$
18182	$v_{\beta} = 0.5$	J_2, J_3 : 2.17, 2.17	J_4, J_6 : 4.08, 4.08
18182	$v_{\beta} = 0.8$	$J_2, J_3: 3, 3$	$J_4, J_6: 4.5, 4.5$
18182	$v_{\gamma} = [0.1, 0.5]$	J_2, J_3 : 2.5, 2.5	$J_4, J_6: 4, 4$
18182	$v_{\gamma} = [0.3, 0.7]$	J_2, J_3 : 2.5, 2.5	$J_4, J_6: 4, 4$
18182	$v_{\gamma} = [0.5, 0.9]$	J_2, J_3 : 2.5, 2.5	$J_4, J_6: 4, 4$
18184	$v_{\alpha} = [0.25, 0.45]$	J_4 : 1	J_2 : 4
18184	$v_{\alpha} = [0.45, 0.65]$	J_4 : 1	J_2 : 4
18184	$v_{\alpha} = [0.65, 0.85]$	J_4 : 5	J_2 : 6
18184	$v_{\beta} = 0.2$	J_4 : 1	J_2 : 3

18184	$v_{\beta} = 0.5$	J_4 : 1	J_2 : 4
18184	$v_{\beta} = 0.8$	J_4 : 1	J_2 : 4
18184	$v_{\gamma} = [0.1, 0.5]$	J_4 : 1	J_2 : 4
18184	$v_{\gamma} = [0.3, 0.7]$	J_4 : 4.12	J_2 : 5.12
18184	$v_{\gamma} = [0.5, 0.9]$	J_4 : 3.6	J_2 : 4.6
18195	$v_{\alpha} = [0.25, 0.45]$	J_4 : 1	$J_1, J_5, J_6: 4, 4, 4$
18195	$v_{\alpha} = [0.45, 0.65]$	J_4 : 1	$J_1, J_5, J_6: 4, 4, 4$
18195	$v_{\alpha} = [0.65, 0.85]$	J_4 : 5	J_1, J_5, J_6 : 4, 4, 4
18195	$v_{\beta} = 0.2$	J_4 : 1	$J_1, J_5, J_6: 4, 4, 4$
18195	$v_{\beta} = 0.5$	J_4 : 1	J_1, J_5, J_6 : 4, 4, 4
18195	$v_{\beta} = 0.8$	J_4 : 1	J_1, J_5, J_6 : 4, 4, 4
18195	$v_{\gamma} = [0.1, 0.5]$	J_4 : 1	J_1, J_5, J_6 : 4, 4, 4
18195	$v_{\gamma} = [0.3, 0.7]$	J_4 : 1	J_1, J_5, J_6 : 4, 4, 4
18195	$v_{\gamma} = [0.5, 0.9]$	J_4 : 1	$J_1, J_5, J_6: 4, 4, 4$
4103	$v_{\alpha} = [0.25, 0.45]$	J_3 : 1	J_1, J_5 : 4.33, 4.33
4103	$v_{\alpha} = [0.45, 0.65]$	J_3 : 1	J_1, J_5 : 4.33, 4.33
4103	$v_{\alpha} = [0.65, 0.85]$	J_3 : 1.75	J_1, J_5 : 4.38, 4.38
4103	$v_{\beta} = 0.2$	J_3 : 1.1	J_1, J_5 : 4.05, 4.05
4103	$v_{\beta} = 0.5$	J_3 : 1.17	J_1, J_5 : 4.08, 4.08
4103	$v_{\beta} = 0.8$	J_3 : 1.67	$J_1, J_5: 3.25, 3.25$
4103	$v_{\gamma} = [0.1, 0.5]$	J_3 : 1	J_1, J_5 : 4.33, 4.33
4103	$v_{\gamma} = [0.3, 0.7]$	J_3 : 1	J_1, J_5 : 4.33, 4.33
4103	$v_{\gamma} = [0.5, 0.9]$	J_3 : 1	J_1, J_5 : 4.33, 4.33
4105	$v_{\alpha} = [0.25, 0.45]$	J_2 : 1	J_1, J_4 : 4, 4
4105	$v_{\alpha} = [0.45, 0.65]$	J_2 : 3	J_1, J_4 : 3.88, 3.88
4105	$v_{\alpha} = [0.65, 0.85]$	J_2 : 3	J_1, J_4 : 4.17, 4.17
4105	$v_{\beta} = 0.2$	J_2 : 1	J_1, J_4 : 2.88, 2.88
4105	$v_{\beta} = 0.5$	J_2 : 1.8	J_1, J_4 : 4.04, 4.04
4105	$v_{\beta} = 0.8$	J_2 : 1	J_1, J_4 : 4, 4
4105	$v_{\gamma} = [0.1, 0.5]$	J_2 : 3	J_1, J_4 : 4.17, 4.17
4105	$v_{\gamma} = [0.3, 0.7]$	J_2 : 3	J_1, J_4 : 4.17, 4.17
4105	$v_{\gamma} = [0.5, 0.9]$	J_2 : 3	J_1, J_4 : 4.17, 4.17
4107	$v_{\alpha} = [0.25, 0.45]$	J_1 : 4	J_5 : 6
4107	$v_{\alpha} = [0.45, 0.65]$	J_1 : 4	J_5 : 2.5
4107	$v_{\alpha} = [0.65, 0.85]$	J_1 : 1	J_5 : 4.25
4107	$v_{\beta} = 0.2$	J_1 : 1	J_5 : 4.75
4107	$v_{\beta} = 0.5$	J_1 : 3.29	J_5 : 4.21

4107	$v_{\beta} = 0.8$	J_1 : 3	J_5 : 5
4107	$v_{\gamma} = [0.1, 0.5]$	J_1 : 4	J_5 : 6
4107	$v_{\gamma} = [0.3, 0.7]$	J_1 : 4	J_5 : 6
4107	$v_{\gamma} = [0.5, 0.9]$	J_1 : 2.75	J_5 : 5.12
4109	$v_{\alpha} = [0.25, 0.45]$	J_3 : 1	$J_4, J_6: 4, 4$
4109	$v_{\alpha} = [0.45, 0.65]$	J_3 : 1	$J_4, J_6: 4, 4$
4109	$v_{\alpha} = [0.65, 0.85]$	J_3 : 1	$J_4, J_6: 4, 4$
4109	$v_{\beta} = 0.2$	J_3 : 1	$J_4, J_6: 4, 4$
4109	$v_{\beta} = 0.5$	J_3 : 1	$J_4, J_6: 4, 4$
4109	$v_{\beta} = 0.8$	J_3 : 1	$J_4, J_6: 4, 4$
4109	$v_{\gamma} = [0.1, 0.5]$	J_3 : 1	$J_4, J_6: 4, 4$
4109	$v_{\gamma} = [0.3, 0.7]$	J_3 : 1	$J_4, J_6: 4, 4$
4109	$v_{\gamma} = [0.5, 0.9]$	J_3 : 1	$J_4, J_6: 4, 4$
4129	$v_{\alpha} = [0.25, 0.45]$	J_5 : 2	J_1, J_3 : 4, 4
4129	$v_{\alpha} = [0.45, 0.65]$	J_5 : 2.33	J_1, J_3 : 4.33, 4.33
4129	$v_{\alpha} = [0.65, 0.85]$	J_5 : 4	J_1, J_3 : 4.75, 4.75
4129	$v_{\beta} = 0.2$	J_5 : 1.29	J_1, J_3 : 4.57, 4.57
4129	$v_{\beta} = 0.5$	J_5 : 3.33	J_1, J_3 : 5, 5
4129	$v_{\beta} = 0.8$	J_5 : 1.26	J_1, J_3 : 3.99, 3.99
4129	$v_{\gamma} = [0.1, 0.5]$	J_5 : 1.43	J_1, J_3 : 4, 4
4129	$v_{\gamma} = [0.3, 0.7]$	J_5 : 1.43	J_1, J_3 : 4, 4
4129	$v_{\gamma}=[0.5,0.9]$	J_5 : 1.43	J_1, J_3 : 4, 4
4155	$v_{\alpha} = [0.25, 0.45]$	J_1 : 4	$J_5, J_6: 5.5, 5.5$
4155	$v_{\alpha} = [0.45, 0.65]$	J_1 : 4	$J_5, J_6: 5.5, 5.5$
4155	$v_{\alpha} = [0.65, 0.85]$	J_1 : 1	$J_5, J_6: 4.5, 4.5$
4155	$v_{\beta} = 0.2$	J_1 : 1	$J_5, J_6: 3.92, 3.92$
4155	$v_{\beta} = 0.5$	$J_1: 2$	$J_5, J_6: 4, 4$
4155	$v_{\beta} = 0.8$	$J_1: 3$	J_5, J_6 : 4.17, 4.17
4155	$v_{\gamma} = [0.1, 0.5]$	J_1 : 1	J_5, J_6 : 4.62, 4.62
4155	$v_{\gamma} = [0.3, 0.7]$	J_1 : 1	$J_5, J_6: 4.62, 4.62$
4155	$v_{\gamma}=[0.5,0.9]$	J_1 : 1	J_5, J_6 : 4.62, 4.62
4157	$v_{\alpha} = [0.25, 0.45]$	J_3 : 1	$J_2, J_6: 4, 4$
4157	$v_{\alpha} = [0.45, 0.65]$	J_3 : 1	$J_2, J_6: 4, 4$
4157	$v_{\alpha} = [0.65, 0.85]$	J_3 : 1	$J_2, J_6: 4, 4$
4157	$v_{\beta} = 0.2$	J_3 : 2	$J_2, J_6: 4, 4$
4157	$v_{\beta} = 0.5$	J_3 : 4	J_2, J_6 : 4.33, 4.33
4157	$v_{\beta} = 0.8$	J_3 : 1	$J_2, J_6: 4, 4$

4157	$v_{\gamma} = [0.1, 0.5]$	J_3 : 1	$J_2, J_6: 4, 4$
4157	$v_{\gamma} = [0.3, 0.7]$	J_3 : 1	$J_2, J_6: 4, 4$
4157	$v_{\gamma} = [0.5, 0.9]$	J_3 : 1	$J_2, J_6: 4, 4$
4158	$v_{\alpha} = [0.25, 0.45]$	J_2 : 1	J_5 : 4
4158	$v_{\alpha} = [0.45, 0.65]$	J_2 : 1	J_5 : 4
4158	$v_{\alpha} = [0.65, 0.85]$	J_2 : 1	J_5 : 4
4158	$v_{\beta} = 0.2$	J_2 : 3	J_5 : 3.33
4158	$v_{\beta} = 0.5$	J_2 : 1	J_5 : 4
4158	$v_{\beta} = 0.8$	J_2 : 1	J_5 : 4
4158	$v_{\gamma} = [0.1, 0.5]$	J_2 : 1	J_5 : 4
4158	$v_{\gamma} = [0.3, 0.7]$	J_2 : 1	J_5 : 4
4158	$v_{\gamma} = [0.5, 0.9]$	J_2 : 1	J_5 : 4
4159	$v_{\alpha} = [0.25, 0.45]$	J_5 : 4	J_1, J_6 : 4.33, 4.33
4159	$v_{\alpha} = [0.45, 0.65]$	J_5 : 4	$J_1, J_6: 3.75, 3.75$
4159	$v_{\alpha} = [0.65, 0.85]$	J_5 : 3	$J_1, J_6: 3.92, 3.92$
4159	$v_{\beta} = 0.2$	J_5 : 1.25	$J_1, J_6: 4.5, 4.5$
4159	$v_{\beta} = 0.5$	J_5 : 1.25	$J_1, J_6: 4.5, 4.5$
4159	$v_{\beta} = 0.8$	J_5 : 3	J_1, J_6 : 4.17, 4.17
4159	$v_{\gamma} = [0.1, 0.5]$	J_5 : 4	J_1, J_6 : 4.33, 4.33
4159	$v_{\gamma} = [0.3, 0.7]$	J_5 : 4	J_1, J_6 : 4.33, 4.33
4159	$v_{\gamma} = [0.5, 0.9]$	J_5 : 1	J_1, J_6 : 4.33, 4.33
4177	$v_{\alpha} = [0.25, 0.45]$	J_5 : 1	J_1, J_4 : 4, 4
4177	$v_{\alpha} = [0.45, 0.65]$	J_5 : 1	J_1, J_4 : 4, 4
4177	$v_{\alpha} = [0.65, 0.85]$	J_5 : 1	J_1, J_4 : 4, 4
4177	$v_{\beta} = 0.2$	J_5 : 1	J_1, J_4 : 4, 4
4177	$v_{\beta} = 0.5$	J_5 : 1	J_1, J_4 : 4, 4
4177	$v_{\beta} = 0.8$	J_5 : 1	J_1, J_4 : 4, 4
4177	$v_{\gamma} = [0.1, 0.5]$	J_5 : 1	J_1, J_4 : 4, 4
4177	$v_{\gamma} = [0.3, 0.7]$	J_5 : 1	J_1, J_4 : 4, 4
4177	$v_{\gamma} = [0.5, 0.9]$	J_5 : 1	J_1, J_4 : 4, 4
4178	$v_{\alpha} = [0.25, 0.45]$	J_3 : 1	J_2 : 5.75
4178	$v_{\alpha} = [0.45, 0.65]$	J_3 : 1	J_2 : 5
4178	$v_{\alpha} = [0.65, 0.85]$	J_3 : 1	J_2 : 5
4178	$v_{\beta} = 0.2$	J_3 : 1.05	J_2 : 4.02
4178	$v_{\beta} = 0.5$	J_3 : 1	J_2 : 4
4178	$v_{\beta} = 0.8$	J_3 : 1	J_2 : 5
4178	$v_{\gamma} = [0.1, 0.5]$	J_3 : 1	J_2 : 5

4178	$v_{\gamma} = [0.3, 0.7]$	J_3 : 1	J_2 : 5
4178	$v_{\gamma} = [0.5, 0.9]$	J_3 : 1	J_2 : 5
4179	$v_{\alpha} = [0.25, 0.45]$	J_6 : 1	J_2 : 4
4179	$v_{\alpha} = [0.45, 0.65]$	J_6 : 1	J_2 : 4
4179	$v_{\alpha} = [0.65, 0.85]$	J_6 : 1	J_2 : 4
4179	$v_{\beta} = 0.2$	J_6 : 1	J_2 : 4
4179	$v_{\beta} = 0.5$	J_6 : 1	J_2 : 4
4179	$v_{\beta} = 0.8$	J_6 : 1	J_2 : 4
4179	$v_{\gamma}=[0.1,0.5]$	J_6 : 1	J_2 : 4
4179	$v_{\gamma} = [0.3, 0.7]$	J_6 : 1	J_2 : 4
4179	$v_{\gamma} = [0.5, 0.9]$	J_6 : 1	J_2 : 4
4205	$v_{\alpha} = [0.25, 0.45]$	$J_1, J_3, J_6: 3, 3, 3$	J_5 : 4
4205	$v_{\alpha} = [0.45, 0.65]$	J_1, J_3, J_6 : 3.08, 3.08, 3.08	J_5 : 3.83
4205	$v_{\alpha} = [0.65, 0.85]$	J_1, J_3, J_6 : 2.57, 2.57, 2.57	J_5 : 4.3
4205	$v_{\beta} = 0.2$	J_1, J_3, J_6 : 2.95, 2.95, 2.95	J_5 : 3.79
4205	$v_{\beta} = 0.5$	$J_1, J_3, J_6: 3, 3, 3$	J_5 : 4
4205	$v_{\beta} = 0.8$	$J_1, J_3, J_6: 3, 3, 3$	J_5 : 4
4205	$v_{\gamma}=[0.1,0.5]$	$J_1, J_3, J_6: 3, 3, 3$	J_5 : 4
4205	$v_{\gamma} = [0.3, 0.7]$	$J_1, J_3, J_6: 3, 3, 3$	J_5 : 4
4205	$v_{\gamma} = [0.5, 0.9]$	$J_1, J_3, J_6: 3, 3, 3$	J_5 : 4
4207	$v_{\alpha} = [0.25, 0.45]$	J_1 : 1.71	J_4 : 4.12
4207	$v_{\alpha} = [0.45, 0.65]$	J_1 : 1.67	J_4 : 4
4207	$v_{\alpha} = [0.65, 0.85]$	J_1 : 5	J_4 : 6
4207	$v_{\beta} = 0.2$	J_1 : 1.1	J_4 : 4.03
4207	$v_{\beta} = 0.5$	J_1 : 1.12	J_4 : 3.94
4207	$v_{\beta} = 0.8$	$J_1:5$	J_4 : 5
4207	$v_{\gamma}=[0.1,0.5]$	J_1 : 1.5	J_4 : 4.12
4207	$v_{\gamma} = [0.3, 0.7]$	J_1 : 1.5	J_4 : 4.12
4207	$v_{\gamma} = [0.5, 0.9]$	J_1 : 5	J_4 : 6
4209	$v_{\alpha} = [0.25, 0.45]$	J_2 : 1	J_3 : 4
4209	$v_{\alpha} = [0.45, 0.65]$	J_2 : 4	J_3 : 4.2
4209	$v_{\alpha} = [0.65, 0.85]$	J_2 : 2	J_3 : 3
4209	$v_{\beta} = 0.2$	J_2 : 1	J_3 : 4
4209	$v_{\beta} = 0.5$	J_2 : 2.5	J_3 : 2.5
4209	$v_{\beta} = 0.8$	J_2 : 1	J_3 : 4
4209	$v_{\gamma}=[0.1,0.5]$	J_2 : 4	J_3 : 4.33
4209	$v_{\gamma} = [0.3, 0.7]$	J_2 : 4	J_3 : 4.33

4209	$v_{\gamma} = [0.5, 0.9]$	J_2 : 4	J_3 : 4.33
4228	$v_{\alpha} = [0.25, 0.45]$	J_5 : 4	$J_1: 3.75$
4228	$v_{\alpha} = [0.45, 0.65]$	J_5 : 4	J_1 : 4.5
4228	$v_{\alpha} = [0.65, 0.85]$	J_5 : 3	J_1 : 5
4228	$v_{\beta} = 0.2$	J_5 : 1	J_1 : 4
4228	$v_{\beta} = 0.5$	J_5 : 2	J_1 : 4
4228	$v_{\beta} = 0.8$	J_5 : 3	$J_1: 3$
4228	$v_{\gamma} = [0.1, 0.5]$	J_5 : 4	J_1 : 4.33
4228	$v_{\gamma} = [0.3, 0.7]$	J_5 : 2.3	J_1 : 4.2
4228	$v_{\gamma} = [0.5, 0.9]$	J_5 : 2.3	J_1 : 4.2
4229	$v_{\alpha} = [0.25, 0.45]$	J_3 : 5	J_2, J_4, J_6 : 4, 4, 4
4229	$v_{\alpha} = [0.45, 0.65]$	J_3 : 3	J_2, J_4, J_6 : 4, 4, 4
4229	$v_{\alpha} = [0.65, 0.85]$	J_3 : 2	J_2, J_4, J_6 : 4.33, 4.33, 4.33
4229	$v_{\beta} = 0.2$	J_3 : 4	J_2, J_4, J_6 : 3.33, 3.33, 3.33
4229	$v_{\beta} = 0.5$	J_3 : 3	J_2, J_4, J_6 : 5, 5, 5
4229	$v_{\beta} = 0.8$	J_3 : 4	J_2, J_4, J_6 : 3.33, 3.33, 3.33
4229	$v_{\gamma} = [0.1, 0.5]$	J_3 : 3	J_2, J_4, J_6 : 4, 4, 4
4229	$v_{\gamma} = [0.3, 0.7]$	J_3 : 2	J_2, J_4, J_6 : 4.33, 4.33, 4.33
4229	$v_{\gamma} = [0.5, 0.9]$	J_3 : 2	J_2, J_4, J_6 : 4.33, 4.33, 4.33
4249	$v_{\alpha} = [0.25, 0.45]$	J_1 : 1	J_5 : 4
4249	$v_{\alpha} = [0.45, 0.65]$	J_1 : 1	J_5 : 4
4249	$v_{\alpha} = [0.65, 0.85]$	J_1 : 3.75	J_5 : 5.75
4249	$v_{\beta} = 0.2$	J_1 : 1.5	J_5 : 3
4249	$v_{\beta} = 0.5$	J_1 : 5	J_5 : 6
4249	$v_{\beta} = 0.8$	J_1 : 1	J_5 : 4
4249	$v_{\gamma} = [0.1, 0.5]$	J_1 : 1	J_5 : 4
4249	$v_{\gamma} = [0.3, 0.7]$	J_1 : 1	J_5 : 4
4249	$v_{\gamma} = [0.5, 0.9]$	J_1 : 1	J_5 : 4
4277	$v_{\alpha} = [0.25, 0.45]$	J_1 : 1	J_5 : 4
4277	$v_{\alpha} = [0.45, 0.65]$	J_1 : 1	J_5 : 4
4277	$v_{\alpha} = [0.65, 0.85]$	J_1 : 1	J_5 : 4
4277	$v_{\beta} = 0.2$	J_1 : 1	J_5 : 4
4277	$v_{\beta} = 0.5$	J_1 : 1	J_5 : 4
4277	$v_{\beta} = 0.8$	J_1 : 1	J_5 : 4
4277	$v_{\gamma} = [0.1, 0.5]$	J_1 : 1	J_5 : 4
4277	$v_{\gamma} = [0.3, 0.7]$	J_1 : 1	J_5 : 4
4277	$v_{\gamma} = [0.5, 0.9]$	J_1 : 1	J_5 : 4

4279	$v_{\alpha} = [0.25, 0.45]$	J_5 : 1	J_6 : 4
4279	$v_{\alpha} = [0.45, 0.65]$	J_5 : 1	J_6 : 4
4279	$v_{\alpha} = [0.65, 0.85]$	J_5 : 3.5	J_6 : 4
4279	$v_{\beta} = 0.2$	J_5 : 1	J_6 : 4
4279	$v_{\beta} = 0.5$	J_5 : 4	J_6 : 5
4279	$v_{\beta} = 0.8$	J_5 : 1	J_6 : 4
4279	$v_{\gamma} = [0.1, 0.5]$	J_5 : 1	J_6 : 4
4279	$v_{\gamma} = [0.3, 0.7]$	J_5 : 1	J_6 : 4
4279	$v_{\gamma} = [0.5, 0.9]$	J_5 : 1	J_6 : 4
4289	$v_{\alpha} = [0.25, 0.45]$	J_5 : 1	J_6 : 4
4289	$v_{\alpha} = [0.45, 0.65]$	J_5 : 1.05	$J_6: 3.95$
4289	$v_{\alpha} = [0.65, 0.85]$	J_5 : 4.75	$J_6: 5.75$
4289	$v_{\beta} = 0.2$	J_5 : 1	J_6 : 4
4289	$v_{\beta} = 0.5$	J_5 : 5	J_6 : 6
4289	$v_{\beta} = 0.8$	J_5 : 1	J_6 : 4
4289	$v_{\gamma} = [0.1, 0.5]$	J_5 : 1	J_6 : 4
4289	$v_{\gamma} = [0.3, 0.7]$	J_5 : 1	J_6 : 4
4289	$v_{\gamma} = [0.5, 0.9]$	J_5 : 5	J_6 : 6
4299	$v_{\alpha} = [0.25, 0.45]$	J_3 : 5	J_6 : 4.5
4299	$v_{\alpha} = [0.45, 0.65]$	J_3 : 3	J_6 : 3
4299	$v_{\alpha} = [0.65, 0.85]$	J_3 : 1	J_6 : 4.43
4299	$v_{\beta} = 0.2$	J_3 : 5	J_6 : 6
4299	$v_{\beta} = 0.5$	J_3 : 4	$J_6: 3.75$
4299	$v_{\beta} = 0.8$	J_3 : 4	J_6 : 4.33
4299	$v_{\gamma} = [0.1, 0.5]$	J_3 : 3	J_6 : 4.5
4299	$v_{\gamma} = [0.3, 0.7]$	J_3 : 3	J_6 : 4.5
4299	$v_{\gamma} = [0.5, 0.9]$	J_3 : 3	J_6 : 4.5
4315	$v_{\alpha} = [0.25, 0.45]$	J_3 : 3	J_6 : 4.75
4315	$v_{\alpha} = [0.45, 0.65]$	J_3 : 3	J_6 : 4.8
4315	$v_{\alpha} = [0.65, 0.85]$	J_3 : 2	J_6 : 5
4315	$v_{\beta} = 0.2$	J_3 : 3	J_6 : 2
4315	$v_{\beta} = 0.5$	J_3 : 1	J_6 : 4
4315	$v_{\beta} = 0.8$	J_3 : 1	J_6 : 4
4315	$v_{\gamma} = [0.1, 0.5]$	J_3 : 2.38	J_6 : 4.54
	$v_{\gamma} = [0.3, 0.7]$		J_6 : 4.67
4315	$v_{\gamma} = [0.5, 0.9]$	J_3 : 2.38	J_6 : 4.54
4316	$v_{\alpha} = [0.25, 0.45]$	J_5 : 1	$J_2, J_3: 4, 4$

4316	$v_{\alpha} = [0.45, 0.65]$	J_5 : 1	$J_2, J_3: 4, 4$
4316	$v_{\alpha} = [0.65, 0.85]$	J_5 : 1	$J_2, J_3: 4, 4$
4316	$v_{\beta} = 0.2$	J_5 : 1	$J_2, J_3: 4, 4$
4316	$v_{\beta} = 0.5$	J_5 : 1	$J_2, J_3: 4, 4$
4316	$v_{\beta} = 0.8$	J_5 : 1	J_2, J_3 : 3.83, 3.83
4316	$v_{\gamma} = [0.1, 0.5]$	J_5 : 1	J_2, J_3 : 4.11, 4.11
4316	$v_{\gamma} = [0.3, 0.7]$	J_5 : 1	J_2, J_3 : 4.11, 4.11
4316	$v_{\gamma} = [0.5, 0.9]$	J_5 : 1	J_2, J_3 : 4.11, 4.11
4317	$v_{\alpha} = [0.25, 0.45]$	J_2 : 2	J_6 : 4
4317	$v_{\alpha} = [0.45, 0.65]$	J_2 : 2.34	J_6 : 4.23
4317	$v_{\alpha} = [0.65, 0.85]$	J_2 : 5	$J_6: 3.5$
4317	$v_{\beta} = 0.2$	J_2 : 1	J_6 : 4
4317	$v_{\beta} = 0.5$	J_2 : 2.75	J_6 : 2
4317	$v_{\beta} = 0.8$	J_2 : 3	J_6 : 4.5
4317	$v_{\gamma} = [0.1, 0.5]$	J_2 : 1.5	J_6 : 4
4317	$v_{\gamma} = [0.3, 0.7]$	J_2 : 1.5	J_6 : 4
4317	$v_{\gamma} = [0.5, 0.9]$	J_2 : 1.5	J_6 : 4
4318	$v_{\alpha} = [0.25, 0.45]$	J_2 : 1	J_1, J_4 : 4, 4
4318	$v_{\alpha} = [0.45, 0.65]$	J_2 : 1	J_1, J_4 : 4, 4
4318	$v_{\alpha} = [0.65, 0.85]$	J_2 : 1	J_1, J_4 : 4, 4
4318	$v_{\beta} = 0.2$	J_2 : 1	J_1, J_4 : 4, 4
4318	$v_{\beta} = 0.5$	J_2 : 1	J_1, J_4 : 4, 4
4318	$v_{\beta} = 0.8$	J_2 : 1	J_1, J_4 : 4.5, 4.5
4318	$v_{\gamma} = [0.1, 0.5]$	J_2 : 1	J_1, J_4 : 4, 4
4318	$v_{\gamma} = [0.3, 0.7]$	J_2 : 1	J_1, J_4 : 4, 4
4318	$v_{\gamma} = [0.5, 0.9]$	J_2 : 1	J_1, J_4 : 4, 4
4319	$v_{\alpha} = [0.25, 0.45]$	J_6 : 1	J_5 : 4
4319	$v_{\alpha} = [0.45, 0.65]$	J_6 : 1	J_5 : 4
4319	$v_{\alpha} = [0.65, 0.85]$	J_6 : 2.2	J_5 : 4.4
4319	$v_{\beta} = 0.2$	J_6 : 1.64	J_5 : 3.36
4319	$v_{\beta} = 0.5$	J_6 : 4	J_5 : 5
4319	$v_{\beta} = 0.8$	J_6 : 1	J_5 : 4
4319	$v_{\gamma} = [0.1, 0.5]$	J_6 : 5	J_5 : 6
4319	$v_{\gamma} = [0.3, 0.7]$	J_6 : 5	J_5 : 6
4319	$v_{\gamma} = [0.5, 0.9]$	J_6 : 5	J_5 : 6
4328	$v_{\alpha} = [0.25, 0.45]$	J_1 : 1	J_2 : 4
4328	$v_{\alpha} = [0.45, 0.65]$	J_1 : 1	J_2 : 4

4328	$v_{\alpha} = [0.65, 0.85]$	J_1 : 5	J_2 : 3
4328	$v_{\beta} = 0.2$	J_1 : 1	J_2 : 4
4328	$v_{\beta} = 0.5$	J_1 : 1	J_2 : 4
4328	$v_{\beta} = 0.8$	J_1 : 1	J_2 : 4
4328	$v_{\gamma} = [0.1, 0.5]$	J_1 : 5	J_2 : 4.5
4328	$v_{\gamma} = [0.3, 0.7]$	J_1 : 5	J_2 : 4.5
4328	$v_{\gamma} = [0.5, 0.9]$	J_1 : 5	J_2 : 4.5
4329	$v_{\alpha} = [0.25, 0.45]$	J_4 : 1	J_5 : 4
4329	$v_{\alpha} = [0.45, 0.65]$	J_4 : 3	J_5 : 4
4329	$v_{\alpha} = [0.65, 0.85]$	J_4 : 2.33	J_5 : 4.67
4329	$v_{\beta} = 0.2$	J_4 : 1	J_5 : 4
4329	$v_{\beta} = 0.5$	J_4 : 1	J_5 : 4.33
4329	$v_{\beta} = 0.8$	J_4 : 1	J_5 : 4
4329	$v_{\gamma} = [0.1, 0.5]$	J_4 : 2	J_5 : 3
4329	$v_{\gamma} = [0.3, 0.7]$	J_4 : 2	J_5 : 3
4329	$v_{\gamma} = [0.5, 0.9]$	J_4 : 2	J_5 : 3
4347	$v_{\alpha} = [0.25, 0.45]$	J_5 : 1	J_3 : 4
4347	$v_{\alpha} = [0.45, 0.65]$	J_5 : 1.19	J_3 : 4.1
4347	$v_{\alpha} = [0.65, 0.85]$	J_5 : 3.33	J_3 : 4.67
4347	$v_{\beta} = 0.2$	J_5 : 1.52	J_3 : 4
4347	$v_{\beta} = 0.5$	J_5 : 1	J_3 : 4
4347	$v_{\beta} = 0.8$	J_5 : 1	J_3 : 4
4347	$v_{\gamma} = [0.1, 0.5]$	J_5 : 5	J_3 : 6
4347	$v_{\gamma} = [0.3, 0.7]$	J_5 : 5	J_3 : 6
4347	$v_{\gamma} = [0.5, 0.9]$	J_5 : 5	J_3 : 6
4349	$v_{\alpha} = [0.25, 0.45]$	J_1, J_2, J_4 : 3, 3, 3	J_5 : 4
4349	$v_{\alpha} = [0.45, 0.65]$	J_1, J_2, J_4 : 3.17, 3.17, 3.17	J_5 : 3.75
4349	$v_{\alpha} = [0.65, 0.85]$	J_1, J_2, J_4 : 2.57, 2.57, 2.57	J_5 : 4.3
4349	$v_{\beta} = 0.2$	J_1, J_2, J_4 : 3, 3, 3	J_5 : 4
4349	$v_{\beta} = 0.5$	J_1, J_2, J_4 : 3, 3, 3	J_5 : 4
4349	$v_{\beta} = 0.8$	J_1, J_2, J_4 : 3, 3, 3	J_5 : 4
4349	$v_{\gamma} = [0.1, 0.5]$	J_1, J_2, J_4 : 3, 3, 3	J_5 : 4
4349	$v_{\gamma} = [0.3, 0.7]$	J_1, J_2, J_4 : 3, 3, 3	J_5 : 4
4349	$v_{\gamma} = [0.5, 0.9]$	J_1, J_2, J_4 : 3, 3, 3	J_5 : 4
4356	$v_{\alpha} = [0.25, 0.45]$	J_1, J_4 : 2.5, 2.5	J_5 : 4
4356	$v_{\alpha} = [0.45, 0.65]$	$J_1, J_4: 3, 3$	J_5 : 3
4356	$v_{\alpha} = [0.65, 0.85]$	$J_1, J_4: 3, 3$	J_5 : 3

4356	$v_{\beta} = 0.2$	J_1, J_4 : 1.75, 1.75	J_5 : 2.88
4356	$v_{\beta} = 0.5$	J_1, J_4 : 2.5, 2.5	J_5 : 5
4356	$v_{\beta} = 0.8$	J_1, J_4 : 2.5, 2.5	J_5 : 4
4356	$v_{\gamma} = [0.1, 0.5]$	J_1, J_4 : 2.25, 2.25	J_5 : 4.12
4356	$v_{\gamma} = [0.3, 0.7]$	J_1, J_4 : 2.25, 2.25	J_5 : 4.12
4356	$v_{\gamma} = [0.5, 0.9]$	J_1, J_4 : 2.25, 2.25	J_5 : 4.12
4357	$v_{\alpha} = [0.25, 0.45]$	J_5 : 1	J_1 : 5
4357	$v_{\alpha} = [0.45, 0.65]$	J_5 : 1	J_1 : 5
4357	$v_{\alpha} = [0.65, 0.85]$	J_5 : 1	J_1 : 5
4357	$v_{\beta} = 0.2$	J_5 : 1	$J_1: 2.5$
4357	$v_{\beta} = 0.5$	J_5 : 4	$J_1: 5$
4357	$v_{\beta} = 0.8$	J_5 : 1.05	$J_1: 3.98$
4357	$v_{\gamma} = [0.1, 0.5]$	J_5 : 1	J_1 : 5
4357	$v_{\gamma}=[0.3,0.7]$	J_5 : 1	J_1 : 5
4357	$v_{\gamma} = [0.5, 0.9]$	J_5 : 1	J_1 : 5