

BAY PROCEDURE


Tacoma RV Center · Document Library

CONCERN FACR08 freeze up interior leak condensate
MODEL Furrion FACR08 **DATE** 2026-09-19 **WO#** WO-FACR
PRIMARY Furrion CCD-0007990 for assembly and condensate. CCD-0008666 is the Chill book.

WHAT THIS PATTERN USUALLY MEANS

A Furrion rooftop freeze, interior leak, or condensate drip is an assembly and condensate problem. Work from CCD-0007990 for the base pan, the drain, and freeze or suction icing. CCD-0008666 is the Furrion Chill model book for layout. This is not a Dometic rooftop job, and it is not a Unity or OneControl board job.

VISUAL FLOWCHART



BAY ORDER (DO THIS FIRST)

- ☐ 1. Open CCD-0007990 for the assembly and condensate path. CCD-0008666 is fine for Furrion Chill layout.
- ☐ 2. Inspect the rooftop assembly, the evaporator pan, and the condensate drain.
- ☐ 3. Clear ice or a restricted drain and confirm the drain path before you condemn the sealed system.
- ☐ 4. Retest cooling. If the freeze or leak returns, stay on CCD-0007990.

DO NOT

- Do not start at Unity or OneControl board manuals for this rooftop freeze.
- Do not start at a Dometic-only rooftop manual for a Furrion rooftop unit.
- Do not invent OEM steps, and do not skip the drain and base-pan check.

SOURCES (SHOP DOCUMENT LIBRARY)

- Furrion Rooftop HVAC Troubleshooting & Service Manual CCD-0007990
- Furrion Chill FACR CCD-0008666