

BAY PROCEDURE


Tacoma RV Center · Document Library

CONCERN	Icing up on rear wall - only about half from the top down			
MODEL	Furrion FCR10DCGTA-BL	DATE	2026-09-19	WO# WO-ICE
PRIMARY	Furrion FCR08/FCR10 SM CCD-0008122, page 36, Ice and Moisture (Fig. 36).			

WHAT THIS PATTERN USUALLY MEANS

Ice or frost on the rear wall, including a pattern that starts about halfway down from the top, is an Ice and Moisture problem. Follow Ice or Moisture in the Fridge on CCD-0008122. This is a moisture, door gasket, and cooling path. It is not a dead-unit fuse check, and it is not a 12-volt inverter path.

VISUAL FLOWCHART



BAY ORDER (DO THIS FIRST)

- ☐ 1. Look at the frost pattern on the rear wall, including whether it starts about halfway from the top.
- ☐ 2. Check whether the temperature dial is all the way at max. If it is, back the dial off and recheck the frost pattern.
- ☐ 3. Inspect the door gasket and reseal or repair it before you condemn the cooling unit.
- ☐ 4. Verify cooling from the Ice and Moisture section on CCD-0008122 page 36. Watch or replace the unit only from that section.

DO NOT

- Do not open the no-power or 15A fuse path for this frost pattern.
- Do not start at the 12-volt inverter unless the unit is dead, has no light, or will not run.
- Do not invent other OEM pages. Stay on the Ice and Moisture section.

SOURCES (SHOP DOCUMENT LIBRARY)

- Furrion FCR08/FCR10 SM CCD-0008122 page 36
Figures: Fig. 36 - Furrion FCR08/FCR10 SM CCD-0008122 p.36