

LEAKING COOLANT PUMPS – 2.0L/P4

Customer Voice:

- Low coolant light on or smell of coolant from engine area.

Technical Description:

- The engine cooling pump has a visible coolant leak.

Status:

- Follow **TOPIX workflow** for coolant leak.
- This item will be removed from the FRED list on December 13th.
- After the 13th, please proceed with repairs as usual.

TOPIX: 303-03B: Engine Cooling - INGENIUM I4 2.0L Petrol

Range Rover

- 20-24MY RR Evoque
- 18-24MY RR Velar

Discovery

- 21-24MY Discovery Sport

Jaguar

- 19-24MY E-PACE
- 18-24MY F-PACE
- 20-24MY F-TYPE
- 19-24MY XF
- 19-21MY XE

