

Reference	SSM71539
Models	F-TYPE / X152
Title	F-Type All centre vent operation concerns
Category	Body
Last modified	05-Feb-2014 00:00:00
Symptom	107000 Interior Trim
Content	<p>Issue: Centre vent on dashboard operates incorrectly, e.g Sticks, does not rise or fall or is noisy in operation.</p> <p>Cause: Jaguar cars are aware of several causes of failure.</p> <p>Action: Update the HVAC module with software part EX53-14D520-AD as per JTB000321, and then replace the vent with a known good part from parts stock. Please retain the displaced part for return as per warranty policy and procedure.</p>