

CAMPAIGN LAUNCH STATUS - RE-LAUNCHED CAMPAIGNS
SERVICE ACTIONS - AJ20P ENGINE COOLANT PUMP OPERATION



| SERVICE ACTION N451 – OWNER NOTIFIED | | SERVICE ACTION H291 – OWNER NOTIFIED | |
|--|--|--|---|
| AFFECTED MODELS (19MY EVOQUE and 19MY DISCOVERY SPORT REMOVED) | 20 MY DISCOVERY SPORT and EVOQUE. 2019-2020 MY DISCOVERY, RR VELAR; RANGE ROVER; RANGE ROVER SPORT | AFFECTED MODELS (E-PACE REMOVED) | 2019-2020 MY F-TYPE; F-PACE; XE; XF; |
| VOLUME AFFECTED | 41,839 USA 4710 CAN | VOLUME AFFECTED | 26,229 USA 2712 CAN |
| REPAIR | All vehicles require a software update to the Powertrain Control Module (PCM) to prevent radiator fans running continuously. 20MY Evoque also require a TCM update | REPAIR | All vehicles require a software update to the Powertrain Control Module (PCM) to prevent radiator fans running continuously |
| REPAIR TIME | 0.2 hrs + Drive in/out | REPAIR TIME | 0.2 hrs + Drive in/out |
| CAMPAGN LAUNCH | July 1 st 2020 | CAMPAGN LAUNCH | July 1 st 2020 |
| Notes | 8234 in unsold Inventory. Vehicles previously updated require no further software | Notes | 3556 in unsold Inventory. Vehicles previously updated require no further software |