

Latest Vehicle Concern Fixes



No Audio Output or Loss of Audio	19 – 20MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport with InControl Touch Pro Audio System
Customer Voice: <ul style="list-style-type: none">Customer states there is no audio output from the speakers on all sources Technical Description: <ul style="list-style-type: none">IMC hardware failure Status: <ul style="list-style-type: none">Primarily reported on 19MY vehiclesCurrently investigating parts stockPlease submit an EPQR if you come across this scenario.	A technical illustration showing two views of a rectangular electronic module. The front view shows a metal frame with two circular ventilation grilles at the bottom. The rear view shows the back panel with various connectors, heat sinks, and a printed circuit board.

