

# TECHNICAL TOPICS

## ELECTRICAL



| Infotainment Updates   |  |   |   |  |
|--|--|---|---|--|
| 16 – 21MY E PACE, F PACE, I PACE, F TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport, & Defender equipped with InControl Touch Pro or Pivi |  |   |   |  |
| Activity   | Purpose  | Vehicles                                  | Completion  | Notes  |
| H251 & N377 - InControl Touch Pro Updates  | To update InControl Touch Pro vehicles to the latest IMC software level, and to enable SOTA updates moving forward.              | 16–18MY Cross Car Line                    | LR<br>78% completed +1%<br><br>Jag<br>82% completed +1% | Update performed via Pathfinder / SDD at retailer to bring the vehicle to a SOTA capable level. NDU for SDD was released on 3-Sep-20 |
| IMC 20C1 Software Release  | Provide additional bug fixes and infotainment stability 20C1 –Resolve X152 & X351 missing InControl Apps & RSE SOTA improvements | 16–20MY Cross Car Line                    | 128,720 Successful Updates                              | 21A was released on TOPIx 30-Mar-21 and suspended on 31-Mar-21<br>20C1 has been reactivated  |
| TCUv19.2   | Provide additional stability for SOTA updates and resolve Remote App concerns.   | 16–20MY Cross Car Line                    | 1,1642 Customer Updates<br>4,286 Updates via TOPIx      | Customer Update for TCUv18.2<br>TOPIX Update for TCU v14.2 – Fix on Fail   |
| Pivi IP27.2 (OS 2.0.6)   | Latest update for Pivi to provide improvements and address known issues.   | 20MY L663 Defender<br>21MY Cross Car Line | N/A Successful Updates                                  | OS 2.0.6 Launched on 27-Nov-20<br>IP30 to launch on 19-Apr-21  |



PRINTED COPIES ARE UNCONTROLLED