


Convertible Top Inoperative (Stuck Closed)	14 – 22MY F-TYPE
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> – A customer may report that the convertible top does not open from the closed position. <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> – This may be caused by a number of potential root causes. 	 <p>E293409 Manually open the folding top.</p>
<p><u>Status:</u></p> <ul style="list-style-type: none"> – The procedure to manually open the convertible top that is stuck in the closed position to allow service work to be conducted has now been added to the TOPIX Workshop Manual. – Please refer to Workshop Manual > Section 501-08 Folding Top > General Procedures > Folding Top Manual Stow Operation. – This procedure requires two people working together to slowly move the top to the open position in an even manner under constant pressure. 	<p>PRINTED COPIES ARE UNCONTROLLED</p>

