

| | |
|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Reference | SSM39211 |
| Models | S-TYPE / X200 XF / X250 XJ / X350 XJ V8 / X308 XK / X150 |
| Title | Jaguar AJ-V8 fuel injector cleaning equipment |
| Category | Engine |
| Last modified | 05-Jan-2015 00:00:00 |
| Symptom | 404000 Fuel System Concerns |
| Content | <p>Issue: Fuel injectors clogged leading to poor running / misfires / engine detonation on AJ-V8 engines.</p> <p>Cause: Poor fuel quality or fuel contaminants blocking the holes in the fuel injector.</p> <p>Action: Jaguar engineering now approve the use of the ASNU ultrasonic fuel injector cleaning system on Jaguar AJ-V8 engines.</p> <p>If the equipment is purchased, training and operating instructions for using the system will be supplied by the ASNU representative.</p> <p>For the fuel injector removal and refit process see Global Technical Reference (GTR) section 303-04.</p> <p>Contact details for ASNU and descriptions of the ultrasonic cleaning systems available can be found on the ASNU website (www.asnu.com).</p> |