

Jaguar F-Type Service Event Catalog and Events Timeline

This document provides a comprehensive overview of the service history and related events for a 2020 Jaguar F-Type (VIN: SAJDD1GX4LCK67497) owned by Nyree Hinton. The **Service Event Catalog** (left) details technical service events, repairs, and vehicle data based on invoices and work orders from Jaguar Land Rover dealerships. The **Events and Communications Timeline** (right) captures the broader context, including customer interactions, complaints, legal actions, and communications with Jaguar Land Rover and regulatory bodies.

Service Event Catalog

Vehicle Information

- **Make/Model/Year:** Jaguar F-Type, 2020
- **VIN:** SAJDD1GX4LCK67497
- **Engine:** 2.0 Liter Supercharged
- **Customer:** Nyree Hinton
- **Contact:** 732-979-6264, na@na.com
- **Address:** 616 Masselin Ave Apt 210, Los Angeles, CA 90036
- **Delivery Date:** 30SEP24
- **Warranty Expiration:** 08NOV24

Service Locations

1. **Jaguar Land Rover South Bay**
 - Address: 3233 Pacific Coast Hwy, Torrance, CA 90505
 - Phone: (310) 798-0550
 - BAR REG: AJ229534
 - EPA: CAD981683915
2. **Jaguar Land Rover Los Angeles**
 - Address: 400 S. La Brea Avenue, Los Angeles, CA 90036
 - Phone: (310) 274-5133
 - BAR REG: ARD303078
 - EPA: CAL000470554
 - Website: www.jlrla.com

Service Events

Event 1: Electrical Issues (Blown Fuse) - October 1-2, 2024

- **Invoice/Work Order:** JO8960
- **Location:** Jaguar Land Rover South Bay
- **Service Advisor:** Joel Cruz (7814)
- **Technician:** Chavez Cuevas

- **Mileage:** 23072 (In), 23073 (Out)
- **Date Opened:** 01OCT24, 14:36
- **Date Completed:** 02OCT24, 17:59
- **Issues Reported:**
 - Driver's side window does not roll up.
 - Window switch, seat switch, and lock/unlock switch not functioning.
- **Diagnosis:**
 - Verified customer concern: Window switch not working, along with seat and lock/unlock switches.
 - Found blown fuse in rear junction box for front left door module.
 - Checked power wire: 12 volts from junction box to left door control module.
 - Identified short to ground in ground wire from junction box to left door module.
- **Repairs Performed:**
 - Repaired ground wire.
 - Replaced blown fuse.
 - Post-repair: Power restored to left front door module; window switch functioning correctly.
- **Cost:** \$0.00 (Warranty, No Charge)
- **Additional Services:**
 - **Multi-Point Inspection (MPI):**
 - Tires: All at 9/32" (minimum 3/32").
 - Brakes: Front at 6mm, Rear at 4mm (minimum 3mm).
 - Battery: Tested good.
 - Declined: Rear brake replacement, scheduled maintenance.
 - **Tire Pressure Service:** Set tire pressures to specification.
- **Recommendations Declined:**
 - Rear brake pads/shoes: \$696.70 (Customer will perform later).
 - 64,000-mile service: \$1428.79 (Customer will perform later).
- **Notes:**
 - All parts new, covered by Jaguar limited warranty.
 - Hazardous waste disposal fee included in service.

Events and Communications Timeline

September 17, 2024: Vehicle Purchase

- **Event:** Nyree Hinton purchased a 2020 Jaguar F-Type (VIN: SAJDD1GX4LCK67497, mileage: 23,278) with Jaguar EliteCare warranty.
- **Details:** Delivery date recorded as 30SEP24.

October 1, 2024: Notification of Electrical Issues and Initial Drop-Off

- **Event:** Customer reported electrical problems (driver-side door electronics failing, battery issues, other electrical malfunctions) to Jaguar Land Rover South Bay.
- **Details:** Vehicle dropped off for service (Invoice #JO8960, mileage: 23072).
- **Communication:** Service advisor Joel Cruz (7814) handled the case.

October 2, 2024: Follow-up Appointment Scheduled

- **Event:** Scheduled follow-up appointment with Jaguar Land Rover Santa Monica for October 9, 2024, due to unresolved issues.
- **Details:** Repairs completed for blown fuse and ground wire (no charge, warranty-covered).

October 7, 2024: Appointment Rescheduling and Vehicle Delivery

- **Event:** Canceled Santa Monica appointment; scheduled new appointment with Jaguar Land Rover Los Angeles (Invoice #824373, mileage: 23278).
- **Details:** Reconfirmed electrical problems (driver-side door controls and battery malfunction).
- **Communication:** Vehicle delivered to Jaguar Land Rover Los Angeles; service advisor Danny Sanchez (3391) notified customer.

October 9, 2024: Battery Diagnosis

- **Event:** Technicians at Jaguar Land Rover Los Angeles drained the battery to diagnose electrical issues.
- **Details:** Notified by Danny Sanchez; ongoing diagnosis for blown fuse and battery failure.

October 10, 2024: Battery Replacement

- **Event:** Battery failed to recharge; replaced under warranty (Invoice #824373).
- **Details:** Battery failure confirmed via in-vehicle and out-of-vehicle tests; new battery installed (Part: T2H33020).

October 14, 2024: Repair Completion and Recurrence

- **Event:** Repairs completed for blown fuse (RF08) and wiring harness (no charge, warranty-covered).
- **Details:** Harness repair from C13H-13 to C1BBO1A-15; vehicle returned same day (mileage: 23279/23282).
- **Issue:** Vehicle malfunctioned again soon after, with driver-side door electronics failing.
- **Communication:** Customer noted recurrence of issues post-service.

November 7, 2024: Coolant Leak Notification

- **Event:** Customer reported "Low Coolant" warning light to Jaguar Land Rover Los Angeles (Workorder #825556).
- **Details:** Attempted to schedule appointment for 07NOV24 but earliest available was 18NOV24 due to dealership scheduling constraints.
- **Communication:** Customer expressed concern about warranty expiration (08NOV24) and requested goodwill coverage.

November 8, 2024: Warranty Expiration

- **Event:** Jaguar EliteCare warranty expired.
- **Details:** Customer unable to secure pre-expiration appointment, impacting warranty coverage for coolant leak repair.

November 14, 2024: Repurchase Request Initiated

- **Event:** Customer formally initiated repurchase request citing unresolved defects.
- **Details:** Request sent to Jaguar Corporate, referencing persistent electrical issues and coolant leak.

November 14-21, 2024: Coolant Leak Service

- **Event:** Vehicle serviced for coolant leak (Invoice #825649, mileage: 23963-23964).
- **Details:** Replaced expansion tank bleed pipe; customer charged \$294.62 post-warranty.
- **Communication:** Danny Sanchez confirmed repair completion; customer paid via Amex (Approval Code: 479385).
- **Issue:** Customer contested charge, citing pre-warranty notification and requested goodwill (CRC: 8001315826).

Post-November 21, 2024: New Electrical Malfunctions

- **Event:** New electrical issues reported post-service, including key fob failures and SOS system malfunction.
- **Details:** Issues covered by warranty but not resolved by dealership.
- **Communication:** Customer noted ongoing unresolved defects.

Early December 2024: Service Records Submission

- **Event:** Jaguar Los Angeles confirmed sending service records to Jaguar Corporate for repurchase request review.
- **Details:** Corporate later claimed records were not received, causing delays.
- **Communication:** Customer frustrated by mishandling of repurchase process.

January 30, 2025: Repurchase Denied

- **Event:** Jaguar Land Rover denied repurchase request (Case #8001315826).
- **Details:** Denial based on alleged lack of service records, despite confirmation of submission.
- **Communication:** Customer notified of decision after two-month delay.

February 3, 2025: Complaints Filed

- **Event:** Customer filed complaints with NHTSA (Complaint #11639993) and Bureau of Automotive Repair (Complaint #CC2025-2049).
- **Details:** Cited extensive post-warranty repairs (~\$10,000), missed coolant leak in inspections, new electrical issues, and failure to provide warranty documentation ("Passport to Service").
- **Communication:** Complaints addressed to Glen Leño, BAR Program Representative II.

February 3, 2025: BBB AUTO LINE Appeal

- **Event:** Customer filed appeal with BBB AUTO LINE contesting repurchase denial.
- **Details:** Sought resolution for unresolved warranty defects and repurchase or equivalent compensation.

March 7, 2025: Formal Complaint Letter

- **Event:** Nyree Hinton submitted a formal complaint letter to BAR (CC2025-2049).
- **Details:** Requested reimbursement for \$294.62 coolant repair, compensation for \$10,000 in post-warranty repairs due to inspection negligence, and resolution of warranty defects under California Business & Professions Code §9884.7(a), Cal. Civ. Code §1793.1, and Bus. & Prof. Code §472 et seq.
- **Communication:** Letter addressed to Glen Leaño, cc'd to BAR Field Operations and Enforcement Division.

Additional Context

- **Extensive Post-Warranty Repairs:** After warranty expiration, dealership recommended \$10,000 in repairs (e.g., brakes, air cleaner, oil service, rear camera) missed during prior inspections.
- **Inspection Negligence:** Multiple complimentary MPIs (October 2, November 21, 2024) failed to detect coolant leak, leading to post-warranty costs.
- **Warranty Documentation:** Dealership repeatedly failed to provide physical "Passport to Service" warranty document.
- **Legal Claims:** Customer seeks restitution under California lemon law and consumer protection statutes, citing unresolved defects and dealership negligence.
- **Customer Frustrations:** Delays in scheduling, mishandling of repurchase request, and recurrence of issues post-service contributed to dissatisfaction.