




JAGUAR
LAND ROVER
LOS ANGELES

TRANSLATE



Inspection Video



Was this video helpful?



Video Summary

The technician has completed a multi-point inspection on your vehicle. The rear tires have 6/32" of tread depth, and the front tires have 8/32" of tread depth. The technician has noted that the rear brake pads have 1 mm of thickness remaining. They have recommended replacing the rotors as they have hot spots and grooves. The voltage surface monitor is on, and the technician has recommended an oil change. The cabin filter is also reported to be dirty.

Services completed:

- Inspection of the vehicle
- Measurement of tire tread depth
- Inspection of brake pads



- Replacement of rotors
- Oil change
- Replacement of cabin filter

 *Disclaimer: AI-generated summary. Please refer to the original video for complete information.*

Was this summary helpful?



YOUR CONCERN

COMPLIMENTARY LAND ROVER
MULTI POINT INSPECTIONCredit* 

Debit

Original Approved:

\$0.00

\$0.00

YOUR CONCERN

CUSTOMER STATES RESET ALL TIRE
PRESSURESCredit* 

Debit

Original Approved:

\$0.00

\$0.00

YOUR CONCERN



PROVIDE COURTESY VEHICLE FOR
24 HOURS UNLESS OTHERWISE
EXTENDED BY JAGUAR LAND
ROVER LOS ANGELES. \$75/DAY
LATE RETURN FEE; FUEL, TOLL
VIOLATIONS AND DAMAGES WILL
BE AT THE CUSTOMERS EXPENSE.
VALID DRIVERS LICENSE AND
INSURANCE REQUIRED.



Your 2020 Jaguar F-Type: (3 items)



CUSTOMER STATES LOW
COOLANT WARNING COMING ON.
PLEASE ADVISE.



Comments: Topped up cooling system. Pressure tested cooling system to 15 psi. Inspected cooling system. recommend replacing leaking coolant hose from reservoir to top radiator hose.

Credit*

Debit

Total Approved:

\$681.64

\$661.79

✓ APPROVED BY ADVISOR



Inspect air cleaner element at 15k or
1 year intervals

Comments: Replace dirty air filter and clean air box assembly. To help improve fuel economy.

Credit*

Debit

Additional Repair Estimate:


\$489.04

\$474.80

✗ DECLINED



Inspect cabin air/HEPA micro filter(if
equipped) at 15k or year intervals



Comments: Replace dirty cabin air/HEPA micro filter and clean air box assembly. To increase cabin air quality

Credit*

Debit


Additional Repair Estimate:

\$316.46

\$307.24



Brake Linings Thickness - Rear



Comments: Replace rear pads, rotors and sensor. Rotors are worn and have grooves and hot spots.

REAR PADS

1 mm

Credit*

Debit

Additional Repair Estimate:

\$2446.97

\$2375.70

X DECLINED



TBS

Comments: Throttle plate service. Recommended with air filter replacement. To remove carbon deposits from throttle plate.

Credit*

Debit

Additional Repair Estimate:

\$188.80

\$183.30

X DECLINED



ACD

Comments: Perform a/c deodorizing and disinfecting. Recommended with filter replacement.

Credit*

Debit

Additional Repair Estimate:

\$256.00

\$248.54

X DECLINED



LOF



Multi Point Inspection

\$681.64



Comments: Service maintenance required warning is on.
Recommend oil change. Reset service indicator.

Credit*

Debit

Additional Repair Estimate:

\$581.48

\$564.54

✕ DECLINED



BFS

Comments: Brake flush. Recommended with brake replacement. Remove air and moisture from system.



Needs Immediate Attention: (8 items)

✕ DECLINED

YOUR CONCERN



*CUSTOMER STATES BRAKE PAD WARNING ON. PLEASE ADVISE.

Comments: see estimate.

Credit*

Debit

Original Approved:

\$0.00

\$0.00

REQUEST ESTIMATE

YOUR CONCERN



*CUSTOMER STATES WOULD LIKE ESTIMATE TO REPLACE AIR FITLERS

Comments: See estimate.

Credit*

Debit

Original Approved:

\$0.00

\$0.00



Needs Attention Soon: (2 items)



Multi Point Inspection

\$681.64



Inspect drive belts



Inspect hood and decklid struts



Inspect all hoses and clamps



Check brake fluid level and condition



Inspect wiper and washer operation



Inspect windshield wiper blades



Inspect rear wiper blade (if applicable)



Perform visual battery inspection



Inspect battery terminal and cables



Inspect heat and air conditioning operation



Instrument cluster warning lamps





Multi Point Inspection

\$681.64



Inspect fog/driving lights (if applicable)



Inspect taillight, turn signal, side marker and license plate lights



Inspect taillight, turn signal and side marker assemblies for cracks and damage



Inspect brake light operation



Inspect hazard light operation



Inspect reverse light operation



Inspect dash and interior lights



Check horn operation



Tread Depth Measurements - Fronts



FRONT LEFT

8/32+ /32nds

FRONT RIGHT

8/32+ /32nds



Tread Depth Measurements - Rears



REAR LEFT

6/32/32nds

REAR RIGHT

6/32/32nds



Brake Linings Thickness - Front



FRONT BRAKES

8 mm



Inspect brake system components



Inspect Engine for oil leaks



Inspect brake system for leaks



Inspect engine cooling system for leaks



Inspect transmission for leaks



Inspect steering system for leaks



Check front differential for leaks



Check rear differential for leaks



Inspect transfer case for leaks(if applicable)



Inspect fuel tank, lines and connections





Multi Point Inspection

\$681.64



Inspect engine mounts



Inspect front suspension components



Inspect transmission mounts



Inspect steering components



Inspect sway bar components



Inspect rear suspension components



Passed Inspection: (42 items)



Inspect axles, drive shaft(s), and joints and CV joints/boots



Additional: (2 items)



Windshield washer fluid



filled as needed - YES



Check and adjust tire pressures



FRONT LEFT

FRONT RIGHT

37 psi


37 psi

REAR LEFT

REAR RIGHT

37 psi

37 psi





Multi Point Inspection

\$681.64



[Terms of Service](#) | [Privacy Policy](#) | [CCPA](#)