




Inspection Video



Was this video helpful?



Video Summary



The technician was able to pressurize the cooling system and found that the coolant bypass hose is leaking, causing residue all over the engine. Additionally, the technician inspected the vehicle and found that the rear brake rotors and pads need replacement, as the rotors have been cut deeply and the pads are below minimum specifications. The technician also recommends an oil service due to the oil being low and dirty, as well as a cabin filter replacement, as the current filter is dirty and discolored.

Services completed:

- Pressurized the cooling system
- Identified a leaking coolant bypass hose

Recommendations:

- Replace the rear brake rotors and pads
- Perform an oil service
- Replace the cabin filter



Disclaimer: AI-generated summary. Please refer to the original video for complete information.

Multi Point Inspection

\$0.00

Your advisor will reach out shortly with more information.

ADVISOR
DANNY SANCHEZ
Nov 18, 2024 03:58PM

REQUEST REPAIR ESTIMATES