



Multi Point Inspection

\$0.00



JAGUAR
LAND ROVER
LOS ANGELES

TRANSLATE



Inspection Video



Your 2020 Jaguar F-Type: (2 items)



Was this video helpful?



Video Summary



The technician has inspected your vehicle and found that the front tires have a tread depth of approximately 7/32 inches, which is nearing the recommended replacement threshold. Additionally, the front brake pads have a thickness of around 9-10 millimeters, indicating they are still in good condition. However, the technician has identified a fault with the Vehicle Stability Control Module, which they recommend replacing to address the issue. Furthermore, the technician has noted that your vehicle is shaking significantly at idle, and has determined that both motor mounts are not holding vacuum properly, requiring replacement.

Services being performed:

- Inspection of tires, brakes, and vehicle



Module fault

Recommendations:

- Replacement of Vehicle Stability Control Module
- Replacement of both motor mounts

Disclaimer: AI-generated summary. Please refer to the original video for complete information.

Was this summary helpful?



YOUR CONCERN



COMPLIMENTARY LAND ROVER
MULTI POINT INSPECTION



Credit*

Debit

Original Approved:

\$0.00

\$0.00

YOUR CONCERN



CUSTOMER STATES RESET ALL TIRE
PRESSURES



Credit*

Debit

Original Approved:

\$0.00

\$0.00



Needs Immediate Attention: (3 items)

APPROVE REMAINING(\$3472.03)

YOUR CONCERN



GUEST REPORTS CHECK ENGINE
LIGHT IS COMING ON AND
VEHICLE WILL NOT GO OVER
40MPH



Comments: CHECK ENGINE LIGHT WAS NOT ON.
CONNECTED TOPIX CLOUD AND HAVE FAULT CODE
FOR QUIESCENT RELAY MODULE. RECOMMEND



Multi Point Inspection

\$0.00

	Credit*	Debit
Original Approved:	\$0.00	\$0.00
Additional Repair Estimate:	\$1199.05	\$1164.13

DECLINE

APPROVE



Inspect windshield wiper blades



Comments: FRONT WIPER BLADES STREAKING
RECOMMEND REPLACEMENT

	Credit*	Debit
Additional Repair Estimate:	\$245.52	\$238.37

DECLINE

APPROVE



Inspect engine mounts



Comments: BOTH MOTOR MOUNTS ARE NOT
HOLDING VACUUM CAUSING EXCESSIVE
VIBRATIONS AT IDLE. RECOMMEND REPLACEMENT
OF BOTH MOTOR MOUNTS

	Credit*	Debit
Additional Repair Estimate:	\$2027.45	\$1968.40

DECLINE

APPROVE



Needs Attention Soon: (2 items)



Tread Depth Measurements - Rears



REAR LEFT

4/32 - /32nds
5/ 32

REAR RIGHT

4/32 - /32nds
5/ 32

REQUEST ESTIMATE



Inspect overall tire wear and condition





Passed Inspection: (26 items)



Inspect wiper and washer operation



Perform visual battery inspection



Inspect battery terminal and cables



Inspect heat and air conditioning operation



Instrument cluster warning lamps



Inspect headlights, low and high beam operation



Inspect fog/driving lights (if applicable)



Inspect taillight, turn signal, side marker and license plate lights



Inspect taillight, turn signal and side marker assemblies for cracks and damage



Inspect brake light operation





Inspect reverse light operation



Inspect dash and interior lights



Check horn operation



Tread Depth Measurements -
Fronts



FRONT LEFT

7/32/32nds

FRONT RIGHT

7/32/32nds



Brake Linings Thickness - Front



FRONT BRAKES

10+ mm



Brake Linings Thickness - Rear



REAR PADS

10+ mm



Inspect brake system components



Inspect brake system for leaks



Inspect engine cooling system for
leaks



Inspect transmission for leaks





Multi Point Inspection

\$0.00



Inspect steering components



Inspect sway bar components



Inspect rear suspension components



Inspect axles, driveshaft(s), u-joints and CV joints/boots



Additional: (2 items)



Windshield washer fluid



filled as needed - NO



Check and adjust tire pressures



FRONT LEFT

NO psi

REAR LEFT

NO psi

FRONT RIGHT

NO psi

REAR RIGHT

NO psi