

VIN:	SAJDD1GX4LCK67497
Vehicle Type:	F-TYPE / X152
Mileage:	30294mi
Agent Group:	P4038R0428
Date:	11-05-2025

DTC Summary

Error code	Description
0x07A3 [PSM]	
U3001-46	Control Module Improper Shutdown - Calibration/parameter memory failure
GWM [GWM]	
B1412-96	Quiescent Relay Box - Component internal failure

VIN	Description
SAJDD1GX4LCK67497	F-TYPE 2.0L T/C Petrol RWD 2 Door Auto 300PS

BASIC VEHICLE INFORMATION

Distance at last claim	23282	CSO number	
Dispatch date	10/02/2019	Trim colour	Ebony/Ebony with Ebony Stitch
Sold date	11/09/2019	Paint	Narvik Black
By	05703 - US	Distance at sale	0
In use date			

ALERTS AND RESTRICTIONS

No Records

WARRANTY COVERAGE

Policy	Expiry Date	Distance
VEHICLE	11/08/2024	60000 MI Expired
PAINT	11/08/2024	60000 MI Expired
CORROSION	11/08/2025	999999 MI Expired
EMISSION_USAFEDERAL	11/08/2027	80000 MI
EMISSION_USASTATE	11/08/2026	70000 MI
DMTL Pump Extended Warranty	11/08/2029	100000 MI
Infotainment Master Controller Extended	02/03/2026	999999 MI

CAMPAIGNS

Open		Expired		Completed	
Code	Expiry Date	Code	Expiry Date	Code	Expiry Date
No Records		> H291	05/31/2022	> H335	05/25/2024

SERVICE MAINTENANCE PLAN

Open			Expired		
Code	Option	Expiry Date	Code	Option	Expiry Date
No Records			> 102E	X	12/09/2024

Model	F-TYPE / X152
Model Year	2020
Module	Gateway Module
DTC	B1412-96
Description	Quiescent Relay Box - Component internal failure

Possible Causes

- Quiescent current control module internal failure

Action

- Using the Jaguar Land Rover approved diagnostic equipment, run application - GWM Quiescent Relay Contact Clean. Clear the DTCs and retest. If the fault persists, install a new quiescent current control module


Model	F-TYPE / X152
Model Year	2020
Module	Gateway Module
DTC	B1412-96
Description	Quiescent Relay Box - Component internal failure

Possible Causes

- Quiescent current control module internal failure

Action

- Using the Jaguar Land Rover approved diagnostic equipment, run application - GWM Quiescent Relay Contact Clean. Clear the DTCs and retest. If the fault persists, install a new quiescent current control module




VIN:	SAJDD1GX4LCK67497
Vehicle Type:	F-TYPE / X152
Mileage:	30294mi
Agent Group:	P4038R0428
Date:	11-05-2025

DTC Summary

Error code	Description
0x07A3 [PSM]	
U3001-46	Control Module Improper Shutdown - Calibration/parameter memory failure
GWM [GWM]	
B1412-96	Quiescent Relay Box - Component internal failure


6.



7.

CAUTION:

Care must be taken not to damage the component.



Torque: 8Nm

INSTALLATION

1. To install, reverse the removal procedure.