2606O-07

REPAIR

HINT:

This is the repair procedure for vehicle pull.

