COMBINATION METER HOWITO PROCEED WITH TROUBLESHOOTING

05651-01

| HOW[]O[PROCEED[WITH[] ROUBLESHOOTING |
|--|
| 1 Vehicle Brought To Workshop |
| |
| 2 Customer Problem Analysis (See page 05-1169) |
| |
| 3 Problem Symptom Confirmation See page 5-1180 |
| |
| 4 Circuit[Inspection[See[page[05-1181 - 05-1222] |
| |
| 5 Repair or Replace |
| |
| 6 Confirmation Test |
| |
| 7 End |