

LIST OF FINDINGS
RIGHTSHIP
RIGHTSHIP INSPECTION SHIP QUESTIONNAIRE (RISQ 3.2)

No.	RISQ Reference	Description of Finding
1	1.20	Amendments to CSR Document Number 10 by the Marshall Islands have information written by hand.
2	1.21	The last Management visit from the Marine Department was conducted by Mr Fatih Dede on 30th Aug 2025. No records of the Tech Department were sighted
3	2.13	The vessel's manager must provide sufficient overlap for the Master / Chief Officer and Chief Engineer / Second Engineer to ensure they are familiar with the vessel's operation before taking charge. Neither senior officers nor senior engineers should be changed simultaneously. The present Master had an overlap of about 8 hours with the previous Master (22nd Jan 26)
4	2.14	The keyboard of both ECDIS is not of an approved type
5	2.14	The vessel was performing manual calculations for ECDIS Safety parameters, which are prone to errors.
6	2.2	Certificate of Financial Security is expiring on 20th Feb 2026
7	2.3	The vessel's working language is Turkish; it was not mentioned in the Log Book.
8	2.5	Rest hour records had more than 2 non-compliances (C/E Ozkan - 22nd Jan 2026)
9	2.6	Chief Officer doesn't have a Ship Handling Simulator Certificate
10	2.7	Master and Deck Personnel don't have HAZMAT training certificates for Bulk carriers.
11	2.9	Company Drug and Alcohol Policy doesn't have mention about: 1) if someone is found selling alcohol or drugs at work other than where use is permitted, 2) Not complying with stand-down orders given after a positive test result, 3) Considerations may include gender sensitivities to carry out relevant tests, and the practicalities of the sampling processes, 4) Understanding Blood vs. Breath Measurements.
12	2.9	The Company Drug and Alcohol Policy must be reviewed as required by 2.9, and changes must be made accordingly.
13	2.9	Records of Alcometer Calibration not found; the certificate on board is for M/V Manta Hacer, not for M/V Manta Merve
14	3.12	BNWAS - Three stage alarms and power failure alarms not sighted
15	3.14	Records of the changeover of steering from Auto to Manual & Manual to Auto were not sighted.
16	3.26	Crew training familiarization with the GNSS System not sighted
17	3.3	No records sighted – Radars' performance in numeric, percentage, graphical, or other measurement values should be recorded.
18	3.3	No records sighted – Radars' shadow and blind sectors
19	3.5	The Compass Error book had no observations for a few months

20	3.6	Pilot card is not complete for ECDIS Parameters, Squat, UKC, Tugs Bollard Pull, Tides, Current, Passage Plan, and Weather.
21	3.6	Master Pilot Exchange Completion Time is not mentioned in any logbook or MPX Checklists.
22	3.9	Bridge manning level was not as per the Matrix; lookout was not posted in the Singapore Straits on 23rd Jan 2026
23	4.11	The fall protection device is kept onboard as "new-in-box," and there are no records of its annual inspection.
24	4.13	The ship-shore checklist was not complete: 1) The ship-shore safety checklists should include a stevedore familiarisation section with emergency procedures, 2) The ship-shore checklist should verify compliance with cargo hold entry procedures at least once every watch.
25	4.13	Ship-shore checklist to be reviewed as per IMSBC/BLU Code
26	4.15	There is no separation between the Messroom and Smoking Room for both officers and crew. Environmental Tobacco Smoke (ETS) is also a health risk to nonsmokers.
27	4.16	No records sighted regarding officers' training in the operation of portable gas detectors.
28	4.16	Vessel has personal gas meters, not portable gas meters. SOLAS XI-1/7 regulation requires portable gas detectors to be dedicated for 4-gas (oxygen, flammable gases, or vapours (% of LFL), carbon monoxide; and hydrogen sulphides), capable of 10 hours continuous operation, waterproof and dustproof to Ingress Protection rating IP67, and capable of remote detection (using a pump with a sample hose) suitable to test the atmosphere in an enclosed space before entry.
29	4.17	Welding curtains are not available.
30	4.2	Form S 001 was not properly used to cover this question: Are safety inspections of the main deck, machinery space, accommodation, and forecastle store conducted at regular intervals in accordance with the company's procedures, and are health, safety, and environmental hazards effectively identified?
31	4.20	Not on board - A lifejacket for an adult must be designed to fit a person weighing up to 140 kg and with a chest measurement of at least 1750 mm.
32	4.33	E/R funnel fire dampers flaps didn't close completely
33	4.36	Gangway markings do not comply with MSC.1/Circ.1331, Guidelines for Construction, Installation, Maintenance, and Inspection/Survey of Means of Embarkation and Disembarkation, 2009
34	4.37	One of the pilot ladder details was not mentioned in the Record of Approved Safety Equipment.
35	4.37	Not sighted - Crew Training for Inspection of Pilot Ladder (ISO799-2:2021 Annex A)
36	4.38	SOLAS and Fire Training Manual was not ship-specific and was not updated as per the relevant items on board
37	4.4	Master's Review of SMS - Feedback from shore not sighted
38	4.41	Not sighted - Inventory of equipment required for Helicopter operations
39	4.41	Not sighted - Crew Training on Helicopter Operation
40	4.5	Enclosed Space Entry Record - 1) White-out ink used 2) The atmosphere was tested for Chlorine, Hydrogen, and other toxic gases, and results were marked as Zero, but there are no tubes or meters onboard to measure the same.

41	4.5	No records that the crew assigned to responsibilities requiring entry into enclosed spaces has attended a dedicated enclosed space entry course
42	4.7	Record of Hot Work Permit dated 24th Nov 2025 - 1) It was mentioned that the Company was notified, but no notification was sighted. 2) Company approval for the hot work permit received and attached was marked as "yes", but no evidence was sighted.
43	4.7	The RA for hot work doesn't specify the scenarios/conditions under which the vessel team must inform the company.
44	4.8	Lockout-Tagout Control: Inventory was not properly maintained. The kit was in a sealed package and was not being used onboard.
45	4.9	Critical Machinery Failure is not included in the drill matrix
46	5.10	The vessel has been flushing the A.P. tank, but no records were found in the Ballast record book.
47	5.10	Records of officers' familiarization with the BWTS and the BWMP were missing.
48	5.12	Not sighted - Records of checking the quality of the water inside the ballast tanks by visually inspecting the surface, drawing samples from the tanks, or monitoring the atmosphere within the tanks by installing a gas sampling system. Vessel has No.4 WBT P & S and No.5 D/O & FO P/S tanks adjacent to each other.
49	5.13	No seal records & no warning notice were available for the Emergency Bilge Suction valve.
50	5.15	The OWS Overboard valve didn't have any seal
51	5.25	No records sighted - Valve Opening/Closing Time, which refers to the duration the actuator of the Valve Remote Control System takes to drive the valves into an open or closed position BALLAST VALVE
52	5.27	No records sighted -Engineer officers should be familiar with the operation and maintenance of the sewage treatment plant, following the manufacturer's guidelines
53	5.6	Not sighted - PMS Record of Non-Return Valve (Overhaul + Inspect before Loading)
54	5.6	Not sighted - Visible Signage for Valves not in Use. OPEN-SHUT MARKING
55	5.9	The dewatering system was marked as completed on 17th Jan 2026, but the results were reported as "N/A".
56	6.2	No records sighted - Inspection reports were not supported with photos and /or video evidence for regular inspection of cargo holds, ballast tanks, void spaces, trunks, duct keel, and cofferdams.
57	9.2	No training records for the inspection and maintenance of the installed hatch cover type were sighted for the Master and Chief Officer.
58	9.20	No.1 crane boom operation handle was getting stuck.
59	10.1	No records sighted - Personnel assigned the responsibility for rope inspections should be properly trained to recognise rope damage and to understand the rope inspection procedures and retirement criteria.
60	10.13	Avoid painting snap-back zones on mooring decks, as they may create a false sense of security. The vessel has snap-back zones painted on the deck.
61	10.14	Rope stoppers are made of Manila rope and exceed 3 meters in length, which does not meet Rightship requirements.
62	10.18	Both anchor bitter end release pins were stuck.

63	10.22	No records sighted - An inventory of equipment onboard that can be used for emergency towing.	WEEKLY TEST
64	10.4	There are four ropes with LBDF 67, three with 65, and one with 69. This is not as per the 100-105 % of the SDMBL requirement. The SDMBL of the vessel is 48.9 MT.	
65	10.5	Winch Brakes are not tested to 60% of the SDMBL, which is 29.34 MT. The brakes at the moment will render at 26.0T.	
66	10.5	The winch brake adjustment pin had excessive clearances.	
67	11.2	No records sighted - Proper operation of the DSC facilities by means of a test call when within the communication range of a coast station fitted with DSC equipment.	
68	12.1	The pre-rightship inspector was not made aware of any specific hazards to the cargo or operations onboard the vessel, and was not provided with instructions on what to do in the event of an emergency.	5 YEARS
69	12.5	No records sighted of updated security charts.	
70	13.11	No records sighted of crew Training for PMS. CARETTA CERT	
71	13.11	The vessel didn't have many critical items as per the relevant list.	
72	13.27	Periodic inspection of the portable lifting equipment is not being made.12 MONTHS	
73	13.29	An excessive amount of water was in the ER bilges, about 10 cm of sounding.	AIR CONDITION
74	13.3	The Chief Engineer's Standing Orders were not signed by the CE or any other Engineer.	
75	13.36	No records sighted - An inventory of equipment onboard that can be used for emergency towing.	
76	13.9	The vessel has been transferring grey water to the A.P. tank, but no appropriate entries have been made. Rightship recommends a Grey and Black water discharge log.	
77	14.12	Delivery pipes of Oxygen and Acetylene bottles in the locker were rusted.	
78	14.6	Stencilling on the ventilators and doors was missing around the accommodation.	AIR CONDITION
79	14.6	Ventilators around the accommodation were rusted, and the mesh was damaged.	
80	15.14	No records sighted - Regular maintenance and cleaning of AHU available.	
81	17.1	The vessel didn't have an STS Operation plan.	
82	17.7	No records sighted regarding the Master and Officers training for STS Operations.	