

RightShip Ship Inspection Program

List of Findings

RightShip Ship Inspection Report - 69615

A general cargo ship that is carrying general cargo and/or container cargo

Vessel Name:	DEVBULK ASLAN
IMO Number:	9673604
DOC Company:	Devbulk Gemi Isletmeciligi AS
Place of Inspection:	Bangladesh, Chittagong
Name of Inspector:	Muhammad Haider Ali
Inspection Completion Date:	6/8/2026 12:00:00 AM
Operational Variant:	

This is a list of Findings made during my inspection of your vessel, completed today. As the scope and scale of the inspection has been limited by time and operational constraints, this does not necessarily constitute a comprehensive list of all Findings on board.

A copy of this list together with a detailed inspection report will be submitted to RightShip, who will liaise directly with your owners / managers in due course. The following Findings should not be considered as a final or comprehensive list and RightShip reserves the right to add to or amend these Findings. If RightShip adds to or amends the list of Findings, they will advise the owner/ship's manager.

When RightShip reviews the inspection report, the vessel's manager and Master will be given the opportunity to provide comments and response to each Finding on the list.

This list of Findings does not constitute any warranty of the fitness or suitability of the vessel. Thank you for the cooperation and hospitality accorded to me by yourself and your crew.

DISCLAIMER

THIS DOCUMENT AND THE CONTENTS HEREOF ARE PREPARED SOLELY FOR RIGHTSHIP'S CUSTOMER IN RESPECT OF THE VESSEL(S) NAMED FOR RIGHTSHIP INSPECTION AND ARE NOT INTENDED FOR ANY THIRD PARTY TO ACCESS, USE, RELY ON OR DISTRIBUTE WITHOUT RIGHTSHIP'S EXPLICIT WRITTEN CONSENT. NOTWITHSTANDING ANY CONSENT THAT MAY HAVE BEEN GIVEN BY RIGHTSHIP AS AFOREMENTIONED, RIGHTSHIP SHALL HAVE NO LIABILITY WHATSOEVER AND HOWSOEVER ARISING TO ANY SUCH PERSON OR ENTITY, OR THIRD PARTY RECIPIENT, WHETHER IN CONTRACT, TORT OR OTHERWISE.

IF, IN RELIANCE OF THIS DOCUMENT, YOU ELECT TO CHARTER ANY VESSEL OR MAKE ANY COMMERCIAL OR OTHER DELIBERATIONS IN CONNECTION WITH IT, YOU DO SO AT YOUR OWN RISK AND YOU MUST MAKE YOUR OWN ASSESSMENT AND SATISFY YOURSELF AS TO THE ACCURACY AND COMPLETENESS OF THE INFORMATION CONTAINED IN THIS DOCUMENT. RIGHTSHIP PROVIDE NO WARRANTY AS TO THE SAFETY OR QUALITY OF THAT VESSEL, ITS FITNESS FOR ANY PURPOSE, OR ANY OTHER FINDINGS ABOUT IT AND RIGHTSHIP DO NOT ACCEPT RESPONSIBILITY OR LIABILITY FOR ANY INCOMPLETENESS OR INACCURACIES IN THE INFORMATION CONTAINED IN THIS DOCUMENT THAT MAY INCLUDE UNVERIFIABLE INFORMATION OF CUSTOMER AND/OR THIRD PARTIES.

THIS DOCUMENT CONTAINS CONFIDENTIAL AND/OR LEGALLY PRIVILEGED INFORMATION AND IS SUBJECT TO THE INTELLECTUAL PROPERTY RIGHTS AND OTHER PROPRIETARY RIGHTS OF RIGHTSHIP AND/OR ITS LICENSORS. UNAUTHORISED ACCESS, USE OR DISTRIBUTION OF THIS DOCUMENT OR ANY CONTENTS HEREOF CONSTITUTES BREACH OF OBLIGATION OF CONFIDENCE TO AND/OR INFRINGEMENT OF INTELLECTUAL PROPERTY AND OTHER PROPRIETARY RIGHTS OF RIGHTSHIP AND/OR ITS LICENSORS, WHICH MAY RESULT IN LEGAL ACTION TAKEN AGAINST YOU. FOR MORE INFORMATION ABOUT THE RIGHTS AND OBLIGATIONS OF RIGHTSHIP'S INSPECTION CUSTOMERS, PLEASE REFER TO TERMS AND CONDITIONS GOVERNING RIGHTSTORE, COPY OF WHICH MAY BE ACCESSED ON RIGHTSTORE OR SUCH OTHER PORTAL ON WHICH RIGHTSHIP MAY CHOOSE TO PUBLISH.

Number of Findings: 11

Section 3: Navigation

3.18 Is the ECDIS of an approved type, compliant with SOLAS requirements, and can the Master and watch keeping officers demonstrate familiarity with its use?

Findings: 2 ECDISs failure drill was not conducted so far (ECDISs were primary means of Navigation). Hence, the bridge team were unfamiliar with the company's contingency plans for ECDIS failures.

3.24 Was the ship's track monitored at sea and during pilotage, and were parallel indexing techniques used to monitor the passage in coastal and pilotage waters ,particularly during restricted visibility or nighttime conditions?

Findings: Deck officers were found not familiar with the parallel index techniques and no evidence found if the parallel index techniques had been used in last voyage to monitor the track of the vessel when passing a suitable features in coastal and pilotage waters , particularly during restricted visibility or at night time conditions.

Section 5: Pollution Prevention and Control

5.8 Are suitable containment arrangements in place around the hydraulic components of deck machinery? (V)

Findings: No containment arrangement / spill Trays were fitted under the hatch cover operating levers' control box stand on deck.

5.9 Are the emergency arrangements to pump out the spaces forward of the collision bulkhead in the event of flooding in good order, and are these arrangements prominently marked? (V)

Findings: The marking (Warning posters) of the system valves and controls of forward D'watering system to ensure correct operation and to avoid accidental opening were not found in place. Vessel specific procedure was not provided/ not found.

Section 12: Security

12.1 Is access to the ship being controlled by an adequate deck watch? (V)

Findings: Access point duty AB could not able to explain in regards to security for visitor entry and when to check ID&when to check visitors bags (Lack of ISPS) Also not explained to Inspector on all emergency alarms and for Mustering points.

12.7 Are cyber security policies and procedures integrated into the safety management system, and has the cyber security management system been evaluated and certified? (V)

Findings: Company Cyber security management system was not undergone for operational, technical, and physical evaluation in accordance with industry standards, and was not evaluated & certified by an expert cyber security firm .

Section 13: Machinery Space

13.14 Are the auxiliary engines maintained as per manufacturer's recommendations and records of periodic maintenance kept?(V)

Findings: Checks on Auxiliary Engines (AE) maintenance records revealed that the following AE many Items were overdue for Overhaul: Manuf & PMS recommendations / Present running hours as below : DG-1: 1) Cylinder Piston 8000/10565 hours for DG 1 for all 6 nos units. 2)Semi (Cylinder head) O/H 8000/10565 hours for DG-1 for all 6 units. 3) Fuel Injector Nozzles 1500/2227 hours for DG-1 for all 6 units. 4)Cylinder Liner O/H 8000/10565 hours for DG-1 for all 6 units. 5) T/C nozzle ring 8000/8054 hours for DG-1 5) T/C Crank deflection 4000/6433 hours for DG-1. DG-2: 1) Cylinder Piston 8000/10934 hours for DG 2 for all 6 nos units. 2)Semi (Cylinder head) O/H 8000/10934 hours for DG-2 for all 6 units. 3) Fuel Injector Nozzles 1500/3131 hours for DG-2 for all 6 units. 4)Cylinder Liner O/H 8000/10934 hours for DG-2 for all 6 units. 5) T/C nozzle ring 8000/8089 hours for DG-2 . 5) T/C G.O.V. nozzle ring 8000/8089 hours for DG-2 . 6) T/C Crank deflection 500/2433 hours for DG-2 .

13.20 Is the lagging and insulation in good condition and free of oil impregnation? (V)

Findings: AE- 1&2 exhaust side laggings found missing/displaced at places and temperature measured 226 -230° C. (>220°)

13.26 Is the workshop clean and tidy, and are the engine room workshop tools' protective guards, shields, and emergency stops in good condition? (V)

Findings: 1)Engine room workshop was not provided with fire curtain surrounding the welding/gas/flame cutting area. 2)No IMO safety posters were posted around the spinning grinder machine area and around hot works areas in Engine room workshop.

13.37 If the starting source of the emergency generator relies on a single starter motor, has a spare starter motor been provided? (V)

Findings: The starting source of the emergency generator was relied on a single starter motor and a spare starter motor had not been provided on board.

Section 14: General Appearance - Hull and Superstructure

14.19 Are the ship's guard rails, walkways, and access ladders, as well as the steps and railings, maintained and in good working order, and are the securing arrangements for deck cargoes on the deck also maintained and in satisfactory condition?(V)

Findings: The chains strung between guard rail stanchions, in lieu of a fixed railing around main deck ,boat decks were sagging and fail to provide a minimum clearance of one meter from the deck. (Measured 85-95cm clearance from the deck)

Vessel's Master Name

Sahin Aytekin

Vessel's Master Email Address

devbulkaslan@devbulk.com

- ☒ By signing the list of Findings, I confirm a closing meeting has taken place and the inspector has informed me that, where not already transmitted, the list of Findings will be sent via internet email once connectivity is restored.

Vessel's Master Signature:



Inspector Name

Muhammad Haider Ali

Inspector's Signature:



CONTACT US

If you're interested and would like to know more, get in touch with our team today.

 www.rightship.com

 dryinspections@rightship.com

 RightShip

MELBOURNE

 Level 8/ 550 Bourke Street,
Melbourne VIC 3000,
Australia

 +61 3 8686 5750

LONDON

 4th Floor, 6 Dowgate Hill,
London EC4R 2SU, United
Kingdom

 +44 203 872 5900

SINGAPORE

 20 Cecil Street, PLUS,
#13-06
Singapore 049705

 +65 3138 3855

HOUSTON

 Suite 140 14141
Southwest Freeway,
Sugar Land TX 77478,
United States of America

 +1 832 770 8200

MALTA

 The Tower, 3rd Floor,
Fortunato Mizzi Street,
Ir-Rabat Għawdex
VCT 2517, Malta