

RightShip Ship Inspection Program

List of Findings

RightShip Ship Inspection Report - 75565

A general cargo ship that is carrying general cargo and/or container cargo

Vessel Name:	DEVBULK DAMLA
IMO Number:	9711717
DOC Company:	Devbulk Gemi Isletmeciligi AS
Place of Inspection:	China, Yantai
Name of Inspector:	Liu Shibao
Inspection Completion Date:	7/26/2026 12:00:00 AM
Operational Variant:	

This is a list of Findings made during my inspection of your vessel, completed today. As the scope and scale of the inspection has been limited by time and operational constraints, this does not necessarily constitute a comprehensive list of all Findings on board.

A copy of this list together with a detailed inspection report will be submitted to RightShip, who will liaise directly with your owners / managers in due course. The following Findings should not be considered as a final or comprehensive list and RightShip reserves the right to add to or amend these Findings. If RightShip adds to or amends the list of Findings, they will advise the owner/ship's manager.

When RightShip reviews the inspection report, the vessel's manager and Master will be given the opportunity to provide comments and response to each Finding on the list.

This list of Findings does not constitute any warranty of the fitness or suitability of the vessel. Thank you for the cooperation and hospitality accorded to me by yourself and your crew.

DISCLAIMER

THIS DOCUMENT AND THE CONTENTS HEREOF ARE PREPARED SOLELY FOR RIGHTSHIP'S CUSTOMER IN RESPECT OF THE VESSEL(S) NAMED FOR RIGHTSHIP INSPECTION AND ARE NOT INTENDED FOR ANY THIRD PARTY TO ACCESS, USE, RELY ON OR DISTRIBUTE WITHOUT RIGHTSHIP'S EXPLICIT WRITTEN CONSENT. NOTWITHSTANDING ANY CONSENT THAT MAY HAVE BEEN GIVEN BY RIGHTSHIP AS AFOREMENTIONED, RIGHTSHIP SHALL HAVE NO LIABILITY WHATSOEVER AND HOWSOEVER ARISING TO ANY SUCH PERSON OR ENTITY, OR THIRD PARTY RECIPIENT, WHETHER IN CONTRACT, TORT OR OTHERWISE.

IF, IN RELIANCE OF THIS DOCUMENT, YOU ELECT TO CHARTER ANY VESSEL OR MAKE ANY COMMERCIAL OR OTHER DELIBERATIONS IN CONNECTION WITH IT, YOU DO SO AT YOUR OWN RISK AND YOU MUST MAKE YOUR OWN ASSESSMENT AND SATISFY YOURSELF AS TO THE ACCURACY AND COMPLETENESS OF THE INFORMATION CONTAINED IN THIS DOCUMENT. RIGHTSHIP PROVIDE NO WARRANTY AS TO THE SAFETY OR QUALITY OF THAT VESSEL, ITS FITNESS FOR ANY PURPOSE, OR ANY OTHER FINDINGS ABOUT IT AND RIGHTSHIP DO NOT ACCEPT RESPONSIBILITY OR LIABILITY FOR ANY INCOMPLETENESS OR INACCURACIES IN THE INFORMATION CONTAINED IN THIS DOCUMENT THAT MAY INCLUDE UNVERIFIABLE INFORMATION OF CUSTOMER AND/OR THIRD PARTIES.

THIS DOCUMENT CONTAINS CONFIDENTIAL AND/OR LEGALLY PRIVILEGED INFORMATION AND IS SUBJECT TO THE INTELLECTUAL PROPERTY RIGHTS AND OTHER PROPRIETARY RIGHTS OF RIGHTSHIP AND/OR ITS LICENSORS. UNAUTHORISED ACCESS, USE OR DISTRIBUTION OF THIS DOCUMENT OR ANY CONTENTS HEREOF CONSTITUTES BREACH OF OBLIGATION OF CONFIDENCE TO AND/OR INFRINGEMENT OF INTELLECTUAL PROPERTY AND OTHER PROPRIETARY RIGHTS OF RIGHTSHIP AND/OR ITS LICENSORS, WHICH MAY RESULT IN LEGAL ACTION TAKEN AGAINST YOU. FOR MORE INFORMATION ABOUT THE RIGHTS AND OBLIGATIONS OF RIGHTSHIP'S INSPECTION CUSTOMERS, PLEASE REFER TO TERMS AND CONDITIONS GOVERNING RIGHTSTORE, COPY OF WHICH MAY BE ACCESSED ON RIGHTSTORE OR SUCH OTHER PORTAL ON WHICH RIGHTSHIP MAY CHOOSE TO PUBLISH.

Number of Findings: 16

Section 2: Certification and Personal Management

2.7 Have officers and ratings responsible for cargo handling on ships carrying dangerous and hazardous substances in solid form in bulk, undergone formal training? (V)

Findings: Officers and ratings responsible for cargo handling on ships carrying dangerous and hazardous substances in solid form in bulk were not received formal training.

Section 4: ISM System

4.11 Has a PPE Matrix for use of personal protective equipment been provided and is it being worn as required?

Findings: The requirement to use inertia reel personal fall arrest systems during aloft and overside work has not been specified in the PPE Matrix. There was no evidence to confirm that fall protection equipment was inspected every 12 months by a competent person in accordance with the manufacturer's instructions.

4.13 Is a completed IMSBC/BLU Code ship/shore safety checklist for loading and unloading dry bulk carriers available and are the requirements of the checklist complied with?

Findings: Ship/Shore Safety Checklist dated 11/JUN/2026 was reviewed: The verification of compliance with cargo hold entry procedures was not recorded for every watch.

4.16 Are portable gas detectors suitable for atmosphere testing of enclosed spaces provided; in good condition; calibrated in accordance with the manufacturer's instructions, and are officers trained and competent with their operation?

Findings: Two multi-gas detectors were carried on board with valid calibration certificates. None were fitted with carbon dioxide detection function.

4.36 Are accommodation ladders and gangways maintained in good condition, marked clearly, and inspected regularly

Findings: The port side accommodation ladder turn table was found its nut corroded rusty at the time of inspection.

Section 5: Pollution Prevention and Control

5.8 Are suitable containment arrangements in place around the hydraulic components of deck machinery? (V)

Findings: All hatch cover control valve stations were not provided with the containment arrangements.

5.25 Are the ballast pumping systems, including their associated instruments, controls, valves, pipework, and the control panel (including pressure gauges, draft gauges, and the remote control system), in good working order and is there recorded evidence of regular inspection?

Findings: 1. No.1 F. O STORAGE Tk (S) Level sensor failure was found on the monitor screen in ship's office at the time of inspection. 2. The drafting gauging system located in the ship's office was found had inaccurate indication, the fore draft was shown as "21.3m" at the time of inspection.

Attachments:



[Q525_d7c5d0f8-6326-405d-9eae-bc3349bf728e.jpg](#)

Section 7A: Fuel Management (Oil)

7A.2 Are bunker transfer systems hydrostatically tested to their Maximum Allowable Working Pressure (MAWP) on an annual basis and to 1.5 times their MAWP at least twice within any five years period?

Findings: The bunker lines had maximum allowable working pressure of 5 kg/cm², the last on board hydrostatic pressure test of the bunker lines was conducted on 03/NOV/2025, the bunker lines were tested to a pressure of 8 kg/cm², which was more than 150% MAWP.

Section 10: Mooring Operations

10.5 Is there a procedure for testing the winch brake rendering setting and is it being tested regularly? (V & M)

Findings: The brake rendering test was conducted on 11/NOV/2025, however, painting ring was used as marking device on the winches, Aft starboard side winch rendering marking was found missing.

10.6 Are mooring lines correctly deployed and tended? (V)

Findings: Mooring lines were found with findings as below: 1. One headline was in slack condition, sagged about 1.5 meter and not evenly tensioned. 2. Fore and aft starboard side loose lines were found in poor condition. 3. One stern line was found frayed at two locations about 0.5 meter each on poop deck port side winch.

10.13 Are the mooring stations maintained in a safe working condition, and is the entire mooring deck area clearly marked with visible signage and appropriately identified as a hazardous zone? (V)

Findings: Both fore and aft mooring deck key areas were not provided with non-slip arrangements.

Section 13: Machinery Space

13.25 Where moving machinery presents a hazard, is it guarded effectively? (V)

Findings: The emergency fire pump was found with the rotator not being fitted with protective guard.

13.27 Is the engine room crane, other lifting equipment, and hydraulic tools inspected, tested, and maintained on a regular basis? (V & M)

Findings: The engine room transverse crane beam was not clearly marked with SWL in several locations.

13.39 Is the main and emergency switchboard earth fault monitoring equipment operational with no earthing faults indicated? (V)

Findings: The insulation alarm setting valve No.2 AC 440V feeder panel was found set on 0.1 megohm at the time of inspection.

Attachments:



[Q1339_c6d70a61-44c1-42a8-a292-55883c27a788.jpg](#)

Section 14: General Appearance - Hull and Superstructure

14.2 Are the following permanent markings on the ship's hull, where applicable, plainly visible and painted in a contrasting colour? (V) The vessel's name Port of registry Load lines Draft marks Thruster warnings Tug push points IMO number Bulbous bow mark

Findings: The starboard side middle drafts mark between the 7.2 meter and 10 meter was found faded.

14.10 Are portable and fixed cargo lights used for illumination of cargo holds inspected regularly and maintained in good condition? (V)

Findings: Lamp holders, drip shields and shades of onboard portable cargo lights(220 voltages) were not constructed of non-conductive material. No objective evidence was available to verify regular insulation inspection and testing of these lights.

Vessel's Master Name

Gurkan Alkan

Vessel's Master Email Address

devbulkdaml@devbulk.com

- ☒ By signing the list of Findings, I confirm a closing meeting has taken place and the inspector has informed me that, where not already transmitted, the list of Findings will be sent via internet email once connectivity is restored.

Vessel's Master Signature:



A handwritten signature in black ink, appearing to be 'Gurkan Alkan', written over a horizontal line.

Inspector Name

Liu Shibao

Inspector's Signature:



A handwritten signature in black ink, appearing to be 'Liu Shibao', written over a horizontal line.

CONTACT US

If you're interested and would like to know more, get in touch with our team today.

 www.rightship.com

 dryinspections@rightship.com

 RightShip

MELBOURNE

 Level 8/ 550 Bourke Street,
Melbourne VIC 3000,
Australia

 +61 3 8686 5750

LONDON

 4th Floor, 6 Dowgate Hill,
London EC4R 2SU, United
Kingdom

 +44 203 872 5900

SINGAPORE

 20 Cecil Street, PLUS,
#13-06
Singapore 049705

 +65 3138 3855

HOUSTON

 Suite 140 14141
Southwest Freeway,
Sugar Land TX 77478,
United States of America

 +1 832 770 8200

MALTA

 The Tower, 3rd Floor,
Fortunato Mizzi Street,
Ir-Rabat Għawdex
VCT 2517, Malta