

RightShip Ship Inspection Program

List of Findings

RightShip Ship Inspection Report - 71112

Vessel Type:	A bulk carrier that is carrying grain cargo
Vessel Name:	VERA LONDON
IMO Number:	9644055
DOC Company:	Q-Shipping BV
Place of Inspection:	Caldera (Costa Rica)
Name of Inspector:	FERNANDO TEODOCIO ANDRADE GARCIA
Inspection Completion Date	26/Mar/2026
Operational Variant:	

This is a list of Findings made during my inspection of your vessel, completed today. As the scope and scale of the inspection has been limited by time and operational constraints, this does not necessarily constitute a comprehensive list of all Findings on board.

A copy of this list together with a detailed inspection report will be submitted to RightShip, who will liaise directly with your owners / managers in due course. The following Findings should not be considered as a final or comprehensive list and RightShip reserves the right to add to or amend these Findings. If RightShip adds to or amends the list of Findings, they will advise the owner/ship's manager.

When RightShip reviews the inspection report, the vessel's manager and Master will be given the opportunity to provide comments and response to each Finding on the list.

This list of Findings does not constitute any warranty of the fitness or suitability of the vessel. Thank you for the cooperation and hospitality accorded to me by yourself and your crew.

Number of Findings: 15

Inspected Item	Response	Finding description
3.5 Are there records indicating that routine tests and checks of bridge equipment are being undertaken regularly? (V)	No	Review of available records did not indicate that bridge window wipers had been subject to routine inspection or testing. No supporting documentation was available on board at the time of inspection.
3.6 Has the Master/Pilot information exchange been taking place effectively and is the standard pilot card being completed as required? (V)	No	Tug boat bollard pull information was not available on the pilot card at the time of inspection.
3.28 Are there procedures in place to limit the use of cell phones, personal electronic devices, the internet, and email on the bridge? (V)	No	No posted procedures were observed on the bridge to limit the use of personal electronic devices, internet, or email. A notice addressing the use of mobile phones was available. The Master advised that additional guidance was posted during the inspection.
4.42 Are the lifebuoys, related equipment, and pyrotechnics in good working order? (V)	No	Port and starboard MOB lifebuoys located on the bridge wings were observed with grip lines showing signs of deterioration due to weathering at the time of inspection.
4.18 Are the lifeboats, rescue boat and davit-launched life raft their equipment and launching arrangements serviced periodically in good condition, and are the crew familiar with the launching procedure and operation? (M&V)	No	The port lifeboat bilge pump was observed with the inlet hose not properly secured at the time of inspection.

Inspected Item	Response	Finding description
4.30 Are firemen's outfits including their equipment, two-way portable radiotelephone apparatus for fire-fighter's communication and breathing apparatus in good condition, fit for purpose and available for instant use? (M&V)	No	The lifelines of the firemen's outfits were observed in good condition; however, the associated signal code was not available at the time of inspection.
5.19 Has a Garbage Management Plan been provided and is the Garbage Record Book (GRB) being correctly maintained? (V)	No	Garbage containers located in the engine room were not marked with their capacity at the time of inspection. Marking of capacity was referenced in the ship's Garbage Management Plan (SMS Appendix 2).
8B.13 Have hatch covers been ultrasonically tested for weather tightness before loading? (M&V)	No	Review of available documentation did not identify any records relating to ultrasonic testing. No supporting evidence was available on board at the time of inspection.
9A.6 Are quick-acting cleats and crutches all in place and in good working condition with the rubber washers flexible and free from paint and cracks? (V)	No	Quick-acting cleats for cargo hold No. 4 on the port side were observed with rubber packing showing signs of deterioration at the time of inspection.
9A.20 Is the cargo crane's machinery and operator's cab, including the operator's cab controls, in good working order and inspected, tested, and maintained in accordance with manufacturer's recommendations? (V)	No	The crane access door was observed with corrosion present at the upper section on the right-hand side at the time of inspection.
10.8 Are all mooring lines on winches correctly reeled on drums, and if made fast ashore, are winch brakes secured and winches out of gear? (V)	No	Pins associated with the aft winch control lever engagement mechanism were observed not secured during inspection.
10.18 Are the windlasses, anchors, locking bars, and cables, as well as the working access arrangement, in good working order and are they maintained as part of the plan maintenance system? (V)	No	The Chief Officer advised that the windlass gear engagement was greased every two weeks. At the time of inspection, the windlass gear engagement was observed in a dry condition.
13.34 Is the pipe work in the machinery space, including but not limited to steam, fuel, lubricating oil, sewage, drain and air lines well maintained, in good condition and free of temporary repair and leakage? (V)	No	A draining pipe located on the second platform in way of the auxiliary generator was observed with multiple areas of pitting and evidence of leakage at the time of inspection.
13.42 Is a heading indicator and communication system provided in the steering gear room and are they in good order? (V)	No	A difference of approximately 1.9 degrees was observed between the steering gear gyro repeater and the bridge gyro repeater at the time of inspection.
14.19 Are the ship's guard rails, walkways, and access ladders, as well as the steps and railings, maintained and in good working order, and are the securing arrangements for deck cargoes on the deck also maintained and in satisfactory condition? (V)	No	The stairway located adjacent to the emergency generator was observed without a handrail on one side (vessel design).

Vessel's Master Name

IGOR POSAD

Vessel's Master Email Address

veralondon@gtmailplus.com



By signing the list of Findings, I confirm a closing meeting has taken place and the inspector has informed me that, where not already transmitted, the list of Findings will be sent via internet email once connectivity is restored.

Vessel's Master Signature:



Inspector Name

FERNANDO TEODOCIO ANDRADE GARCIA

Inspector's Signature:

A handwritten signature in black ink, appearing to read 'Fernando', is written over a horizontal line. The signature is stylized with large, overlapping loops and a vertical stroke that extends below the line.