

RightShip Ship Inspection Program

List of Findings

RightShip Ship Inspection Report - 70802

Vessel Type:	A general cargo ship that is carrying general cargo and/or container cargo
Vessel Name:	DEVBULK SINEM
IMO Number:	9416458
DOC Company:	Devbulk Gemi Isletmeciligi AS
Place of Inspection:	Rio Haina
Name of Inspector:	Arnold Garcia
Inspection Completion Date	31/Mar/2026
Operational Variant:	A bulk carrier that is carrying grain cargo-The cargo spaces had been fumigated at least once in the last 12 months

This is a list of Findings made during my inspection of your vessel, completed today. As the scope and scale of the inspection has been limited by time and operational constraints, this does not necessarily constitute a comprehensive list of all Findings on board.

A copy of this list together with a detailed inspection report will be submitted to RightShip, who will liaise directly with your owners / managers in due course. The following Findings should not be considered as a final or comprehensive list and RightShip reserves the right to add to or amend these Findings. If RightShip adds to or amends the list of Findings, they will advise the owner/ship's manager.

When RightShip reviews the inspection report, the vessel's manager and Master will be given the opportunity to provide comments and response to each Finding on the list.

This list of Findings does not constitute any warranty of the fitness or suitability of the vessel. Thank you for the cooperation and hospitality accorded to me by yourself and your crew.

Number of Findings: 10

Inspected Item	Response	Finding description
3.2 Are the requirements of the Master's standing orders explained to the deck officers, and are bridge order books (Night Order) being completed by the Master and countersigned by the officers? (M&V)	No	A review of the bridge documentation, it was noted that specific instructions regarding the required ECDIS display layers and system settings for various navigational conditions were not incorporated into the Master's Standing Orders.
3.20 Are <u>T&P NMs</u> and navigation warnings being used correctly in voyage planning and monitoring? (V)	No	During the assessment of the navigational equipment on the Navigation Bridge, it was observed that NAVTEX and Inmarsat-C navigational warnings are manually plotted on the ECDIS. However, there was no objective evidence sighted, nor a defined procedure, demonstrating how expired or obsolete manual entries are tracked, managed, and subsequently deleted from the system.
4.7 Are procedures in place for the control of hot work, are they incorporated in the safety management system and is there documented evidence of compliance? (M)	No	A review of the Permit to Work records, it was observed that the Hot Work Permit (dated 25/Feb/2025) issued for welding operations at the forward windlass was deficient in the following areas: The mandatory pre-work safety checklist associated with the permit was not fully completed. There was no objective evidence sighted to confirm that prior authorization had been obtained from the Company's shore management for conducting hot work outside a designated workspace.

Inspected Item	Response	Finding description
4.17 Is the welding and gas-burning equipment, as well as the electric arc welding equipment, properly stored and maintained in good working order? (M&V)	No	During the inspection of the hot work equipment located in the Engine Room workshop, the following critical safety deficiencies were observed: The oxygen and acetylene hoses were secured to their respective hose tails using unapproved, re-usable worm-drive clamps. The primary cable for the electrical welding machine was found to be improperly repaired, with a section spliced and wrapped in black electrical tape.
4.35 Is a safe means of access to the vessel being provided? (V)	No	At the time of boarding, it was observed that a lifebuoy equipped with a self-igniting light and a buoyant lifeline was not provided for immediate deployment in the vicinity of the accommodation ladder
5.25 Are the ballast pumping systems, including their associated instruments, controls, valves, pipework, and the control panel (including pressure gauges, draft gauges, and the remote control system), in good working order and is there recorded evidence of regular inspection? (V)	No	During the review of the vessel's maintenance records, there was no objective evidence sighted to confirm that the operating times of the power-operated ballast valves are being regularly checked. Furthermore, there are no records demonstrating that the actual opening and closing times are periodically verified against the manufacturer's original design.
7A.7 Are bunkering and oil fuel transfer procedures carefully planned and executed in accordance with industry standards, are the details of the last operation in accordance with industry standards, is the vessel equipped with a procedure for sampling the oil fuel used on board, and are bunker samples stored in a sheltered location? (V)	No	During the review of the bunkering records, it was noted that the vessel's specific Bunkering Operations Plan does not include calculations for the vessel's stability, drafts, trim, and list during the various stages of the transfer operation.
9A.6 Are quick-acting cleats and crutches all in place and in good working condition with the rubber washers flexible and free from paint and cracks? (V)	No	Physical inspection of the hatch cover securing arrangements revealed that the vertical supporting bracket of the quick-acting cleat assembly for Cargo Hold #1 located on the Port side was severely deformed and bent outwards.
10.5 Is there a procedure for testing the winch brake rendering setting and is it being tested regularly? (M&V)	No	Visual inspection of the forward and aft mooring winches revealed that the permanent physical indicators, required to accurately align and verify the correct brake tightening point established during the brake rendering tests, were not fitted on the brake mechanisms.
12.1 Is access to the ship being controlled by an adequate deck watch? (V)	No	At the time of boarding the vessel the deck watch rating did not give any safety briefing to the inspector and did not point out any instructions related to what to do in the event of an emergency.

Vessel's Master Name

Yavuz KASIM

Vessel's Master Email Address

devbulksinem@devbulk.com

☒ By signing the list of Findings, I confirm a closing meeting has taken place and the inspector has informed me that, where not already transmitted, the list of Findings will be sent via internet email once connectivity is restored.

Vessel's Master Signature:



Inspector Name

Arnold Garcia

Inspector's Signature:

