

RightShip Ship Inspection Program

List of Findings

RightShip Ship Inspection Report - 72593

Vessel Type:	A general cargo ship that is carrying general cargo and/or container cargo
Vessel Name:	DEVBULK ALARA
IMO Number:	9449895
DOC Company:	Devbulk Gemi Isletmeciligi AS
Place of Inspection:	Batumi
Name of Inspector:	Boris Kokorev
Inspection Completion Date	26/May/2026
Operational Variant:	

This is a list of Findings made during my inspection of your vessel, completed today. As the scope and scale of the inspection has been limited by time and operational constraints, this does not necessarily constitute a comprehensive list of all Findings on board.

A copy of this list together with a detailed inspection report will be submitted to RightShip, who will liaise directly with your owners / managers in due course. The following Findings should not be considered as a final or comprehensive list and RightShip reserves the right to add to or amend these Findings. If RightShip adds to or amends the list of Findings, they will advise the owner/ship's manager.

When RightShip reviews the inspection report, the vessel's manager and Master will be given the opportunity to provide comments and response to each Finding on the list.

This list of Findings does not constitute any warranty of the fitness or suitability of the vessel. Thank you for the cooperation and hospitality accorded to me by yourself and your crew.

Number of Findings: 10

Inspected Item	Response	Finding description
4.18 Are the lifeboats, rescue boat and davit-launched life raft their equipment and launching arrangements serviced periodically in good condition, and are the crew familiar with the launching procedure and operation? (M&V)	No	Free fall life boat three seats were found with not securely fastened bolts (one bolt for each seats.)
5.25 Are the ballast pumping systems, including their associated instruments, controls, valves, pipework, and the control panel (including pressure gauges, draft gauges, and the remote control system), in good working order and is there recorded evidence of regular inspection? (V)	No	Ballast Water Treatment Lamp drive cabinet cooling system sea water inlet and outlet pipes in the areas of connection to cooler were found temporary repaired.
6.7 Is the vessel free of any apparent structural defects? (V)	No	There was indent observed on port side shell plating on the area 176 to 183 frames in the ballast tank 1SWBP with depth about 50mm and on the height 9.5 to 10m from bottom. There were no condition of class recorded in the latest available Class Status.
9A.9 Are the side and cross-joint rubber seals in good condition? (V)	No	Cargo hold No,5 rubber packing on panels 5-3, and 5-2 were noted with replacement about 150 mm in length (less than at least 1 m.) in areas of forward and aft corners on port side.
13.19 Are engine exhausts and other hot surfaces effectively shielded against oil spray and are flanges and connections of flammable liquid pipelines adequately protected with guards and spray tape? (V)	No	Auxiliary Engines 1 and 3 exhaust gas pipe hot surfaces were not fully protected with insulation in the area of turbocharger. The hot surface when measured on the Auxiliary Engine No.1 was about 343C.
13.31 Is the bilge high level alarm system in good order, regularly tested and are records of test maintained? (V)	No	High-level alarm for engine room bilges was not tested prior to leaving the engine room in Unmanned Machinery Space mode

Inspected Item	Response	Finding description
14.2 Are the following permanent markings on the ship's hull, where applicable, plainly visible and painted in a contrasting colour? • The vessel's name • Port of registry • Load lines • Draft marks • Thruster warnings • Tug push points • <u>IMO</u> number • Bulbous bow mark (V)	No	• Forward port side draft marking was not painted in a contrasting color and plainly visible in area from 8 to 9 m draft.
14.10 Are portable and fixed cargo lights used for illumination of cargo holds inspected regularly and maintained in good condition? (V)	No	• Portable cargo holds lights recently supplied were suitable for power voltage 220 V greater than 50V AC (1-1000Hz) or 120V DC
14.13 Are the stores located inside the accommodation and on the weather decks clean and tidy? (V)	No	• Steel materials and spare reinforcements were not secured in the forecastle space.
14.19 Are the ship's guard rails, walkways, and access ladders, as well as the steps and railings, maintained and in good working order, and are the securing arrangements for deck cargoes on the deck also maintained and in satisfactory condition? (V)	No	• Accommodation ladder from the Bridge deck to C Deck was found with one step significantly corroded and partly wasted,.

Vessel's Master Name

Fatih GECGEL

Vessel's Master Email Address

devbulkalara@devbulk.com



By signing the list of Findings, I confirm a closing meeting has taken place and the inspector has informed me that, where not already transmitted, the list of Findings will be sent via internet email once connectivity is restored.

Vessel's Master Signature:



Inspector Name

Boris Kokorev

Inspector's Signature:

A handwritten signature in black ink, appearing to read 'Boris Kokorev', is written over a horizontal line. The signature is stylized, with the first letter 'B' being large and the last letter 'v' having a long, sweeping tail that extends to the right.