

RightShip Ship Inspection Program

List of Findings

RightShip Ship Inspection Report - 71290

Vessel Type:	A bulk carrier that is carrying solid bulk cargo
Vessel Name:	KIRAN AUSTRALIA
IMO Number:	9576961
DOC Company:	Pasifik Gemi Isletmeciligi ve Ticaret AS
Place of Inspection:	Iskenderun
Name of Inspector:	Sadi Toklu
Inspection Completion Date	07/May/2026
Operational Variant:	

This is a list of Findings made during my inspection of your vessel, completed today. As the scope and scale of the inspection has been limited by time and operational constraints, this does not necessarily constitute a comprehensive list of all Findings on board.

A copy of this list together with a detailed inspection report will be submitted to RightShip, who will liaise directly with your owners / managers in due course. The following Findings should not be considered as a final or comprehensive list and RightShip reserves the right to add to or amend these Findings. If RightShip adds to or amends the list of Findings, they will advise the owner/ship's manager.

When RightShip reviews the inspection report, the vessel's manager and Master will be given the opportunity to provide comments and response to each Finding on the list.

This list of Findings does not constitute any warranty of the fitness or suitability of the vessel. Thank you for the cooperation and hospitality accorded to me by yourself and your crew.

Number of Findings: 30

Inspected Item	Response	Finding description
2.5 Do all personnel maintain rest period/work hours and are the rest hours in compliance with <u>STCW</u> or <u>MLC</u> requirements? (V)	No	-It was observed that the vessel carried out bunkering operation between 0500 and 0600 on 21/Apr/2026, but all engine crew, except duty engineer, were at the rest according to record of rest hours.26/Apr/2025. - Review of hot work permits, it was recorded that repair on aft mooring deck was conducted between 0820 and 1500 on 09/Apr/2026, but the officer who responsible for supervising the work was at the rest according to record of rest hours.
3.4 Have operational checks on navigational equipment been done and are checklists being effectively completed when preparing for sea and prior to port entry? (V)	No	-According to vessel last pre departure check list SMP 7.1, the vessel bow thruster, stabilizer and pitch controller were tested, although vessel does not have such a equipment. - It was observed that steering gear checklist (C2.1) before the departure was not included in operator SMS, and there was no any record/evidence was sighted steering gear was checked according to checklist C2.1 before departure.
3.13 Where fitted are the standard magnetic compass, gyro compass and Global Navigation Satellite System compass, operational, adjusted and properly maintained? (M&V)	No	• The magnetic compass had a bubble inside, approximately 7 cm diameter. Rectified during the inspection.
3.16 Is a chart and publication management system being implemented to ensure that all charts, nautical publications, and other publications on board are current, maintained and up to date? (M&V)	No	• NP133C Admiralty ENC Maintenance Record book was not updated at the time of inspection, last update was sighted on 02/Oct/2025.
4.7 Are procedures in place for the control of hot work, are they incorporated in the safety management system and is there documented evidence of compliance? (M)	No	• It was noted that, there were no requirements for company pre-approval for hot work outside designated area.

Inspected Item	Response	Finding description
4.11 Has a <u>PPE</u> Matrix for use of personal protective equipment been provided and is it being worn as required? (V)	No	The minimum PPE requirement when entry to enclosed space was not incorporated into the PPE matrix.
4.16 Are portable gas detectors suitable for atmosphere testing of enclosed spaces provided; in good condition; calibrated in accordance with the manufacturer's instructions, and are officers trained and competent with their operation? (V)	No	According to the master verbal information, two gas detectors were sent to shore for annual calibration, but no landing report was available on board at the time of inspection.
4.39 If the vessel is provided with a helicopter operating area, does the area comply with the requirements of <u>ICS</u> guidelines, and is there a safe access from the hatch cover to deck? (V)	No	The access from hatch cover to deck was a provided with aluminum ladder, width 40 cm, without fixing to main deck and to hatch coaming.
4.42 Are the lifebuoys, related equipment, and pyrotechnics in good working order? (V)	No	It was observed that two lifebuoy light, located at the main deck starboard side was not functional at the time of inspection.
5.15 Are the engineering officers familiar with the company procedures for operating the oil filtering equipment, and was the equipment in satisfactory condition and used in compliance with company procedures, the manufacturer's instructions, and <u>MARPOL</u> Annex I? (M&V)	No	It was noted that the Oily Water Separator (OWS) discharge line, from the OWS to the overboard valve, was fitted with several flange connections. However, no effective sealing arrangement was in place to prevent unauthorized access, and none of the flange connections were sealed.
5.26 Are bunker and ballast tank manholes maintained in good condition? (V)	No	It was observed that several fastening bolts were not in place on some of the access manhole cover of the cargo hold cat walk on main deck.
6.2 Does the <u>SMS</u> include procedures and instructions for regular inspection of cargo holds, ballast tanks, void spaces, trunks, duct keel and cofferdams by the ship's personnel and are records maintained? (V)	No	Ballast tanks were to be inspected every 18 months, not annually, according to operator SMS. The last inspection of all ballast tanks were recorded on 11/Apr/2025.
6.5 Are the air pipes and sounding pipes in the cargo holds and void spaces in good condition? (V)	No	The screw down cap and the pipe-end of the %80 WBT sounding pipes, located on main deck port / starboard side, were found corroded and thread damaged that the pipe could not be fully capped, was capped with teflon.
9A.3 Are adequate procedures in place for carrying out hose and / or ultrasonic testing of hatch covers and is documented evidence of such testing available? (V)	No	Hatch cover tightness hose test was required to be carried out before each loading according to the operator SMS. It was noted that last hose test was carried out 19/Nov/2025, and was not carried out for last three cargo loading. The last ultrasonic test was done during the drydock in March 2024.
10.4 Do mooring lines and mooring tails comply with industry guidelines and are they in good order? (M&V)	No	The vessel EN number was indicated 3292 in Line Management Plan, and SDMBL was calculated 735 kN. But, 6 mooring ropes LDBF fitted on board was 59,5 T and 6 mooring ropes LDBF was 67,5 T.
10.16 Are the pedestal fairleads, roller fairleads and other rollers free of grooving, well-greased and free to turn? (V)	No	Grooving and corrosion was observed on mooring chocks and rollers at the forward mooring deck.
13.11 Is an effective and up to date planned maintenance system available and being followed on board the vessel? (V)	No	As review of randomly selected work done report on the vessel PMS, It was noted that main engine pick up and tachometer sensors cleaning, main engine fuel injector overhaul and main engine scavenge check were done while the engine running.
13.13 Is the main engine maintained as per manufacturer's recommendations and records of periodic maintenance kept? (V)	No	-The vessel was fitted with ME-C (Electronically controlled) engine. Oil leakage was observed on the main engine Hydraulic Power Supply (HPS) unit located aft side of the main engine, about 5 liter leak oil was observed in the drip tray of HPS. -It was observed that oily rags were placed at the main engine recess area. One 20 liter can and one 5 liter can were full with the leaked oil was observed at the front of main engine recess area.
13.14 Are the auxiliary engines maintained as per manufacturer's recommendations and records of periodic maintenance kept? (V)	No	Large amount of diesel oil leakage was observed on high pressure fuel pumps location of NO-2 and 3 Diesel generator.
13.26 Is the workshop clean and tidy, and are the engine room workshop tools' protective guards, shields, and emergency stops in good condition? (V)	No	Emergency stop were not fitted for the drill and grinder in engine room workshop.

Inspected Item	Response	Finding description
13.31 Is the bilge high level alarm system in good order, regularly tested and are records of test maintained? (V)	No	The engine room was operated at UMS mode. It was noted that engine room bilge high level alarm was tested weekly, and engine room bilge high level alarm was required to be tested weekly according to operator SMS, not on a daily basis.
13.33 Is the following machinery/equipment, where applicable, in good order and well maintained? - Shaft generator and emergency generator - Boilers, including waste heat and domestic boilers (Boilers should be operated in automatic mode where the automated boilers are installed) - Boiler safety system and instrumentation - Boiler water safety system - Main and emergency air compressors - Purifiers and fuel oil handling equipment - Stern tube sealing arrangements - Incinerator - Sewage system - Air condition and heating system - Refrigeration plant - Accommodation service systems (i.e., Calorifiers, Portable water equipment, heating etc) - Any other items of machinery, including stand-by machinery. - Burners, tubes, uptakes, exhaust manifolds and spark arrestors. - Engine control console including the control and monitoring system - Steering gear system - Battery maintenance and renewal. (V)	No	The boiler was fitted with two side supports, one at the front side and one at the starboard side in order to compensate the boiler thermal expansion. It was observed that boiler starboard side support, located funnel inside, was broken, and one additional lifting with wire fitted at the port side of boiler.
14.1 Is the ship's hull clean, free of significant corrosion, extensive coating breakdown and marine growth? (V)	No	Local breakdown was observed on the port side antifouling paint after 13 meters draft of the hull up to 5% of the surface area, especially around welding seams. The hull plating was free of structural damages. Marine growth was not observed.
14.2 Are the following permanent markings on the ship's hull, where applicable, plainly visible and painted in a contrasting colour? - The vessel's name - Port of registry - Load lines - Draft marks - Thruster warnings - Tug push points - IMO number - Bulbous bow mark (V)	No	The port side midship draft marks were not clearly visible.
14.4 Are the pipes on deck free of significant corrosion, pitting, soft patches, leakage or temporary repair and maintained in good condition? (V)	No	It was observed that air pipe and fresh water pipe on main deck, valve remote control hydraulic pipe foundation were heavily corroded and wasted on main deck port side.
14.5 Are all watertight doors (where fitted), fire doors, weathertight doors, portholes and wheelhouse windows maintained in good order? (V)	No	Spring balance quick acting watertight hatch was fitted on weather deck for entrance of cargo hold 1 forward/aft and cargo hold 2 forward. It was observed that these hatches spring were lost tension and not operational.
14.6 Are the vents and air pipes on weather decks maintained in good order and are they clearly marked to indicate the compartment they serve? (V)	No	It was observed that several ballast tank vent head bolts were missing, and vent head inside full of dropped rust residues and paint flakes.
14.12 Are the chemicals and gases stored correctly, and are the paint locker, battery room, oxygen and acetylene rooms, and other flammable lockers and storage spaces equipped with ventilation systems, explosion-proof lights, and other fittings in good working order? (V)	No	It was observed that the floor of the chemical store, located between CH 3 and 2, was covered with chemical that had leaked and mixed with water, about 5 liters.

Inspected Item	Response	Finding description
14.13 Are the stores located inside the accommodation and on the weather decks clean and tidy? (V)	No	Unsecured steel pipes and angle bars were placed in the forecastle store. There was no any procedure in operator SMS for the storing, securing and manual handling of spare parts and steel plates.
15.14 Does the Air Handling Unit (AHU) maintain a comfortable temperature and is there recorded evidence of regular maintenance and cleaning of AHU available? (V)	No	-It was noted that package type unit air condition for galley was removed and not in place at the time of inspection. -It was observed that AHU fan foundation was heavily corroded and wasted. AHU fan was required to be provided with three V-Belt, but one of the V-belt was missing and fan was run with two belt at the time of inspection.

Vessel's Master Name

NEDİM BEŞİKÇİ

Vessel's Master Email Address

kiranaustralia@pasifikgemi.com



By signing the list of Findings, I confirm a closing meeting has taken place and the inspector has informed me that, where not already transmitted, the list of Findings will be sent via internet email once connectivity is restored.

Vessel's Master Signature:



Inspector Name

Sadi Toklu

Inspector's Signature:

