

RightShip Ship Inspection Program

List of Findings

RightShip Ship Inspection Report - 73677

A general cargo ship that is carrying general cargo and/or container cargo

Vessel Name:	MANTA FATMA
IMO Number:	9604809
DOC Company:	Manta Denizcilik Nakliyat ve Ticaret Ltd Sti
Place of Inspection:	United States, Houston
Name of Inspector:	Ahmed Reza
Inspection Completion Date:	8/12/2026 12:00:00 AM
Operational Variant:	

This is a list of Findings made during my inspection of your vessel, completed today. As the scope and scale of the inspection has been limited by time and operational constraints, this does not necessarily constitute a comprehensive list of all Findings on board.

A copy of this list together with a detailed inspection report will be submitted to RightShip, who will liaise directly with your owners / managers in due course. The following Findings should not be considered as a final or comprehensive list and RightShip reserves the right to add to or amend these Findings. If RightShip adds to or amends the list of Findings, they will advise the owner/ship's manager.

When RightShip reviews the inspection report, the vessel's manager and Master will be given the opportunity to provide comments and response to each Finding on the list.

This list of Findings does not constitute any warranty of the fitness or suitability of the vessel. Thank you for the cooperation and hospitality accorded to me by yourself and your crew.

DISCLAIMER

THIS DOCUMENT AND THE CONTENTS HEREOF ARE PREPARED SOLELY FOR RIGHTSHIP'S CUSTOMER IN RESPECT OF THE VESSEL(S) NAMED FOR RIGHTSHIP INSPECTION AND ARE NOT INTENDED FOR ANY THIRD PARTY TO ACCESS, USE, RELY ON OR DISTRIBUTE WITHOUT RIGHTSHIP'S EXPLICIT WRITTEN CONSENT. NOTWITHSTANDING ANY CONSENT THAT MAY HAVE BEEN GIVEN BY RIGHTSHIP AS AFOREMENTIONED, RIGHTSHIP SHALL HAVE NO LIABILITY WHATSOEVER AND HOWSOEVER ARISING TO ANY SUCH PERSON OR ENTITY, OR THIRD PARTY RECIPIENT, WHETHER IN CONTRACT, TORT OR OTHERWISE.

IF, IN RELIANCE OF THIS DOCUMENT, YOU ELECT TO CHARTER ANY VESSEL OR MAKE ANY COMMERCIAL OR OTHER DELIBERATIONS IN CONNECTION WITH IT, YOU DO SO AT YOUR OWN RISK AND YOU MUST MAKE YOUR OWN ASSESSMENT AND SATISFY YOURSELF AS TO THE ACCURACY AND COMPLETENESS OF THE INFORMATION CONTAINED IN THIS DOCUMENT. RIGHTSHIP PROVIDE NO WARRANTY AS TO THE SAFETY OR QUALITY OF THAT VESSEL, ITS FITNESS FOR ANY PURPOSE, OR ANY OTHER FINDINGS ABOUT IT AND RIGHTSHIP DO NOT ACCEPT RESPONSIBILITY OR LIABILITY FOR ANY INCOMPLETENESS OR INACCURACIES IN THE INFORMATION CONTAINED IN THIS DOCUMENT THAT MAY INCLUDE UNVERIFIABLE INFORMATION OF CUSTOMER AND/OR THIRD PARTIES.

THIS DOCUMENT CONTAINS CONFIDENTIAL AND/OR LEGALLY PRIVILEGED INFORMATION AND IS SUBJECT TO THE INTELLECTUAL PROPERTY RIGHTS AND OTHER PROPRIETARY RIGHTS OF RIGHTSHIP AND/OR ITS LICENSORS. UNAUTHORISED ACCESS, USE OR DISTRIBUTION OF THIS DOCUMENT OR ANY CONTENTS HEREOF CONSTITUTES BREACH OF OBLIGATION OF CONFIDENCE TO AND/OR INFRINGEMENT OF INTELLECTUAL PROPERTY AND OTHER PROPRIETARY RIGHTS OF RIGHTSHIP AND/OR ITS LICENSORS, WHICH MAY RESULT IN LEGAL ACTION TAKEN AGAINST YOU. FOR MORE INFORMATION ABOUT THE RIGHTS AND OBLIGATIONS OF RIGHTSHIP'S INSPECTION CUSTOMERS, PLEASE REFER TO TERMS AND CONDITIONS GOVERNING RIGHTSTORE, COPY OF WHICH MAY BE ACCESSED ON RIGHTSTORE OR SUCH OTHER PORTAL ON WHICH RIGHTSHIP MAY CHOOSE TO PUBLISH.

Number of Findings: 20

Section 2: Certification and Personal Management

2.1 Is the latest Class Survey Status available, are all Statutory Certificates listed within it valid, is the vessel free of any overdue Conditions of Class, and are all classification and statutory surveys up to date?

Findings: Vessel's Class Survey Status (NKK), dated 12/Aug/2026, reviewed and observed below condition of class, due date - 16/Jan/2027: Indented shell plate, 1st and 2nd below sheer, i.w.o. No.3 S.W.B.T.(P) at Fr.Nos.123-127(P) between SL-10 to SL-12, max 50mm, to be further examined and dealt with as necessary by the next Docking Survey, subject to re-examination at Periodical Surveys.

Section 4: ISM System

4.5 Is the vessel provided with an enclosed space entry procedure, and is there documented evidence that it was followed, and is there evidence that the crew assigned to responsibilities requiring entry into enclosed spaces has attended a dedicated enclosed space entry course?

Findings: While checking the vessel's enclosed space entry permits form P 001, it was observed that on 15/Jul/2026, fore peak tank enclosed space entry permit was issued at 1500 hours, whereas the initial atmosphere check was carried out at 1513 hours, person entered signed at 1510 hours and Master approved the permit at 1503 hours.

4.11 Has a PPE Matrix for use of personal protective equipment been provided and is it being worn as required?

Findings: It was observed during the inspection that one of the accompanying engineers did not use any ear protection during starting the emergency generator and inspecting the engine room.

4.16 Are portable gas detectors suitable for atmosphere testing of enclosed spaces provided; in good condition; calibrated in accordance with the manufacturer's instructions, and are officers trained and competent with their operation?

Findings: The vessel was provided with two (2) portable/personal Honeywell BW Flex4 multi-gas (5 gases) detectors, however, when two persons entered inside the enclosed space, there is no gas meter outside the space for repetitive checks.

4.37 Are pilot ladders used for pilot transfer in good condition, and inspected regularly, clearly identified with tags or with permanent marking and are maintenance records available and, are crew members capable of demonstrating proper rigging of the pilot-ladder arrangement?

Findings: The pilot ladder was rigged on the vessel's stbd side during the inspection, however, synthetic ropes were used to secure the ladder. Rectified during the inspection.

4.39 If the vessel is provided with a helicopter operating area, does the area comply with the requirements of ICS guidelines, and is there a safe access from the hatch cover to deck?

Findings: Vessel's cargo hold # 3 hatch covers were designated for helicopter landing area, however, a strength confirmation letter from a classification society was not available on board for the same.

Section 5: Pollution Prevention and Control

5.9 Are the emergency arrangements to pump out the spaces forward of the collision bulkhead in the event of flooding in good order, and are these arrangements prominently marked? (V)

Findings: An emergency pumping arrangement was provided in the bosun store in the event of flooding, however, the valves were not marked and no warning poster was available to prevent accidental opening. Rectified during the inspection.

5.13 Are the emergency bilge suction and emergency overboard discharge valves in the engine room in good order and clearly identified with a notice warning against accidental opening and, is the area around the bilge injection suction bellmouth clear of debris and clean?

Findings: The emergency bilge suction was found closed during the inspection, however, it was not sealed with a breakable seal, electronic tracking, or any similar method. Rectified before completion of inspection.

5.15 Are the engineering officers familiar with the company procedures for operating the oil filtering equipment, and was the equipment in satisfactory condition and used in compliance with company procedures, the manufacturer's instructions, and MARPOL Annex I?

Findings: While testing the oily water separator 15 ppm alarm during the inspection, it was observed that the sea water inlet valve was in-operational due to broken valve wheel. However, later opened the valve with the help of spanner which took much longer time. Replaced the valve before completion of inspection.

Section 7A: Fuel Management (Oil)

7A.3 Are the drains, vents, pressure gauges, and thermometers on the bunker manifolds in good working order, and are blanks fitted when they are not in use? (V)

Findings: The thermometer was not connected to the bunker manifold. Rectified before completion of inspection.

Section 9A: Hatch Cover and Lifting Appliances

9A.8 If the hatch covers are supported by bearing pads, are they free from wear or damage? (V)

Findings: The cargo hold hatch covers were supported by the bearing pads, however, numerous bearing pads were found heavily corroded.

9A.13 Are the following parts of the hatch covers, where applicable, all in good order and do they appear to be well maintained?

- Wheels/bearings or trackway
- Hydraulic system including hoses
- Chains
- Link pin and safety pin
- Cargo holds' ventilator on the side and end of hatch panel

Findings: Minor continuous hydraulic oil leakage was observed from cargo hold # 1 stbd side aft hatch cover hydraulic ram, approximately 20 drops per minute and 100 ml accumulation of oil on the deck.

9A.22 Are the loose gears of lifting appliances clearly marked and are the certificates of the loose gears available and traceable on board?

Findings: The cargo crane hooks were marked with SWL on one side only.

Section 10: Mooring Operations

10.14 Are appropriate stoppers in use and are the mooring ropes turned up to bitts correctly? (V)

Findings: At aft mooring station, it was observed that two mooring ropes were laid up onto the mooring bitts, however, the first two turns were not taken directly around the first post of the bitts before the rope is laid up in a figure eight around the bitts. Rectified before completion of inspection.

10.18 Are the windlasses, anchors, locking bars, and cables, as well as the working access arrangement, in good working order and are they maintained as part of the plan maintenance system? (V)

Findings: Vessel's stbd anchor was housed in the hawse pipe properly, however, it was not secured by the guillotine bar as the bar did not sit in its locking position.

Section 14: General Appearance - Hull and Superstructure

14.1 Is the ship's hull clean, free of significant corrosion, extensive coating breakdown and marine growth? (V)

Findings: Moderate sporadic rust was observed on the forward part of the port side hull during the inspection.

14.4 Are the pipes on deck free of significant corrosion, pitting, soft patches, leakage or temporary repair and maintained in good condition? (V)

Findings: The whole fresh water line on deck ran through the port side of the vessel was found heavily corroded.

14.8 Are the hatch numbers clearly indicated and correctly placed? (V)

Findings: The hatch covers of the cargo holds were not marked with the hatch numbers.

14.10 Are portable and fixed cargo lights used for illumination of cargo holds inspected regularly and maintained in good condition? (V)

Findings: The lamp holder, drip shield, and shade of portable cargo lights were not made of non-conductive material.

14.12 Are the chemicals and gases stored correctly, and are the paint locker, battery room, oxygen and acetylene rooms, and other flammable lockers and storage spaces equipped with ventilation systems, explosion-proof lights, and other fittings in good working order? (V)

Findings: Thinners were stored inside the undesignated (deck house) store between the cargo hold # 1 and 2, where no fixed fire fighting arrangement was available.

Vessel's Master Name

ISMAIL EKEN

Vessel's Master Email Address

mantafatma@skyfile.com

- ☒ By signing the list of Findings, I confirm a closing meeting has taken place and the inspector has informed me that, where not already transmitted, the list of Findings will be sent via internet email once connectivity is restored.

Vessel's Master Signature:


A handwritten signature in black ink, appearing to be 'ISMAIL EKEN', written over a horizontal line.

Inspector Name

Ahmed Reza

Inspector's Signature:


A handwritten signature in black ink, appearing to be 'Ahmed Reza', written over a horizontal line.

CONTACT US

If you're interested and would like to know more, get in touch with our team today.

 www.rightship.com

 dryinspections@rightship.com

 RightShip

MELBOURNE

 Level 8/ 550 Bourke Street,
Melbourne VIC 3000,
Australia

 +61 3 8686 5750

LONDON

 4th Floor, 6 Dowgate Hill,
London EC4R 2SU, United
Kingdom

 +44 203 872 5900

SINGAPORE

 20 Cecil Street, PLUS,
#13-06
Singapore 049705

 +65 3138 3855

HOUSTON

 Suite 140 14141
Southwest Freeway,
Sugar Land TX 77478,
United States of America

 +1 832 770 8200

MALTA

 The Tower, 3rd Floor,
Fortunato Mizzi Street,
Ir-Rabat Għawdex
VCT 2517, Malta