

RightShip Ship Inspection Program

List of Findings

RightShip Ship Inspection Report - 72575

A general cargo ship that is carrying general cargo and/or container cargo

Vessel Name:	MANTA NILGUN
IMO Number:	9553024
DOC Company:	Manta Denizcilik Nakliyat ve Ticaret Ltd Sti
Place of Inspection:	Poland, Swinoujscie
Name of Inspector:	P.-U. Kunrad Brandes
Inspection Completion Date:	7/22/2026 12:00:00 AM
Operational Variant:	

This is a list of Findings made during my inspection of your vessel, completed today. As the scope and scale of the inspection has been limited by time and operational constraints, this does not necessarily constitute a comprehensive list of all Findings on board.

A copy of this list together with a detailed inspection report will be submitted to RightShip, who will liaise directly with your owners / managers in due course. The following Findings should not be considered as a final or comprehensive list and RightShip reserves the right to add to or amend these Findings. If RightShip adds to or amends the list of Findings, they will advise the owner/ship's manager.

When RightShip reviews the inspection report, the vessel's manager and Master will be given the opportunity to provide comments and response to each Finding on the list.

This list of Findings does not constitute any warranty of the fitness or suitability of the vessel. Thank you for the cooperation and hospitality accorded to me by yourself and your crew.

DISCLAIMER

THIS DOCUMENT AND THE CONTENTS HEREOF ARE PREPARED SOLELY FOR RIGHTSHIP'S CUSTOMER IN RESPECT OF THE VESSEL(S) NAMED FOR RIGHTSHIP INSPECTION AND ARE NOT INTENDED FOR ANY THIRD PARTY TO ACCESS, USE, RELY ON OR DISTRIBUTE WITHOUT RIGHTSHIP'S EXPLICIT WRITTEN CONSENT. NOTWITHSTANDING ANY CONSENT THAT MAY HAVE BEEN GIVEN BY RIGHTSHIP AS AFOREMENTIONED, RIGHTSHIP SHALL HAVE NO LIABILITY WHATSOEVER AND HOWSOEVER ARISING TO ANY SUCH PERSON OR ENTITY, OR THIRD PARTY RECIPIENT, WHETHER IN CONTRACT, TORT OR OTHERWISE.

IF, IN RELIANCE OF THIS DOCUMENT, YOU ELECT TO CHARTER ANY VESSEL OR MAKE ANY COMMERCIAL OR OTHER DELIBERATIONS IN CONNECTION WITH IT, YOU DO SO AT YOUR OWN RISK AND YOU MUST MAKE YOUR OWN ASSESSMENT AND SATISFY YOURSELF AS TO THE ACCURACY AND COMPLETENESS OF THE INFORMATION CONTAINED IN THIS DOCUMENT. RIGHTSHIP PROVIDE NO WARRANTY AS TO THE SAFETY OR QUALITY OF THAT VESSEL, ITS FITNESS FOR ANY PURPOSE, OR ANY OTHER FINDINGS ABOUT IT AND RIGHTSHIP DO NOT ACCEPT RESPONSIBILITY OR LIABILITY FOR ANY INCOMPLETENESS OR INACCURACIES IN THE INFORMATION CONTAINED IN THIS DOCUMENT THAT MAY INCLUDE UNVERIFIABLE INFORMATION OF CUSTOMER AND/OR THIRD PARTIES.

THIS DOCUMENT CONTAINS CONFIDENTIAL AND/OR LEGALLY PRIVILEGED INFORMATION AND IS SUBJECT TO THE INTELLECTUAL PROPERTY RIGHTS AND OTHER PROPRIETARY RIGHTS OF RIGHTSHIP AND/OR ITS LICENSORS. UNAUTHORISED ACCESS, USE OR DISTRIBUTION OF THIS DOCUMENT OR ANY CONTENTS HEREOF CONSTITUTES BREACH OF OBLIGATION OF CONFIDENCE TO AND/OR INFRINGEMENT OF INTELLECTUAL PROPERTY AND OTHER PROPRIETARY RIGHTS OF RIGHTSHIP AND/OR ITS LICENSORS, WHICH MAY RESULT IN LEGAL ACTION TAKEN AGAINST YOU. FOR MORE INFORMATION ABOUT THE RIGHTS AND OBLIGATIONS OF RIGHTSHIP'S INSPECTION CUSTOMERS, PLEASE REFER TO TERMS AND CONDITIONS GOVERNING RIGHTSTORE, COPY OF WHICH MAY BE ACCESSED ON RIGHTSTORE OR SUCH OTHER PORTAL ON WHICH RIGHTSHIP MAY CHOOSE TO PUBLISH.

Number of Findings: 9

Section 4: ISM System

4.2 Has a safety officer been appointed and adequately trained, onboard safety meetings held regularly and acknowledged by the vessel's manager, with feedback provided where necessary, and are safety inspections of the main deck, machinery space, accommodation and forecastle store conducted at regular intervals in accordance with the company's procedures, and are health, safety, and environmental hazards effectively identified? (V)

Findings: 1.) Expired pyrotechnics were kept inside safety locker next to 2 BA sets and the firemen suit. Area not with fixed fire detection nor fixed fire extinguishing system. 2.) Ocenco EEBD (Chemical reaction box) in safety locker with wrong instruction poster nearby (MSA compressed bottle type).

4.15 Has a smoking policy been implemented; is it being followed and are designated smoking areas adequately identified?

Findings: Common working areas like bridge, ships office and engine control room were considered smoking areas by the company smoking policy. These areas were being used by smokers and non smokers at the same time.

4.38 Has the vessel been provided with ship-specific fire safety and SOLAS training manuals and operational booklets?

Findings: Fire safety operational booklet did not have any information included on firemen hood (Bakalava) as provided on board. No donning instructions and no maintenance information of it was included.

Section 6: Ship's Structure

6.5 Are the air pipes and sounding pipes in the cargo holds and void spaces in good condition? (V)

Findings: Caps of two(2) sounding pipes on open weather deck were seen missing. One was next to aft entry booby hatch to cargo hold No.5 and second one was for TST No.4 starboard side.

Section 9A: Hatch Cover and Lifting Appliances

9A.6 Are quick-acting cleats and crutches all in place and in good working condition with the rubber washers flexible and free from paint and cracks? (V)

Findings: On No 1 cargo hold aft two quick acting cleats counter pieces on hatch cover were seen bent. They were bent open around 1 cm from their straight line.

9A.22 Are the loose gears of lifting appliances clearly marked and are the certificates of the loose gears available and traceable on board?

Findings: Inside steering gear room one chain block was seen with safety latch of its hook missing.

Section 10: Mooring Operations

10.20 Are the chain locker doors firmly battened down and are the bitter end securing arrangements located outside the chain locker and accessible? (V)

Findings: The bitter ends of anchor chains were secured inside the chain locker and not accessible from outside by ships design.

Section 12: Security

12.7 Are cyber security policies and procedures integrated into the safety management system, and has the cyber security management system been evaluated and certified? (V)

Findings: Inside ECR the passphrase for unlocking the computer was seen posted on the upper part of the screen

Section 13: Machinery Space

13.19 Are engine exhausts and other hot surfaces effectively shielded against oil spray and are flanges and connections of flammable liquid pipelines adequately protected with guards and spray tape? (V)

Findings: On both auxiliary engines parts of the flange between turbo charger and exhaust pipe were seen with no insulation. On No.2 Auxiliary engine an area of around 10cm on the exhaust pipe was seen not covered by insulation.

Vessel's Master Name

MUZAFFER KAPICIOGLU

Vessel's Master Email Address

mantanilgun@skyfile.com

- ☒ By signing the list of Findings, I confirm a closing meeting has taken place and the inspector has informed me that, where not already transmitted, the list of Findings will be sent via internet email once connectivity is restored.

Vessel's Master Signature:

A handwritten signature in black ink, appearing to be 'Muzaffer Kapicioğlu', written over a horizontal line.

Inspector Name

P.-U. Kunrad Brandes

Inspector's Signature:

A handwritten signature in black ink, appearing to be 'P.-U. Kunrad Brandes', written over a horizontal line.

CONTACT US

If you're interested and would like to know more, get in touch with our team today.

 www.rightship.com

 dryinspections@rightship.com

 RightShip

MELBOURNE

 Level 8/ 550 Bourke Street,
Melbourne VIC 3000,
Australia

 +61 3 8686 5750

LONDON

 4th Floor, 6 Dowgate Hill,
London EC4R 2SU, United
Kingdom

 +44 203 872 5900

SINGAPORE

 20 Cecil Street, PLUS,
#13-06
Singapore 049705

 +65 3138 3855

HOUSTON

 Suite 140 14141
Southwest Freeway,
Sugar Land TX 77478,
United States of America

 +1 832 770 8200

MALTA

 The Tower, 3rd Floor,
Fortunato Mizzi Street,
Ir-Rabat Għawdex
VCT 2517, Malta