Please note that these 2 holes do not perfectly align on this version although they will be fixed in the next revision. Please fix by clearing with a 1/8" drill bit after assembly, and then fitting with standoff and screws.

