

Inspection Report

Client Name Tysen and Chantel Gough


Address of Inspection 1428 Ridgeline Dr

Ogden, UT 84403

Date of Inspection 09/28/2026

Real Estate Agent Cyndi Farrais

Name of Inspector Jeremy K. Heath



Property Information

Inspection details & property description

Type of inspection	Real Estate Sale	Type of loan	Conventional
Property type	Single Family	Construction style	Ranch
Year of construction	1998	Total square footage	2,400 sq ft
Valuation	\$450,000	Lot size	0.25 acres
Stories	1.5	Basement	Unfinished
Garage	Attached · 2 cars	Car port	None
Bedrooms	4	Bathrooms	3
Hallways	2	Kitchen	1
Checklist depth	Standard		

ADDITIONAL INSPECTION SERVICES

Radon · Thermal Audit · Termite

CLIENT

Tysen and Chantel Gough · (801) 555-0134 · tysen.gough@example.com

Beginning Notes

Conditions at the time of inspection

Property status	Owner Occupied	Weather	Sunny
Temperature	72°F	Power is on	Yes
Gas is on	Yes	Water is on	Yes

BUYER'S AREAS OF CONCERN

Buyer asked us to pay particular attention to the roof, the electrical panel, and any signs of water intrusion in the basement.

APPARENT HAZARDS OBSERVED BEFORE INSPECTION

Tree branches in contact with the structure on the north side. Section of front walkway concrete lifting — trip hazard.

02 Landscaping

Fence Type	Reviewed
Front Gate	Reviewed
Other Gate	Reviewed
Grading	Reviewed
Landscaping	Reviewed
Vegetation	Reviewed
Water Feature	Reviewed
Brush Fire Defensible Space	Reviewed
Surface Drainage	Reviewed
Wall	Reviewed
Retaining Wall	Reviewed
Driveway	Reviewed
Walk Ways	Reviewed
Bushes	Reviewed
Trees	Reviewed
Electrical Receptacles	Reviewed
Sprinkler System	Reviewed

Overall condition

Good

COMMENTS

No significant concerns noted at the time of inspection.


FINDINGS

- Category 1 · Safety — No power to exterior receptacle — wiring damaged at housing (back of property).
- Category 1 · Safety — Tree branches in contact with the structure.

02 Landscaping · Photos



Front Yard



Concerns — Safety concern - address immediately

Cat 1

10 Exterior Walls

Siding Material	Reviewed
Soffits	Reviewed
Trim	Reviewed
Rain Gutters	Reviewed
Water Down Spouts	Reviewed
Windows	Reviewed
Lintels	Reviewed
Concrete Sidewalk	Reviewed
Front Steps	Reviewed
Front Porch	Reviewed
Doorbell	Reviewed
Exterior Doors	Reviewed
Chimney	Reviewed
Foundation Type	Reviewed
Exterior Foundation	Reviewed
Dryer Exhaust Vent	Reviewed
Hose Bib(s)	Reviewed
Lighting	Reviewed
Electrical Receptacles	Reviewed
Mail Box	Reviewed

Overall condition

Good**COMMENTS**

No significant concerns noted at the time of inspection.




FINDINGS

- Category 1 · Safety — Rail required for stairs down to basement back door.
- Category 2 · Functional — Section of concrete is lifting — trip hazard.
- Category 3 · Items to monitor — Residue of ivy on the front of the house.



10 Exterior Walls · Photos



Front



Left Side

14 Garage

Garage type	None
Foundation Type	Reviewed
Roof Type	Reviewed
Exterior Walls	Reviewed
Electrical	Reviewed
Hose Bib(s)	Reviewed
Door(s)	Reviewed
Floor Surfacing	Reviewed
Visible Foundation	Reviewed
Trusses	Reviewed
Connector Plates	Reviewed
Ceiling	Reviewed
Attic (secondary)	Reviewed
Windows	Reviewed
Thermal Imaging	Reviewed
Garage Door(s)	Reviewed
Lintels	Reviewed
Interior Walls	Reviewed
Lighting	Reviewed
Wiring Type	Reviewed
Electrical Receptacles	Reviewed
EV Charging	Reviewed
Mold	Reviewed
Heated	Reviewed

Overall condition

Good



COMMENTS

No significant concerns noted at the time of inspection.

17 Bedroom 1

Type	Master Bed
Level	Main Floor
Door(s)	Reviewed
Ceiling	Reviewed
Floor	Reviewed
Sub Floor	Reviewed
Interior Walls	Reviewed
Windows	Reviewed
Thermal Anomalies	Reviewed
Closet	Reviewed
Lighting	Reviewed
Shelves	Reviewed
Electrical Receptacles	Reviewed
Ceiling Fan	Reviewed
HVAC	Reviewed
Thermostat	Reviewed
Alarms	Reviewed

Overall condition

Good
COMMENTS

No significant concerns noted at the time of inspection.

19 Living Room

Door(s)	Reviewed
Ceiling	Reviewed
Floor	Reviewed
Sub Floor	Reviewed
Stairways	Reviewed
Railing	Reviewed
Interior Walls	Reviewed
Windows	Reviewed
Thermal Anomalies	Reviewed
Lighting	Reviewed
Electrical Receptacles	Reviewed
Ceiling Fans	Reviewed
Fireplace	Reviewed
HVAC	Reviewed
Alarms	Reviewed

Overall condition

Good**COMMENTS**

No significant concerns noted at the time of inspection.

23 Kitchen

Remodel	Reviewed
Door(s)	Reviewed
Ceiling	Reviewed
Floor	Reviewed
Sub Floor	Reviewed
Interior Walls	Reviewed
Windows	Reviewed
Thermal Anomalies	Reviewed
Counters	Reviewed
Cupboards	Reviewed
Cabinets	Reviewed
Island	Reviewed
Pantry	Reviewed
Sink	Reviewed
Plumbing	Reviewed
Dishwasher	Reviewed
Stove & Oven	Reviewed
Exhaust Hood	Reviewed
Refrigerator	Reviewed
Lighting	Reviewed
Electrical Receptacles	Reviewed
HVAC	Reviewed

Overall condition

Good

COMMENTS

No significant concerns noted at the time of inspection.



23 Kitchen · Photos



General Area



Summary of Findings

Findings grouped by category, in the order they appear in the report

1

Category 1 · Safety

Address before closing

3

- 1** No power to exterior receptacle — wiring damaged at housing (back of property). (Landscaping)
- 2** Tree branches in contact with the structure. (Landscaping)
- 3** Rail required for stairs down to basement back door. (Exterior Walls)

2

Category 2 · Functional

Address in the first few months after closing

2

- 1** No diverter; water going into foundation causing settling. (Roof)
- 2** Section of concrete is lifting — trip hazard. (Exterior Walls)

3

Category 3 · Items to monitor

Monitor and address over time

1

- 1** Residue of ivy on the front of the house. (Exterior Walls)