



Vision Property Inspections
2029 N Main St Suite 103
Sunset, UT 84015
VisionPropertyInspections@Gmail.com

Inspection Report

Client Name Tysen and Chantel Gough

Address of Inspection 1428 Ridgeline Dr
Ogden, UT 84403, NH

Date of Inspection 09/28/2026

Real Estate Agent Cyndi Farrais

Name of Inspector Jeremy K. Heath **License #** FL-HI9921



**This inspection report is the property of
Vision Property Inspections.
Any reproduction or distribution without
written consent is prohibited.**



Property Information

Inspection details & property description

Type of inspection	Real Estate Sale	Type of loan	Conventional
Property type	Single Family	Construction style	Ranch
Year of construction	1998	Total square footage	2,400 sq ft
Valuation	\$450,000	Lot size	0.25 acres
Stories	1.5	Basement	Unfinished
Garage	Attached · 2 cars	Car port	None
Bedrooms	4	Bathrooms	3
Hallways	2	Kitchen	1
Checklist depth	High Detail		

ADDITIONAL INSPECTION SERVICES

Radon · Thermal Audit · Termite

CLIENT

Tysen and Chantel Gough · (801) 555-0134 · tysen.gough@example.com

Beginning Notes

Conditions at the time of inspection

Property status	Owner Occupied	Weather	Sunny
Temperature	72°F	Power is on	Yes
Gas is on	Yes	Water is on	Yes

BUYER'S AREAS OF CONCERN

Buyer asked us to pay particular attention to the roof, the electrical panel, and any signs of water intrusion in the basement.

APPARENT HAZARDS OBSERVED BEFORE INSPECTION

Tree branches in contact with the structure on the north side. Section of front walkway concrete lifting — trip hazard.

02 Landscaping

Fence Type	Reviewed
Front Gate	Concerns ●
Other Gate	Reviewed
Grading	Reviewed
Landscaping	Reviewed
Vegetation	Reviewed

Water Feature

Water Feature	Water fall
---------------	------------

Overall condition

Good

COMMENTS

No significant concerns noted at the time of inspection.

FINDINGS


- Category 1 · Safety — No power to exterior receptacle — wiring damaged at housing (back of property).
- Category 1 · Safety — Tree branches in contact with the structure.
- Category 1 · Safety — Front Gate: Latch does not catch



02 Landscaping · Photos



Front Yard



Concerns — Safety concern - address immediately

Cat 1



10 Exterior Walls

Line items

No line items recorded

Overall condition

Good

COMMENTS


No significant concerns noted at the time of inspection.

FINDINGS

- Category 1 · Safety — Rail required for stairs down to basement back door.
- Category 2 · Functional — Section of concrete is lifting — trip hazard.
- Category 3 · Items to monitor — Residue of ivy on the front of the house.



10 Exterior Walls · Photos



Front



Left Side



14 Garage

Line items

No line items recorded

Overall condition

Good

COMMENTS

No significant concerns noted at the time of inspection.



17 Bedroom 1

Type

Master Bed

Overall condition

Good

COMMENTS

No significant concerns noted at the time of inspection.



19 Living Room

Line items

No line items recorded

Overall condition

Good

COMMENTS

No significant concerns noted at the time of inspection.



23 Kitchen

Line items

No line items recorded

Overall condition

Good

COMMENTS

No significant concerns noted at the time of inspection.



23 Kitchen · Photos



General Area



Summary of Findings

Findings grouped by category, in the order they appear in the report

1

Category 1 · Safety

Address before closing

4

- 1** No power to exterior receptacle — wiring damaged at housing (back of property). (Landscaping)
- 2** Tree branches in contact with the structure. (Landscaping)
- 3** Front Gate: Latch does not catch (Landscaping)
- 4** Rail required for stairs down to basement back door. (Exterior Walls)

2

Category 2 · Functional

Address in the first few months after closing

2

- 1** No diverter; water going into foundation causing settling. (Roof)
- 2** Section of concrete is lifting — trip hazard. (Exterior Walls)

3

Category 3 · Items to monitor

Monitor and address over time

1

- 1** Residue of ivy on the front of the house. (Exterior Walls)