

# **Accessories**




## **Accessories**







Pin	Signal
1	S/G 1
2	S/G 1
3	S/G 2
4	S/G 2



Color

brown white

blue

black

Signal S/G 2


S/G 1

n.c.

n.c.



## Analysis Software InspectMaster



This software is included in every Strain Clamp Set or DDBF.

### **Functions:**

- Four channel display in με
- Display of sum value in με
- Display of clamping force in kN
- Display of deviation of tie bar load distribution in %
- Cycle function with auto reset mode
- Display of graphs
- Saving of measured data
- Export function (Text file can be processed with Excel)

### Requirements:

- PC with Windows 2000, XP, NT minimum 500 MHz and USB interface required