

Re: IronForms 930E Electrical Service Brush Length Issues

From Bukit Technology Support <support@bukittechnology.com>
Date Thu 8/6/2026 8:58 AM
To Will Mullany <william.mullany@buma.com.au>
Cc Scott McBryde <scott.mcbride@buma.com.au>; Stuart Cameron <stuart.cameron@buma.com.au>; Traven Hooper <traven.hooper@buma.com.au>; DL Blackwater Reliability <blackwater.reliability@buma.com.au>

Hi Will,

Thanks for the detailed information and attachments. They really help our team investigate the root cause.

We'll look into this and get back to you as soon as possible. If we need any additional information, we'll let you know.

Regards,

Pradya

From: Will Mullany <william.mullany@buma.com.au>
Sent: Thursday, August 6, 2026 7:58 AM
To: Bukit Technology Support <support@bukittechnology.com>
Cc: Scott McBryde <scott.mcbride@buma.com.au>; Stuart Cameron <stuart.cameron@buma.com.au>; Traven Hooper <traven.hooper@buma.com.au>; DL Blackwater Reliability <blackwater.reliability@buma.com.au>
Subject: RE: IronForms 930E Electrical Service Brush Length Issues


Hi Pradya,

Example of error on brush replacement 5-8 on service sheets (this was on 4267274 DT0768 500hr service but problem is consistent for all 930E trucks).


I have videos of the below – but they are too big to attach, is there a shared folder or a folder I can share with you so you can see the full videos of this error?

Also please see attached network HAR log file of when I replicated this fault.


- 1. Out of spec measurement is entered on **Brush 6** (and service sheet correctly identifies brush is out of spec)




- 2. Replace button is pressed



3. Out of range error pops up then disappears after 1-2 seconds



4. Brush is still evaluated as out of spec – but electrician still replaces brush as it is out of spec – and we lose important service information + defect/intervention is raised unnecessarily.



Let me know if you need more info

Kind regards,
Will



Will Mullany

Graduate Mechanical Engineer

Ardurad Road

Blackwater QLD 4717

Email

william.mullany@buma.com.au

Website

buma.com.au

BUMA-OFFICIAL

From: Bukit Technology Support <support@bukittechnology.com>
Sent: Thursday, 16 July 2026 7:04 PM
To: Will Mullany <william.mullany@buma.com.au>
Cc: Traven Hooper <traven.hooper@buma.com.au>; Benedict Panizza <benedict.panizza@buma.com.au>
Subject: Re: IronForms 930E Electrical Service Brush Length Issues

Hi Will,

We are still currently trying to reproduce the same scenario as the production environment in our non-production environment to investigate this further for the A5-A8.

I'll get back to you once we have an update.

Regards,
Pradya

From: Will Mullany <william.mullany@buma.com.au>
Sent: Wednesday, July 15, 2026 10:34 AM
To: Bukit Technology Support <support@bukittechnology.com>
Cc: Traven Hooper <traven.hooper@buma.com.au>; benedict.panizza <benedict.panizza@buma.com.au>
Subject: RE: IronForms 930E Electrical Service Brush Length Issues

Hi Pradya,

In your non-production environment why is the available previous data is only up to **A4?**

Whereas the production environment has prev data for all brushes,

The issues are with the brushes you cannot test in non-prod, is there a way your non-prod can be changes to reflect prod environment? So you can test the functionality.

Cheers
Will



Will Mullany

Graduate Mechanical Engineer

Ardurad Road

Blackwater QLD 4717

Email

william.mullany@buma.com.au

Website

buma.com.au

BUMA-OFFICIAL

From: Will Mullany
Sent: Monday, 6 July 2026 2:50 PM
To: Bukit Technology Support <support@bukittechnology.com>

Cc: Justin Shaw <justin.shaw@buma.com.au>; Traven Hooper <traven.hooper@buma.com.au>; Benedict Panizza <benedict.panizza@buma.com.au>
Subject: RE: IronForms 930E Electrical Service Brush Length Issues

Hi Pradya,

This affects all 930E electrical service sections, for all machines,

Regards,
Will



Will Mullany

Graduate Mechanical Engineer

Ardurad Road

Blackwater QLD 4717

Email

Website

william.mullany@buma.com.au

buma.com.au

From: Bukit Technology Support <support@bukittechnology.com>
Sent: Monday, 29 June 2026 1:18 PM
To: Will Mullany <william.mullany@buma.com.au>
Cc: Justin Shaw <justin.shaw@buma.com.au>; Traven Hooper <traven.hooper@buma.com.au>; Benedict Panizza <benedict.panizza@buma.com.au>
Subject: Re: IronForms 930E Electrical Service Brush Length Issues

Hi Will,

Thanks, that would be really helpful.

In the meantime, could you also let us know the **WO number** and **Equipment Number** for the affected service? We'd like to trace the historical data of that service.

Thanks.

Regards,
Pradya


From: Will Mullany <william.mullany@buma.com.au>
Sent: Monday, June 29, 2026 10:03 AM
To: Bukit Technology Support <support@bukittechnology.com>
Cc: Justin Shaw <justin.shaw@buma.com.au>; Traven Hooper <traven.hooper@buma.com.au>; benedict.panizza <benedict.panizza@buma.com.au>
Subject: RE: IronForms 930E Electrical Service Brush Length Issues

Thanks Pradya,

In the production environment, there is and as you can see on a recent service, since they are unable to replace the brush in ironforms, they can only enter 0, as the last measurement is 0.

I will take a screenshot/recording of the error for you for more information,

Cheers
Will



Item	Measurement Location	Prev. Value	Current Value	Unit	Brush Length Status	Rating	Notes
a1	Comm Brush 1 (100 v-back)	38	34	mm	Out of spec	X	Group Health: 2026-06-29 10:03 AM (AUSST)
	Replacement		52	mm	In spec	A	Group Health: 2026-06-29 10:03 AM (AUSST)
	Comment		Additional Comments (Optional)				
a2	Comm Brush 2 (100 v-back)	40	41	mm	In spec	B	Group Health: 2026-06-29 10:03 AM (AUSST)
a3	Comm Brush 3 (2 v-back)	40	41	mm	In spec	A	Group Health: 2026-06-29 10:03 AM (AUSST)
a4	Comm Brush 4 (2 v-back)	0	0	mm	Out of spec	X	Group Health: 2026-06-29 10:03 AM (AUSST)
a5	Comm Brush 5 (4 v-back)	40	42	mm	In spec	A	Group Health: 2026-06-29 10:03 AM (AUSST)
a6	Comm Brush 6 (4 v-back)	40	42	mm	In spec	A	Group Health: 2026-06-29 10:03 AM (AUSST)
a7	Comm Brush 7 (4 v-back)			mm	Out of spec	X	Group Health: 2026-06-29 10:03 AM (AUSST)
a8	Comm Brush 8 (4 v-back)			mm	Out of spec	X	Group Health: 2026-06-29 10:03 AM (AUSST)



Will Mullany

Graduate Mechanical Engineer

Ardurad Road

Blackwater QLD 4717

Email

Website

william.mullany@buma.com.au

buma.com.au

BUMA-OFFICIAL

From: Bukit Technology Support <support@bukittechnology.com>
Sent: Monday, 29 June 2026 12:47 PM
To: Will Mullany <william.mullany@buma.com.au>
Cc: Justin Shaw <justin.shaw@buma.com.au>; Traven Hooper <traven.hooper@buma.com.au>; Benedict Panizza <benedict.panizza@buma.com.au>
Subject: Re: IronForms 930E Electrical Service Brush Length Issues

Hi Will,

Thanks for the clarification.

In the non-production environment, the available previous data is only up to **A4**, so we were only able to test the replacement scenario where a **Rating X** is generated up to that point.

Item	Measurement Location	Prev. Value	Current Value	UoM	Brush Length Status	Rating	
a1	Comm Brush 1 (10 o'clock)	26	26	mm	Out of spec	X	Replace
	Replacement		52	mm	In spec	A	Replace
	Comment	Additional information (if required)					
a2	Comm Brush 2 (10 o'clock)	52	29	mm	Out of spec	X	Replace
	Replacement		52	mm	In spec	A	Replace
	Comment	Additional information (if required)					
a3	Comm Brush 3 (2 o'clock)	50	29	mm	Out of spec	X	Replace
	Replacement		52	mm	In spec	A	Replace
	Comment	Additional information (if required)					
a4	Comm Brush 4 (2 o'clock)	46	40	mm	In spec	X	Replace
	Replacement		52	mm	In spec	A	Replace
	Comment	Additional information (if required)					
a5	Comm Brush 5 (4 o'clock)	-	40	mm	In spec	A	Replace
a6	Comm Brush 6 (4 o'clock)	-	30	mm	Out of spec	A	Replace
a7	Comm Brush 7 (8 o'clock)	-	0	mm	Out of spec	A	Replace
a8	Comm Brush 8 (8 o'clock)	-	10	mm	Out of spec	A	Replace

Based on the implementation, the replacement functionality is intended to behave the same across all brush items (A1–A8), so we would expect the same behaviour for A5–A8 as well.

If you're able to provide a screen recording of the issue from your side, that would be very helpful. It will allow us to review the process in more detail and identify what may be causing the error.

Thanks,
Pradya

From: Will Mullany <william.mullany@buma.com.au>
Sent: Friday, June 26, 2026 4:52 PM
To: Bukit Technology Support <support@bukittechnology.com>
Cc: Justin Shaw <justin.shaw@buma.com.au>; Traven Hooper <traven.hooper@buma.com.au>; benedict.panizza <benedict.panizza@buma.com.au>
Subject: Re: IronForms 930E Electrical Service Brush Length Issues

Hi Pradya

Thanks for the feedback, really appreciate it,

Yes I can confirm the below process is being followed correctly.

was the testing done on all brush input and replacement fields (a1 to a8)? Since this issue only occurs on a4 to a8.

The replace button appears but it throws an error on a4–a8 after replace is clicked.

Could you confirm replace works on these too without error after pressing?

If you are unable to replicate this error in the non-production environment, I will take a screen recording of the error and send it through & send the network log.

Kind regards
Will

Get [Outlook for iOS](#)

BUMA-OFFICIAL

From: Bukit Technology Support <support@bukittechnology.com>
Sent: Friday, June 26, 2026 7:42 pm
To: Will Mullany <william.mullany@buma.com.au>
Cc: Justin Shaw <justin.shaw@buma.com.au>; Traven Hooper <traven.hooper@buma.com.au>; Benedict Panizza <benedict.panizza@buma.com.au>
Subject: Re: IronForms 930E Electrical Service Brush Length Issues

Hi Will,

Following up on this issue, we have tested the scenario in our **non-production environment**.

Based on our testing, the **Replace** button is displayed correctly and can be clicked successfully when it gets the bad value or rating (rating C/X).

Item	Measurement Location	Prev. Value	Current Value	UoM	Brush Length Status	Rating	
a1	Comm Brush 1 (10 o'clock)	26	26	mm	Out of spec	A	Replace
a2	Comm Brush 2 (10 o'clock)	52	40	mm	In spec	X	Replace
	Replacement		52	mm	In spec	A	Replace
	Comment	Additional information (if required)					
a3	Comm Brush 3 (2 o'clock)	50	46	mm	In spec	X	Replace
a4	Comm Brush 4 (2 o'clock)	46	45	mm	In spec	A	Replace
a5	Comm Brush 5 (4 o'clock)	-	20	mm	Out of spec	A	Replace
a6	Comm Brush 6 (4 o'clock)	-	10	mm	Out of spec	A	Replace
a7	Comm Brush 7 (8 o'clock)	-	0	mm	Out of spec	A	Replace
a8	Comm Brush 8 (8 o'clock)	-	30	mm	Out of spec	A	Replace

Take photo of Cab Side & Off Cab Side

Could you please make sure the process follows the expected flow below?

1. User measures the Comm Brush and gets a bad value or rating.
2. User enters the measured value in the **Current Value** field.
3. If the brush needs to be replaced based on the supervisor's recommendation, the user clicks the **Replace** button.
4. User enters the new brush measurement in the **Replacement** field.

For your reference, I've also attached a previous email regarding a similar issue.

Thank you.

Regards,

From: Will Mullany <william.mullany@buma.com.au>
Sent: Friday, June 26, 2026 7:47 AM
To: Bukit Technology Support <support@bukittechnology.com>
Cc: Justin Shaw <justin.shaw@buma.com.au>; Traven Hooper <traven.hooper@buma.com.au>; benedict.panizza <benedict.panizza@buma.com.au>
Subject: RE: IronForms 930E Electrical Service Brush Length Issues

Thanks Okky, greatly appreciated



Will Mullany
Graduate Mechanical Engineer
Ardurad Road
Blackwater QLD 4717

Email william.mullany@buma.com.au
Website buma.com.au

BUMA-OFFICIAL

From: Bukit Technology Support <support@bukittechnology.com>
Sent: Thursday, 25 June 2026 4:35 PM
To: Will Mullany <william.mullany@buma.com.au>
Cc: Justin Shaw <justin.shaw@buma.com.au>; Traven Hooper <traven.hooper@buma.com.au>; Benedict Panizza <benedict.panizza@buma.com.au>
Subject: Re: IronForms 930E Electrical Service Brush Length Issues

Hi Will,

We will check this issue to validate the root cause.

Regards,
Okky

From: Will Mullany <william.mullany@buma.com.au>
Sent: Thursday, June 25, 2026 9:08 AM
To: Bukit Technology Support <support@bukittechnology.com>
Cc: Justin Shaw <justin.shaw@buma.com.au>; Traven Hooper <traven.hooper@buma.com.au>; benedict.panizza <benedict.panizza@buma.com.au>
Subject: IronForms 930E Electrical Service Brush Length Issues

Hi Okky,

Items a5 to a8 (brush measurement 5 to 8) on the 930E-4 HPI service will not let the sparkys click *replace* if they need to change the brush on the service sheet.

The replace button is giving an unknown error when clicked (for both retarder grid box sections)

Since they cannot click replace, they are forced to enter a measurement that's less than Prev. Value, which makes every data point after redundant.

Could this issue please be fixed ASAP? Let me know if you need more info

Item	Measurement Location	Prev. Value	Current Value
a1	Comm Brush 1 (10 o'clock)	52	51
a2	Comm Brush 2 (10 o'clock)	52	51
a3	Comm Brush 3 (2 o'clock)	52	51
a4	Comm Brush 4 (2 o'clock)	40	40
a5	Comm Brush 5 (4 o'clock)	41	39
a6	Comm Brush 6 (4 o'clock)	34	34
a7	Comm Brush 7 (8 o'clock)	38	38
a8	Comm Brush 8 (8 o'clock)	38	38

Kind regards,
Will



Will Mullany
Graduate Mechanical Engineer
Ardurad Road
Blackwater QLD 4717

Email william.mullany@buma.com.au
Website buma.com.au

NOTICE:This message is for the named person's use only. It may contain confidential, proprietary or legally privileged information. BUMA Australia does not waive any confidentiality, copyright or legally privileged information by any transmission. If you receive this message in error, please immediately delete it and all copies of it from your system, destroy any hard copies of it and notify the sender. You must not, directly or indirectly, use, disclose, distribute, print, or copy any part of this message if you are not the intended recipient. BUMA Australia reserves the right to monitor all e-mail communications through its networks. Any views expressed in this message are those of the individual sender, except where the message states otherwise and the sender is authorized to state them to be the views of any such entity.

BUMA-OFFICIAL

NOTICE:This message is for the named person's use only. It may contain confidential, proprietary or legally privileged information. BUMA Australia does not waive any confidentiality, copyright or legally privileged information by any transmission. If you receive this message in error, please immediately delete it and all copies of it from your system, destroy any hard copies of it and notify

the sender. You must not, directly or indirectly, use, disclose, distribute, print, or copy any part of this message if you are not the intended recipient. BUMA Australia reserves the right to monitor all e-mail communications through its networks. Any views expressed in this message are those of the individual sender, except where the message states otherwise and the sender is authorized to state them to be the views of any such entity.

NOTICE:This message is for the named person's use only. It may contain confidential, proprietary or legally privileged information. BUMA Australia does not waive any confidentiality, copyright or legally privileged information by any transmission. If you receive this message in error, please immediately delete it and all copies of it from your system, destroy any hard copies of it and notify the sender. You must not, directly or indirectly, use, disclose, distribute, print, or copy any part of this message if you are not the intended recipient. BUMA Australia reserves the right to monitor all e-mail communications through its networks. Any views expressed in this message are those of the individual sender, except where the message states otherwise and the sender is authorized to state them to be the views of any such entity.

NOTICE:This message is for the named person's use only. It may contain confidential, proprietary or legally privileged information. BUMA Australia does not waive any confidentiality, copyright or legally privileged information by any transmission. If you receive this message in error, please immediately delete it and all copies of it from your system, destroy any hard copies of it and notify the sender. You must not, directly or indirectly, use, disclose, distribute, print, or copy any part of this message if you are not the intended recipient. BUMA Australia reserves the right to monitor all e-mail communications through its networks. Any views expressed in this message are those of the individual sender, except where the message states otherwise and the sender is authorized to state them to be the views of any such entity.

NOTICE:This message is for the named person's use only. It may contain confidential, proprietary or legally privileged information. BUMA Australia does not waive any confidentiality, copyright or legally privileged information by any transmission. If you receive this message in error, please immediately delete it and all copies of it from your system, destroy any hard copies of it and notify the sender. You must not, directly or indirectly, use, disclose, distribute, print, or copy any part of this message if you are not the intended recipient. BUMA Australia reserves the right to monitor all e-mail communications through its networks. Any views expressed in this message are those of the individual sender, except where the message states otherwise and the sender is authorized to state them to be the views of any such entity.

NOTICE:This message is for the named person's use only. It may contain confidential, proprietary or legally privileged information. BUMA Australia does not waive any confidentiality, copyright or legally privileged information by any transmission. If you receive this message in error, please immediately delete it and all copies of it from your system, destroy any hard copies of it and notify the sender. You must not, directly or indirectly, use, disclose, distribute, print, or copy any part of this message if you are not the intended recipient. BUMA Australia reserves the right to monitor all e-mail communications through its networks. Any views expressed in this message are those of the individual sender, except where the message states otherwise and the sender is authorized to state them to be the views of any such entity.