

ISO metric thread chart: pitch, tap drill and clearance holes

The chart: ISO coarse pitch, M1.6 to M36

Thread	Pitch	Tap drill	Clearance fine	Clearance medium	Clearance coarse	Wrench (hex)	Hex key (SHCS)
M1.6	0.35	1.25	1.7	1.8	2	3.2	1.5
M2	0.4	1.6	2.2	2.4	2.6	4	1.5
M2.5	0.45	2.05	2.7	2.9	3.1	5	2
M3	0.5	2.5	3.2	3.4	3.6	5.5	2.5
M4	0.7	3.3	4.3	4.5	4.8	7	3
M5	0.8	4.2	5.3	5.5	5.8	8	4
M6	1	5	6.4	6.6	7	10	5
M8	1.25	6.8	8.4	9	10	13	6
M10	1.5	8.5	10.5	11	12	16	8
M12	1.75	10.2	13	13.5	14.5	18	10
M14	2	12	15	15.5	16.5	21	12
M16	2	14	17	17.5	18.5	24	14
M18	2.5	15.5	19	20	21	27	14
M20	2.5	17.5	21	22	24	30	17
M22	2.5	19.5	23	24	26	34	17
M24	3	21	25	26	28	36	19
M27	3	24	28	30	32	41	19
M30	3.5	26.5	31	33	35	46	22
M33	3.5	29.5	34	36	38	50	24
M36	4	32	37	39	42	55	27

1. Fine pitch: the sizes you actually meet

Fine pitch is used when you need better resistance to loosening (vibration), fine adjustment, or a thin wall that can't take a deep thread. It is always written with the pitch: **M12 × 1.5**. With no pitch stated, it's coarse.

Thread	Tap drill
M8 × 1	7
M10 × 1.25	8.8
M10 × 1	9
M12 × 1.5	10.5
M12 × 1.25	10.8
M14 × 1.5	12.5
M16 × 1.5	14.5
M18 × 1.5	16.5
M20 × 1.5	18.5

Thread	Tap drill
M20 × 2	18
M22 × 1.5	20.5
M24 × 2	22
M27 × 2	25
M30 × 2	28
M36 × 3	33

Clearance holes and wrench sizes are the same as for coarse pitch: only the tap drill changes.

Reference values taken from the article <https://www.baouch.fr/en/blog/tableau-filetage-metrique-percentage-taraudage/>, which explains the assumptions, formulas and edge cases. For critical use, check the current standard or the manufacturer's documentation. Free to print and share with credit to the source.