


TODO:
Add battery power switch
Add IMU
Add battery charge sensor
Change reset button to right angle
Connect CHR9 output to GPIO
Add auto reset transistors
Link TX/RX to cp2101n
Replace CP2102 with CP2102N?
Battery options:
- https://www.banggood.com/5PCS-3_7V-300mAh-25C-Lipo-Battery-Charger-Set-for-H8-H22-Eachine-H8-mini-RC-Quadcopter-p-1380233.html
- https://hobbyking.com/en_us/turnigy-2000mah-1s-1c-lipoly-w-2-pin-jst-ph-connector.html



Button 1: IO34
Button 2: IO35
Button 3: IO32
Button 4: IO33
Button 5: IO4
Button 6: IO16
Button 7: IO12
Button 8: IO2
Output1: IO14
Output2: IO27
Output3: IO26
Output4: IO25
Output5: IO19
Output6: IO17
Output7: IO18
Output8: IO23

