

X-RiteColor® Premier 8000 Series

Setting up the instrument drivers

Turn the instrument on. If it is already on, turn it off and back on. This will prompt the computer to install a new USB device. On Windows 98, Click