CA22 Spectrophotometer User Manual

CA22 SPECTROPHOTOMETER

CE DECLARATION

Manufacturer's Name: X-Rite, Incorporated Manufacturer's Address: 3100 44th Street, S.W.

Grandville, Michigan 49418

U.S.A.

Model Name: Spectrophotometer

Model No.: DTP22

Directive(s) Conformance: EMC 89/336/EEC LVD 73/23/EEC

PROPRIETARY NOTICE

Table of Contents

1 Installation and Maintenance

€ Safe storage ensures proper maintenance of the instrument optics. Do not spray cleaners or compressed air up into optics area. Do not stick cotton swabs into the optics.

Cleaning the Calibration Reference

When not in use, store the calibration reference in a dry, dust free area, away from direct exposure to light. Clean the calibration reference before every calibration:

€ Gently clean the reference and white opal area with a dry, lint-free cloth. Do not use solvents or cleaners of any kind.

4. Point the Target Eye of your instrument toward a dark area that is shielded from lighting, such as underneath a table or desk. Make sure that there are no objects or surfaces within at least two feet of the front or sides of the Target

CA22 SPECTROPHOTOMETER

Press the Handpiece together with the Shoe and hold.

NOTE

3 Taking Measurements

Troubleshooting

Error messages indicate that the instrument is not responding to the software program.

∉ Make sure your instrument is connected to the Serial Port of your computer. If it is not, shut down your computer, connect to the Serial Port, and then restart your computer. Make sure you select the correct

Appendix A: Technical Support

If you are having a problem or if you have a question that is directly related to

P/N CA22-500 Rev. I-07/17/02